BEFORE THE PUBLIC UTILITIES COMMISSION OF THE STATE OF SOUTH DAKOTA

)
IN THE MATTER OF THE PETITION OF) Docket 14-001
TransCanada KEYSTONE PIPELINE, LP FOR)
ORDER ACCEPTING CERTIFICATION OF) DAKOTA RURAL ACTION'S POST-
PERMIT ISSUED IN DOCKET HP09-001 TO) HEARING BRIEF
CONSTRUCT THE KEYSTONE XL PIPELINE)
)

To say that these proceedings have been contentious risks making a gross understatement. The permitting process for TransCanada Keystone Pipeline LP's ("TransCanada") proposed Keystone XL Pipeline (the "KXL Pipeline") has been a classic example of long-held privileges afforded the global fossil fuel industry arrayed against the interests of a public that is increasingly concerned about the effects of fossil fuel on our environment. This post-hearing brief is submitted on behalf of Dakota Rural Action ("DRA"), a nonprofit organization that represents the interests of South Dakota's farming and ranching families – individuals whose lands have been negatively affected by TransCanada's base Keystone pipeline, and who will bear the burden and effects of the proposed KXL Pipeline should it ever be constructed.

INTRODUCTION

Nine days of regulatory hearings before the South Dakota Public Utilities Commission (the "Commission") were barely enough to permit a thorough examination of the risks to the public that would be posed by the KXL Pipeline. These challenges were exacerbated by a clear power imbalance – a multinational corporation with tremendous resources arrayed against a small group of individuals, nonprofit organizations, and indigenous tribes, all of whom lacked the resources to do very basic things, such as engage much-needed expert witnesses to counter the paid-for narrative presented by TransCanada. Compounding these challenges was the Commission's own unwillingness to permit a thorough discovery process, illustrated by its order of December 17, 2014, limiting the scope of the

proceedings and discovery. Additionally, TransCanada's obfuscation in responding to discovery requests – and the lack of resources by intervening parties to hire experts to fully analyze and interpret the information ultimately provided by TransCanada – further exacerbated the challenges. These circumstances left many intervenors, including DRA, with the clear impression that when challenging the economic privilege and power of the entrenched fossil fuel industry, the deck is stacked against citizens. With this institutional imbalance embedded in the overall process, intervenors such as DRA and the general public has no choice but to rely upon the Commission to carefully scrutinize claims made by well-funded corporations such as TransCanada in order to proactively protect South Dakota's water and land resources. We would suggest that the Commission's obligation to do so rises to the level of a fiduciary duty owed to the citizens of South Dakota in order to fulfill the public trust with which it is entrusted. The Commission is the only entity that can offset structural imbalances faced in proceedings such as this.

Even in the face of the tremendous power and resource imbalance DRA and the other intervenors faced, a remarkable thing happened during the course of these proceedings. Perhaps overly-confident in its political and economic power, TransCanada made a significant error fatal to its case for recertification of the permit for the KXL Pipeline. TransCanada failed to put on a case that even touched upon the majority of the conditions it had to demonstrate that it could meet. Instead, TransCanada simply believed that it could get by with saying "trust us, we'll comply." Time and time again throughout the nine-day hearing, TransCanada's witnesses came up short and the company failed to present evidence that it would or even could comply with permit conditions. TransCanada is asking the Commission to grant recertification on a hope and a prayer, with no substantive evidence that permit conditions can be met. That is not sufficient for TransCanada to prevail. Its petition for certification should be denied.

Even more remarkably, with the lack of substantial evidence to support its petition for certification, TransCanada – with support from Commission staff – argues that the scope of the Commission's authority is severely limited. DRA suggests this attempt to severely restrict the

Commission's authority to consider issues and evidence in the context of certification proceedings is incorrect.

As a final note, DRA would encourage the Commission to carefully examine the transcripts of the proceedings. Commissioner Fiegen, for example, is already examining the transcripts due to her medical absence during the hearing. Commissioner Hansen, who is also facing medical issues, should also be afforded the full opportunity to examine the hearing transcripts as well, perhaps after he is fully healed. The Commission as a whole has ample time to do so, given the statement by TransCanada executive Corey Goulet that no other permits were currently being applied for, in addition to the fact that the proposed KXL Pipeline's fate in Nebraska is still in question, not to mention the fact that no federal permit has been forthcoming. In short, there is no need for the Commission to feel rushed in its evaluation of these matters because time is not of the essence.

PROCEDURAL BACKGROUND

TransCanada was originally granted a permit for construction of the proposed KXL Pipeline through South Dakota on June 29, 2010 via entry by the Commission of its Amended Final Decision and Order (the "2010 Permit"), subject to fifty separate conditions. The conditions imposed on TransCanada by the 2010 Permit ranged from compliance with all federal and state environmental laws, to compliance with a variety of other matters as set forth in the 2010 Permit. Because TransCanada failed to commence construction of the proposed KXL Pipeline within four years of the date of the 2010 Permit, under SDCL § 49-41B-27 it was required to file a petition with the Commission certifying that it could continue to meet the conditions upon which the 2010 Permit was issued. SDCL § 49-41B-27 states:

Utilities which have acquired a permit in accordance with the provisions of this chapter may proceed to improve, expand, or construct the facility for the intended purposes at any time, subject to the provisions of this chapter; provided, however, that *if such construction*, expansion and improvement *commences more than four years after a permit has been issued, then the utility must certify to the Public Utilities Commission that such facility continues to meet the conditions upon which the permit was issued*. (Emphasis added.)

STANDARD OF REVIEW

In rendering a decision the Commission must do so within an appropriate legal framework. This issue gets to the heart of the matter – what is required in order for TransCanada to "certify to the Public Utilities Commission that such facility continues to meet the conditions upon which the permit was issued" under SDCL § 49-41B-27? DRA suggests there are three key principles: (a) TransCanada's burden of proof, (b) the requirement that TransCanada present substantial evidence in support of its petition, and (c) the application of the public trust doctrine, which places a fiduciary duty on the Commission to protect South Dakota's land, water, and environment.

Burden of Proof

There is no question that TransCanada bears the burden of proof in advancing its petition for certification under SDCL § 49-41B-27. This principle is long-standing under South Dakota law, with the South Dakota Supreme Court "affirming the well-established rule that, "He who asserts an affirmative has the burden of proving the same."" *Tripp State Bank of Tripp v. Jerke*, 189 N.W. 514 (S.D. 1922).

Beyond the basic standard articulated by the South Dakota Supreme Court, the Commission's own administrative rules expressly address the question of which party carries the burden of proof in a contested case. The Commission's rules state that "[i]n any contested case proceeding ... petitioner has the burden of proof as to factual allegations which form the basis of the ... application, or petition ..." S.D. Admin. R. 20:10:01:15.01 (2006). The Commission's rules are dispositive of this issue. TransCanada is the petitioner. TransCanada submitted a petition to the Commission pursuant to SDCL § 49-41B-27. The petition asks the Commission to make a factual determination that it can continue to meet the conditions upon which the 2010 Permit was granted. That petition was opposed by the intervenors, including DRA. Hence, TransCanada has the burden of proving that the proposed KXL Pipeline project continues to meet the conditions upon which the 2010 Permit was granted.

These principles were acknowledged prior to the Final Evidentiary Hearing (hereinafter, referenced as "EH" when citing to the hearing transcript), when the Commission and the parties expressed their respective understanding of what areas of inquiry and issues were before the Commission in these highly-contested proceedings. In fact, Chairman Nelson directly instructed the parties as to who had the burden of proof and what that burden was:

"It is the Petitioner, TransCanada, that has the burden of proof. And under SDCL 49-41B-27, that burden of proof is to establish that the proposed facility continues to meet the 50 Conditions set forth in the Commission's Amended Final Decision. I would like to stress again to all parties here today that this case is about whether the project continues to meet those 50 Conditions." [7/27/15 EH: 10. *Also see*, 7/27/15 EH: 472].

This reality was acknowledged by TransCanada itself in its opening statement to the Commission, where it stated that the burden of proof was limited to the Amended Conditions established as part of the 2010 Permit: "We are here today to meet Keystone's burden of 18 proof. That is, certifying that the project continues to meet the 50 Conditions on which the Permit was issued and that it can be constructed and operated accordingly." [7/26/15 EH: 67]. TransCanada directly stated that it would call seven witnesses to satisfy its burden of proof, "five of whom are direct witnesses, two of whom are rebuttal. We will present exhibits that meet that burden of proof." [7/26/15 EH: 67].

Finally, TransCanada's burden of proof was articulated by the Commission's counsel, John Smith who, after opening statements had been completed, launched the presentation of evidence by stating: "And the party having the burden of proof, the Petitioner, TransCanada Keystone Pipeline, LP, please proceed with your case in chief." [7/26/15 EH: 148]. Extending this burden further, Commission counsel even determined that since TransCanada's witnesses were describing the nature and purpose of the proposed changes in the Findings of Fact (Exhibit C to TransCanada's petition for certification), cross-examination would be permitted in those areas, despite the fact they were "not part of Conditions that I know of." [7/26/15 EH: 212-213]. Given that TransCanada advanced that proposition in its petition for certification, even the proposed changes to the Findings of Fact as to the 2010 Permit were to be used as a guideline at the hearing, per Chairman Nelson's suggestion. [7/26/15 EH: 213].

Substantial Evidence

With the burden of proof squarely on TransCanada, it has the obligation to demonstrate that it can meet that burden through the presentation of substantial evidence in support of its petition. While South Dakota's courts are obligated to give broad deference to the decisions of administrative agencies, including the Commission, judicial deference is not absolute, and courts may reverse or modify agency decisions if "…substantial rights of the appellant[s] have been prejudiced because the administrative findings, inferences, conclusions, or decisions are...(5) [c]learly erroneous in light of the entire evidence in the record; or (6) [a]rbitrary or capricious or characterized by abuse of discretion or clearly unwarranted exercise of discretion." SDCL § 1-26-36.

When deciding whether a decision by the Commission is "clearly erroneous" courts will examine whether "substantive evidence" exists in the record upon which the Commission based its decision. *Helms v. Lynn's, Inc.*, 542 N.W.2d 764 (S.D. 1996); *Therkildsen v. Fisher Beverage*, 545 N.W.2d 834 (S.D. 1996) (citing *In re Establishing Certain Territorial Elec. Boundaries.*, 318 N.W.2d 118 (S.D. 1982)); *Helms v. Lynn's, Inc.*, 542 N.W.2d 764 (S.D. 1996) (stating '[t]he issue we must determine is whether the record contains substantial evidence to support the agency's determination.'); *Abilb v. Gateway 2000, Inc.*, 547 N.W.2d 556 (S.D. 1996) (stating '[t]he question is not whether there is substantial evidence contrary to the findings, but whether there is substantial evidence to support them.'); *see also Westergren v. Baptist Hosp. of Winner*, 549 N.W.2d 390 (S.D. 1996); *Zoss v. United Bldg. Centers, Inc.*, 566 N.W.2d 840 (S.D. 1997); *Jackson v. Lee's Travelers Lodge, Inc.*, 563 N.W.2d 858 (S.D. 1997); *Rohleck v. J & L Rainbow, Inc.*, 553 N.W.2d 531 (S.D. 1996) (each case cites to and applies the substantive evidence test described in *Therkildsen, Helms*, and *Abilb*). Of note, the substantive evidence standard explicitly

applies to decisions by the Commission. See *In re Establishing Elec. Boundaries*, 318 N.W.2d at 121.

Substantive or substantial evidence is much more than a mere promise, hope, or conclusory statement. SDCL § 1-26-1(9) defines the term as "…such relevant and competent evidence as a reasonable mind might accept as being sufficiently adequate to support a conclusion." South Dakota's Supreme Court delved into the meaning of this requirement in *M.G. Oil Co. v. City of Rapid City*, 793 N.W.2d 816 (S.D. 2011). The *M.G. Oil. Co.* case involved an application for a conditional use permit to operate a video lottery casino. *Id.*, at 817. Rapid City's City Council could deny issuing a permit if it concluded that the permit would cause an undue concentration of similar uses, resulting in blight, deterioration or substantially diminished or impaired property value. *Id.* at 822. The "evidence" at a public meeting consisted of vague conclusory statements as to the potential impact of granting the permit – mainly, allegations that an increase in crime would occur. Additionally, a City Alderman expressed his belief that real estate values might fall as a consequence of issuing the permit. *Id.*, at 821-22. As a result the City Council voted to deny the permit. The applicant appealed arguing that the City's decision was arbitrary and capricious and an abuse of discretion. *Id.*, at 820.

In looking at the substantial evidence requirement, the Court examined whether the testimony and comments submitted during City Council meetings constituted substantial evidence upon which the Council could base its decision. *Id.*, at 822-23. Its conclusion was that it was not. The Court held that "[v]ague reservations expressed by [Council] members and nearby landowners are not sufficient to provide factual support for a Board decision." *Id.*, at 823 (citing *Olson v. City of Deadwood*, 480 N.W.2d 770, 775 (S.D. 1992)). Of note, the Court also stated that the City's failure to link specific and substantive testimonial evidence to the governing statute resulted in nothing more than simply repeating the language of the ordinance as a basis to deny the permit. *Id.* 823-24. That did not constitute substantial evidence in the Court's eyes.

TransCanada's case presents the same issue. Its witnesses' testimony largely consisted of conclusory, unsupported statements that it would comply with the conditions of the 2010 Permit. That is insufficient and does not constitute the substantial evidence necessary to support granting its petition.

Public Trust Doctrine – Commission has a Fiduciary Duty

In addition to determining whether TransCanada has presented substantial evidence demonstrating that it continues to meet the conditions of the 2010 Permit, in making its decision whether or not to grant TransCanada's petition for certification under SDCL § 49-41B-27, the Commission is held to a higher standard under the principles of the public trust doctrine. The public trust doctrine holds that certain natural resources belong to all and cannot be privately owned or controlled because of their intrinsic value to each individual and society. Public governmental bodies such as the Commission are, in effect, held to be trustees, with a fiduciary duty owed to the public to safeguard those resources. "[T]he Public Trust Doctrine is a critically important reminder of the duty of government to preserve wildlife, to protect the public's right to enjoy and benefit from a diverse ecosystem, and the duty of courts to carefully scrutinize any attempts to abandon the public trust in those resources." *Center for Biological Diversity, Inc. v. FPL Group, Inc.*, 166 Cal. App. 4th 1349 (2008) (quoting Carstens, *The Public Trust Doctrine: Could a Public Trust Declaration for Wildlife Be Next?* (2006) vol. 2006, No. 9, Cal.Envtl. L.Rptr. 1).

South Dakota has explicitly recognized the public trust doctrine. The most recent and most discussed case is *Parks v. Cooper*, 676 N.W.2d 823 (S.D. 2004), which held that "as matter of first impression, all water in South Dakota belongs to the people in accord with the public trust doctrine ..." This principle in South Dakota extends back to the earlier part of last century, when in *Filsrand v. Madson*, 35 S.D. 457 (1915), the Court held that a riparian owner of water cannot interfere with "navigating, boating, fishing, fowling and like public uses" by the public. Interestingly, while not directly

addressing the public trust doctrine, the South Dakota Supreme Court, in *State v. Schwartz*, 689 N.W.2d 430 (S.D. 2004), stated:

"South Dakota retains a distinctly individual character, evident in its diverse communities, its amalgam of cultures, its mixture of heritages, and its contrasting terrain. Matters unique to South Dakota may generate a reason to view a particular constitutional provision differently. ... [O]ur decision in *Parks v. Cooper* exhibits the type of deeply rooted regional issue—preservation of precious water resources through the public trust doctrine—that a court might take into account in examining a disputed provision of our constitution." *Id*.

DRA suggests that the public trust doctrine imposes upon the Commission a heightened fiduciary standard when it comes to protecting South Dakota's environment and resources from damage that could be caused by a pipeline leak or spill. While the Courts have explicitly referenced the public trust doctrine extending to protection of the State's water resources – which, by necessity, would include its surface and groundwater – the same principle applies to protection of the State's land, including its soil, native grasses, and crops. DRA suggests that the application of the public trust doctrine means that the Commission should set a higher bar for companies such as TransCanada, whose activities risk damaging the State's land and water resources.

TransCanada FAILS TO MAKE ITS CASE

With the procedural standards firmly in mind, the Commission must decide whether TransCanada met its burden of proof through the presentation of substantial evidence demonstrating that it could continue to meet the conditions of the 2010 Permit. The entire purpose of having a nine-day evidentiary hearing was to provide TransCanada with an opportunity to present substantial evidence. In the end, TransCanada embodied the classic fairy tale of the emperor who wore no clothes. Its case was sorely lacking. TransCanada's witnesses presented conclusory statements that were largely untied to specific conditions. Where conditions were referenced, TransCanada largely failed to present supporting evidence.

Witness after witness presented by TransCanada agreed that their pre-filed substantive written testimony was not related to showing compliance with any specific condition of the 2010 Permit, but

instead, to support TransCanada's proposed amendment of the Findings of Fact.¹ For example, the President of TransCanada's Keystone system, Corey Goulet [7/27/15 (Goulet) EH: 148, 7/29/15 (Goulet) EH: 507] stated: "The changes discussed in FF 24-29 related to demand, do not affect Keystone's ability to meet the conditions upon which the Permit was issued." Direct Testimony of Corey Goulet, HP 14-001, ¶11, p. 5. When asked if this statement referred to Amended Conditions 6, 7, and 37, Goulet could only answer: "I'll just refer to those Conditions, but I believe that that's part of my certificate as well." 7/27/15 (Goulet) EH: 151. Goulet offered no proof showing how TransCanada had been and would be able to continue to do so. See, as further examples of the record: 7/29/15 (Schmidt) EH: 531-532;² 7/30/15 (Tillquist) EH: 655-656; Meera Kothari (agrees pre-filed testimony makes no reference to any Amended Condition it purportedly provides evidence for. 7/31/15 (Kothari) EH: 1078). However, while Kothari generally testified that her pre-filed testimony "related" to Amended Conditions 2 and 31 [7/30/15 (Kothari) EH:993, 1064-1065], she made no connection in her oral testimony between any particular testimony as evidence showing TransCanada's history and continued ability to comply with the 2010 Permit.

Demonstrating a remarkable ability to pass the buck, many of TransCanada's witnesses claimed that others could better answer questions being posed. Most of the TransCanada witnesses who said so named Meera Kothari as the person who could answer their questions about:

• Whether representatives of TransCanada's "engineering or construction department" would testify at the hearing: 7/27/15 (Goulet) EH:182.



¹ Each objection to admission of pre-filed written testimony based only on Findings of Fact and not specific Amended Conditions was overruled by the PUC. 7/28/15 (Goulet) EH: 474; 7/29/15 (Schmidt) EH: 533; 7/30/15 (Tillquist) EH: 658; 7/31/15 (Kothari) EH:1078. DRA respectfully submits such rulings were in error and seeks reversal of the admission of such evidence as being irrelevant to whether TransCanada has been and will continue to comply with the Commission's Amended Conditions, by way of reconsideration.

² Although Schmidt responded to TransCanada Attorney White, that such testimony related to Amended Conditions 1-3, 6, 13-16, 20, 22, 26, 41, 43, 44, there was no testimony by Schmidt as to how such evidence showed TransCanada had been and will continue to comply with all or even these specific Amended Conditions. [7/29/15 (Schmidt) EH: 533].

- The length of the proposed KXL Pipeline to be above versus below ground. 7/28/15 (Goulet) EH:335-336.
- Whether there had been consultation with and input from nearby and affected tribes as to routing issues. 7/27/15 (Goulet) EH:182.
- Specifically whether the Yankton Sioux Tribe was notified of proposed local route changes.
 7/27/15 (Goulet) EH:170.
- Whether TransCanada provided contact information for its land representative Sarah MeTransCanadaalf to landowners, the designated TransCanada public liaison. 7/27/15 (Goulet) EH:171
- About KXL routing, particularly through John Harter's land. 7/29/15 (Schmidt) EH:628.
- Details about the "89 crossings of pipeline" in the South Dakota portion of the proposed KXL Pipeline and particular waterbody crossing plans. 7/28/15 (Goulet) EH:260-261.
- How large a creek needs to be before TransCanada proposes Horizontal Directional Drilling (HDD) be used for the crossing. 7/28/15 (Goulet) EH:336.
- Details about the HDD process [7/29/15 (Schmidt) EH:545], including open cut and HDD
 "construction methodologies." 7/29/15 (Schmidt) EH:627.
- Details regarding the proposed HDD Bridger Creek crossing. 7/28/15 (Goulet) EH:279.
- Explanations as to why the Bridger Creek crossing has now be selected by TransCanada for utilization of HDD rather than open cut methods for pipeline installation. 7/29/15 (Schmidt) EH:589.
- What kind of pipe is used by the Mni Wiconi Water system at the location where it is proposed to be crossed over by the proposed KXL Pipeline. 7/29/15 (Schmidt) EH:633.
- Whether planning by TransCanada for the proposed KXL Pipeline includes the occurrence of earthquakes. 7/28/15 (Goulet) EH:336.
- Whether sliding slope soil concerns caused re-routing of KXL. 7/29/15 (Schmidt) EH:577.

• Information about the TransCanada website which had contained a section regarding a South Dakota voluntary evacuation zone. 7/28/15 (Goulet) EH:281-282.

Curiously and significantly, as the Commission weighs any purported claims of compliance with the Amended Conditions of the 2010 Permit, although Kothari was called by TransCanada as a witness "to speak to the engineering design construction for that project" [7/30/15 (Kothari) EH:1010], she was not and has never been licensed to provide engineering services in the United States. 7/31/15 (Kothari) EH:1124. *Kothari, despite her supervisory work on projects in the United States, never made any effort to become licensed to professionally work in the United States as an engineer.* 7/31/15 (Kothari) EH:1202. Remarkably, Kothari admitted, "I don't perform any specific services. My role ... as the project engineer is to know the requirements and ensure that we have subject-matter experts and specialty engineers who can fulfill that function." *Id.* This is significant because the record shows that TransCanada failed to call any of the subject-matter experts and specialty engineers on the KXL Pipeline project who could arguably have presented the substantive evidence that was lacking. In short, when it comes to substantial evidence, TransCanada's witnesses largely passed the buck to Kothari, who was ultimately found to be holding an empty bag.

However, although having served as the former lead project engineer for the KXL Pipeline³ [7/30/15 (Kothari) EH:993], Kothari had overall engineering oversight for the Keystone Pipelines, including the proposed KXL Pipeline [7/30/15 (Kothari) EH:1010, 1083]. That duty involved "oversight of the third-party engineering firm that was responsible for pipeline design," specifically for "routing,"⁴ "materials selection," and "interfacing with other disciplines within the project team" [7/31/15 (Kothari)



³ TransCanada failed to present the current project engineer, hopefully licensed as an engineer in the United States, who could educate the Commission as to his or her duties and actually answer the many questions about the current design plans for the KXL Pipeline, ostensibly showing incorporation of the Commission's 50 Amended Permit Conditions, including PHMSA's 59 Special Conditions. However, choosing not to, TransCanada instead presented the former project engineer who was unlicensed in the United States to perform professional engineering services.

⁴ At least prior to her testimony in 2009, Kothari had not looked at any USGS geological maps along the route which the KXL Pipeline was proposed and TransCanada previously made little mention to the Commission of the existence of a lengthy slope slide high hazardous areas at that time. 7/31/15 (Kothari) EH:1103.

EH:1052-1053]. She described herself as having not been "the responsible engineer for the base Keystone so I was not the licensed engineer in charge of authenticating the designs" and "was there to provide company oversight." 7/30/15 (Kothari) EH:1013. Kothari said she provided "engineering construction support to the project management team" during construction of Gulf Coast segment. 7/30/15 (Kothari) EH:1011-1012.

Suggestive of her qualifications as an engineering expert, her engineering skills and value of her testimony, TransCanada was "transitioning" Kothari into a new, non-engineering position in its "business development" department, which would be "non-technical" in nature and not include providing engineering advice to decision makers regarding prospective development projects and the commercial marketing groups. 7/30/15 (Kothari) EH:1009; 7/31/15 (Kothari) EH:1060. Remarkably, this was a position in business development for which Kothari had little training or education. 7/31/15 (Kothari) EH:1091.

For someone proffered as being in an oversight capacity over design and construction of the KXL Pipeline, Kothari displayed a remarkable lack of information and was even dismissive of the specifics of major safety issues clearly within duties. For some examples, Kothari acknowledged that she was unable to answer questions about:

- spills from the base Keystone pipeline system, as leaks during operation of Keystone Base were
 "not within" her "scope of responsibility."⁵ 7/30/15 (Kothari) EH:1011, 1018-1019;
- organic chemistry questions regarding the fusion bonded epoxy (FBE) coating on the pipelines
 [7/30/15 (Kothari) EH:1019],⁶ only "to a certain extent" the vulnerabilities of FBE [7/30/15 (Kothari) EH:1019];



⁵ While Kothari later testified: "I believe I'm aware of all the pipeline related issues specifically. That's within my scope" [7/30/15 (Kothari) EH:1030], she previously had said: "I'm not familiar with the details specific to those spills". [7/30/15 (Kothari) EH:1005].

⁶ This despite Kothari having had a job as an engineer in the pipeline integrity engineer for asset responsibility for TC for nearly three and one-half years within a department that involved coating. 7/31/15 (Kothari) EH:1088-1089.

- corrosion and cathodic protection issues as a specialist [7/30/15 (Kothari) EH:1027, 1088],
 including describing and differentiating between AC and DC current corrosion [7/30/15 (Kothari) EH:1031];
- operational aspects of the base Keystone Pipeline [7/30/15 (Kothari) EH:1025]; about any electrical engineering issues [7/30/15 (Kothari) EH:1030];
- corrosion engineering issues [7/30/15 (Kothari) EH:1032];
- the chemistry of crude oil, including the different hydrocarbons contained therein [7/31/15 (Kothari) EH:1051-52];
- "any specific details" about "measures and verification and testing that were done during that integrity program" after a 2009 PHMSA advisory about installation of "lower strength" steel pipe 7/31/15 (Kothari) EH:1055, 1057] nevertheless, she claimed it was still safe [7/31/15 (Kothari) EH:1058;
- root causes of pipeline deficiencies [7/31/15 (Kothari) EH:1058], and whether it was a chemistry or fabrication problem [7/31/15 (Kothari) EH:1057-1058];
- the type or specific location of the threaded fitting issues causing pump station leaks on Keystone Base in the first year [7/31/15 (Kothari) EH:1058];
- other than changed route in Nebraska, why the first application to the US State Department was denied [7/31/15 (Kothari) EH:1068];
- PHMSA's accusations against TransCanada for failure to adequately monitor pipelines by air patrols ("not specifically aware") [7/31/15 (Kothari) EH:1074-1075].

Kothari agreed, in sum, that there were quite a few skills, training, and experience that she did not have to do her job, which caused her to "rely on my engineering specialty disciplines to provide that additional review and oversight as it comes up through to the management review of those particular issues." 7/31/15 (Kothari) EH:1083. Again, the majority of TransCanada's witnesses deferred to Kothari as the former lead project engineer for the KXL Pipeline, but in the end, she was found lacking. As is



TransCanada's "substantial evidence" of its ability to comply with the Amended Conditions of the 2010 Permit.

Heidi Tillquist was TransCanada's second most deferred-to witness. Although qualified as an environmental toxicologist, Tillquist also failed to show how TransCanada was meeting each of the Amended Conditions of the 2010 Permit and would continue to do so. In fact, Tillquist's testimony revealed that TransCanada not even completed its engineering analysis for the KXL Pipeline. [EH: 825-826].

A large portion of Tillquist's testimony focused on her performance of risk analysis with respect to the probabilities of pipeline leaks and spills, as well as possible spill volumes and the environmental effects of a spill. Rather troubling, her testimony exposed serious holes in TransCanada's purported ability to comply with the Amended Conditions of the 2010 Permit, and very possibly a disregard for the safety of South Dakota's residents and environment. This was highlighted by her admission that her choice of statistical methodologies used to calculate the risks posed by the KXL Pipeline were, in part, designed for public relations purposes. [EH: 844-847].

Casting further doubt on TransCanada's presentation of the risks posed by the KXL Pipeline, Tillquist revealed a startling deficiency in her analysis by acknowledging she did not know what a "black swan even" was. [EH: 850]. The black swan theory or theory of black swan events is perhaps one of the more widely-known principles of risk analysis. It is a metaphor that describes an event that comes as a surprise, has a major effect, and is often inappropriately rationalized after the fact with the benefit of hindsight. The theory was developed by Nassim Nicholas Taleb⁷ to explain: (a) the disproportionate role of high-profile, hard-to-predict, and rare events that are beyond the realm of normal expectations in history, science, finance, and technology; (b) the non-computability of the probability of the consequential rare events using scientific methods (owing to the very nature of small probabilities); and

⁷ Taleb is a bestselling author, is Distinguished Professor of Risk Engineering at the New York University Polytechnic School of Engineering, and as co-Editor in Chief of the academic journal, Risk and Decision Analysis.

(c) the psychological biases that blind people, both individually and collectively, to uncertainty and to a rare event's massive role in historical affairs.

For Tillquist to hold herself out as risk analyst and have no knowledge of a key principle of risk analysis is remarkable. Instead, she admitted that her risk analysis was based largely on analysis of the PHMSA database [EH: 825-828], which she acknowledged only contained domestic data. [EH: 830-831]. She also acknowledged that her risk analysis excluded risk of spills at tanks and terminals [EH: 832], that she did not take geographical variance into account [EH: 861-863], that she was unable to factor in different construction and operation standards between pipeline companies reporting in PHMSA database [EH: 834-835], and that her risk analysis failed factor in increased likelihood of adverse weather events [EH: 867]. This last point was crucial in light of her admission that she did not take into account data on adverse weather events such as the two contiguous hurricanes that caused damage to a TransCanada pipeline in Guadalajara, Mexico [EH: 2380-81].

Tillquist's risk analysis ultimately proved to be folly. She testified that her calculation of a risk of a spills was conservative (2.2 spills over 10 years), yet real-world experience resulted in spills on the base Keystone pipeline that greatly exceeded her estimates (12 spills shortly after being placed in service). [EH: 855-856, 860]. When asked about risks from landslides, Tillquist admitted her risk data was taken from an analysis of the entire PHMSA database and was not localized to areas of high risk. She stated that TransCanada would perform a more detailed engineering analysis, but that had not been completed. [EH: 871-872].

Compliance with environmental laws and regulations designed to protect water and other natural resources from harm is a critical component of the Amended Conditions contained in the 2010 Permit. Given that Tillquist testified that hundreds of High Consequence Areas exist in South Dakota [EH: 886-887], and that the chemical constituents of the diluted bitumen to be transported by the KXL Pipeline, including the BTEX complex of chemicals, are harmful to human health in small quantities [EH: 883-885], instead of bolstering TransCanada's case, her testimony revealed a tremendous lack of substantial

evidence that TransCanada can even begin to comply, much less continue to comply, with the Amended Conditions of the 2010 Permit.

Continuing its failure to show how it can comply or continue to comply with the Amended Conditions of the 2010 Permit, including addressing the inadequacies in evaluation and analysis required for a more accurate risk analysis, TransCanada did not even present evidence that it was addressing issues noted by US State Department analysts in the 2014 FSEIS. For example:

- "at...small stream crossings, TransCanada needs to conduct location-specific analysis of fate and effects of spills...consider the use of additional valves &/or noninvasive boring technologies."
 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(24), p. 37]
- E^xponent identified "additional potentially sensitive ecological areas and where Keystone's release analysis shows potential exists for medium to very large spills." 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(24), p. 37.
- Regarding "expressions of average risk, care should be taken when stating a U.S. threat rate, or state level threat rate because downplays the absolute importance of potentially large localized and/or periodic events." [FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(15a), p. 33] and including "overland flow (spreading)" [*Id.*, 3.0(17), p. 34], "4 streams identified by E^xponent" [*Id.*].
- TransCanada's risk assessment should include evaluation of potential damage of a spill "at least 10 miles downstream "...for identifying sensitive areas and contributory pipeline segments "during .. final design phase." [2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(18), p. 34]. As the FSEIS pointed out, such studies are needed to determine if "sensitive areas," in order to be "protected," whether still "additional valves would not have a net benefit." *Id.*, 3.0(18a), p. 34.

- "[I]f...PHMSA approves construction" of the KXL pipeline, the FSEIS recommended that TransCanada "should assess incident likelihood considering the benefits of (having) "alternative, preventive, protective, and mitigating features in place." 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(15a), p. 33.
- TransCanada needs to conduct a "stream-specific scour analysis" for small streams in light of
 potential for flood events, specifically for small stream crossings identified by E^xponent where
 TransCanada plans to bury pipe through open cut methodology, less than five feet below creek
 bed. 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures
 Recommended, 3.0(25), p. 37-38.
- TransCanada used a "query process" which utilized CAUSE and GEN__CAUSE fields "to obtain...cause/threat results." It "appears...their ouTransCanadaomes exclude the facilities which are an essential element of any pipeline system." FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(19b), p. 34. A "better approach" would "capitalize on PHMSA National Pipeline Mapping System to geolocate the historic spill records as the means to better quantify localized threats." 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(19b), p. 35.

Of note, TransCanada failed to present substantial evidence, much less any evidence at all, as to how it would deal with these crucial risk factors in order to minimize harm to the environment and to water resources.

DRA would also ask the Commission to take administrative notice of Kothari's prior testimony before the Commission in evaluating both her credibility and the significance of prior admissions. For example, by 2007 TransCanada reported some "576" spills from its pipeline system, of which "80%" involved "equipment related spills of "hydraulic oil, lube oil, glycol and fuel." Written Testimony of Meera Kothari, HP 07-001, Ques. 19, p. 5. TransCanada had already experienced 20 "near misses" [*Id.*, Ques. 19, p. 6], 28 of which were "serious," meaning "less than 20 gallons" spilled [*Id.*], one was

"critical," involving "approximately "100 gal. of various liquids such as lube oil [*Id.*]." In a 1996 incident at one the pump stations on the TransCanada-operated Platte Pipeline, "approximately 220 bbls of oil were released" of which "none" recovered. Written Testimony of Kothari, HP 07-001, Ques. 21, p. 6.

To estimate the likely number of spills expected from the KXL Pipeline, the FSEIS advised TransCanada that it should include "threat-based sensitivity analysis including scope and results." FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(14), p. 33. The FSEIS found that TransCanada had "not used" "sensitivity analysis to understand the underlying drivers for incidents when estimating spill frequencies" FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(14a), p. 33. The State Department analysts advised TransCanada that Battelle suggested that such "sensitivity analysis could help identify localized threats." *Id*.

Risk assessment is required by PHMSA - Condition 14 and 49 CFR 195.452 for HCAs. FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(14), p. 33. The State Department analysts noted the "large differences" between "system components and facilities that comprise the discrete elements cast uncertainty on the use of aggregated metrics for risk" and equally cast uncertainty on the use of aggregated "professional engineering judgment." [2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(26), p. 38. For example, the 2014 FSEIS further observed that seals and seats have a "higher potential for spills than (on equipment & pumps)" 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(11)(a), p. 32. Due to "dominance" of risks "associated with mainline pipe and other system components (other than mainline valves or tanks)" the "risk assessment" required by 29 CFR 195.452 should address both "to effectively reduce risk," observing that 97% of risk occurs in mainline pipe and "fixed facilities" (e.g., pumping stations. 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(20a), p. 35. The State Department reported that it expected TransCanada to be "diligent" in its "material section for" these components. FSEIS,

Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(11)(a), p. 32]. Remarkably, TransCanada provided no substantial evidence during nine days of evidentiary hearings to demonstrate compliance – other than conclusory statements promising compliance.

KXL to be Safest Pipeline?

In response to Commissioner Hanson's statement during the hearing of how he had read and heard "several" times that the KXL will be "the safest pipeline ever built", Goulet gushed how no other pipeline has been requested to incorporate 59 special conditions (referencing Appendix Z of the FSEIS), and as such, other pipelines "don't have the redundancies and safety measures which we will build on KXL." 7/27/15 (Goulet) EH:302. The colloquy continued:

Hanson: It sounds as if, though, it might be safer to say it's one of the safest pipelines....can you honestly say this is the safest....?

Goulet:until we build the pipeline, I suppose we can't say it is ...

7/27/15 (Goulet) EH:303.

Yet, later during later under cross-examination, Goulet clarified that he "never said it will not leak" ... and "can't predict" whether a leak would be large or small. "I can't predict the future." 7/28/15 (Goulet) EH:354.

Goulet's backtracking is not surprising when seen in the light of Kothari's acknowledgment that, since 2010, TransCanada has not submitted any detailed geologic, biologic, environmental, engineering studies and current designs to the Commission for review as to sufficiency or accuracy, or to show compliance with any of the 50 Amended Conditions. Similarly, TransCanada has not submitted updated or corrected design plans and environmental studies surrounding HCAs [7/31/15 (Kothari) EH:1117], or otherwise presented the Commission with evidence it is in compliance with the many deficiencies in

evaluations, analysis, or otherwise completed to address many important issues necessary to show it can safely construct the KXL Pipeline.

TransCanada Admitted It Cannot Meet Condition 3

Significantly, TransCanada's paid corporate expert witness Jon Schmidt agreed during crossexamination that TransCanada cannot meet Amended Condition 3 of the 2010 Permit since the submission and testimony to the Commission in these proceedings were based upon a US State Department Permit Application that had been denied [7/29/15 (Schmidt) EH:542].

In addition to TransCanada's failure to meet its burden of proof to warrant certification, the hearing evidence tends to show the contrary.

Kothari testified she performed "oversight" for TransCanada of the "design and engineering" on the Gulf Coast and Keystone Base pipeline design and construction projects. 7/31/15 (Kothari) EH:1090. However, she quickly attempted to absolve herself of responsibility for any design or construction related flaws in the respective pipelines since she didn't design the pipelines and an authenticating engineer, not her, was responsible to ensure pipeline designed and built correctly. 7/31/15 (Kothari) EH:1090-1091.

Kothari agreed that "preventing leaks is a primary goal because any leak could release product into potentially sensitive ecosystems or critical resource areas" and testified it was a "one of the primary goals". 7/31/15 (Kothari) EH: 1091. However, like other parts of her testimony, her rose-tinted sugar-coated promises to comply with all Amended Conditions of the 2010 Permit can be seriously questioned by the evidence in the record.

What TransCanada would like to transport through South Dakota is a "hazardous liquid". 7/31/15 (Kothari) EH: 1092. And, "modern pipelines can fail in a number of different ways." This includes "internal and external corrosion, third party damage, equipment failure, or outside force type failures." 7/31/15 (Kothari) EH: 1092. Part of Kothari's job was to "review potential pipeline threats to the pipeline and work with our design engineers to ensure that we have safeguards and various design requirements built in to prevent, mitigate, and monitor those particular threats to the pipeline." 7/31/15 (Kothari) EH: 1092-1093.

Despite these assuring words, the evidence in the record shows that TransCanada has a questionable ability or willingness to comply with all applicable design and construction regulations of all agencies which have established permit conditions (Condition 2), should provide, in addition to TransCanada's failure to meet its burden of proof, providing an additional basis for this Commission to deny recertification of the construction permit for TransCanada.

59 Special Conditions "were put out by PHMSA" regarding the proposed KXL pipeline. 7/31/15 (Kothari) EH: 1115. These 59 Special Conditions are eight additional to those PHMSA required on the base Keystone. 7/28/15 (Goulet) EH: 354. Amended Condition 2 provides that TransCanada comply with any conditions imposed by any permitting agency, including PHMSA (see Finding of Fact 22). Yet in a revealing moment for this Commission to consider in terms of TransCanada's willingness to comply with permit conditions, TransCanada has taken the position that the 59 Special Conditions imposed on the KXL Pipeline by PHMSA need only be complied with if the hazardous material transportation company chooses to do so. As Kothari testified, at this point in time, TransCanada has "voluntarily adopted to apply those Permit Conditions." 7/31/15 (Kothari) EH:1079-1080, 1105, 1110. See, Direct Testimony of Corey Goulet, HP 14-001, ¶9, p. 3; 7/27/15 (Goulet) EH:215, 216. This despite the admission that there is no correspondence from PHMSA telling TransCanada that the 59 Special Conditions are merely "advisory." 7/31/15 (Kothari) EH:1106. By way of further example, there is no SCADA requirement in Amended Conditions, although TransCanada recognizes there is one from PHMSA in the 59 Special Conditions - Appendix Z to the FSEIS. 7/31/15 (Kothari) EH:1076.

Failure to Recognize Magnitude and Risk of Routing Pipeline through High Hazard Slip Slope Areas.

Dr. (and now Professor Emeritus of geology) Arden Davis of the South Dakota School of Mines [8/3/15 (Davis) EH:1784], testified that from the USGS map in the FSEIS, he estimated the pipeline would travel within "slightly more than 150 miles of Pierre Shale." 8/3/15 (Davis) EH:1784. The Commission has in the record the USGS map of South Dakota with the pipeline drawn through the various geologic formations along its proposed route. The USGS map characterizes a significant portion as a "high landslide Hazard Area." RST EX-4, also contained within the 2014 FSEIS, Volume 2, Chapter 3, 3.1 Geology, Figure 3.11.2-3, p. 3.1-29.

Yet, despite such evidence and TransCanada's purported commitment to follow the guidance and recommendations in the FSEIS in the construction of the KXL pipeline, and perhaps reflective of other evidence that regulatory safety requirements are merely voluntary, and defective design or construction issues seem to never involve real pipeline safety issues, just meaningless regulations, this Commission heard testimony that TransCanada considers only 1.6 miles of its proposed route to be "considered in that high hazard, high landslide type scenario." Responded Dr. Arden: "I would be very surprised to hear that." 8/3/15 (Davis) EH: 1796. And what should be of additional concern to the Commission, TransCanada is not sure if even this minute portion of the KXL Pipeline route is really in such a high hazard area. 7/31/15 (Kothari) EH:1094-1097. This despite Kothari's agreement that the USGS map in the FSEIS shows the pipeline traversing up to 150 miles of the high hazard slide topography just between four planned pump stations. 7/31/15 (Kothari) EH:1097.

To his credit, TransCanada witness John Schmidt acknowledged that slope stability is an important consideration as to routing of pipeline. 7/29/15 (Schmidt) EH:578. If "there's slope coupled with erodible...then yeah, you look to try and minimize," claiming it would become a "reclamation issue" following construction, since it would be "difficult to maintain that right of way." 7/29/15 (Schmidt) EH:581. He further agreed that bentonite soils would "potentially" create a "stability problem," especially when "coupled with water source and slope and other factors." 7/29/15 (Schmidt) EH:582.

He agreed ground movement "may" occur in this area of the State due to presence of Pierre Shale, especially the bentonite layers. 7/29/15 (Schmidt) EH:594.

Dr. Davis described the clay nature of bentonite and what should be remembered about construction where it predominates the ground-structure: "It's a platy mineral that can absorb water in betwen the sheetlike layers....up to around 190% of its own weight in water....And when it absorbs water then it's prone to failure." [8/3/15 (Davis) EH:1788].

From his knowledge of the high slide areas depicted on the USGS map, Schmidt agreed the "land forms and topography of the area" the KXL pipeline is routed to go through "is characterized by dissected plateau with river channels that have incised into the landscape" and the each has numerous tributaries that feed water into the major rivers 7/29/15 (Schmidt) EH:586-587. Such are "important" component of "watershed." 7/29/15 (Schmidt) EH:588.

Schmidt also acknowledged that additionally along the KXL Pipeline route, almost all of Haakon, Jones, and portions of Tripp County have potentially unstable "gumbo" soils. 7/29/15 (Schmidt) EH:593. He did "not" know status of any plans to compensate for weather issues during construction, as required by Amended Condition 25 [7/29/15 (Schmidt) EH:623], despite this area and the areas with bentonite soils were susceptible to instability upon weathering [7/29/15 (Schmidt) EH:594], "basic wind, sun, water...those are mainly the erosive forces." 7/29/15 (Schmidt) EH:623

However, as the TransCanada contractor charged with responsibility for "cultural surveys, biological surveys, wetlands, water bodies, things of that nature" [7/29/15 (Schmidt) EH:540], he "wasn't aware" of a recent 500 year flood, then admitting that 2, 3, 4, or 5 inches of rain "could" create a problem for the KXL Pipeline in unstable soils.⁸ 7/29/15 (Schmidt) EH:583. He also did not recall seeing information in the 2014 FSEIS he reviewed [7/29/15 (Schmidt) EH:555] that a majority of pipeline through South Dakota is routed through what was described as a "high landslide hazard area," and

⁸ Schmidt acknowledged that clay is well-known for absorbing large quantities of water. 7/29/15 (Schmidt) EH:591.

disagreed it did so. 7/29/15 (Schmidt) EH:583-584. He acknowledged TransCanada's proposed rerouting maps did "obviously not" remove the pipeline from such high landslide hazard areas shown on the USGS map. 7/29/15 (Schmidt) EH:584.

So far and fortunately, evidence in this record show that most of the spills from the Keystone pipeline system to the Gulf of Mexico have been relatively minor and there have only been "near misses" of potentially disastrous incidents. By way of the examples discussed below, the DRA respectfully submits that TransCanada's history of safety issues should give further pause by any Commissioner of a thought of granting certification.

2009 Incident

Kothari admitted some knowledge about pipeline integrity issues arising in pipe used by TransCanada. There was a "PHMSA advisory...issued late in 2009 related to low yield materials that potential pipeline operators would be susceptible to." [A]s we moved into operations...integrity management folks developing plans, implementing plans, to meet that advisory requirement." 7/31/15 (Kothari) EH:1055. The advisory "requested operators to verify the integrity of the pipeline" regarding a materials issue. 7/31/15 (Kothari) EH:1055. TransCanada's response included "digs involved ... locations ... identified through high resolution in-line inspection, as per the advisory requirements." 7/31/15 (Kothari) EH:1055.

Reflecting TransCanada's attitude towards safety regulations, Kothari saw nothing "wrong" with below PHMSA regulation "lower-strength" pipe being used in TransCanada's pipelines or it being insufficient to meet safety specifications from PHMSA, claiming, nevertheless, it was "[n]othing that would ensure the ongoing safe operations of the pipeline." 7/31/15 (Kothari) EH:1056-1057.

Pipeline Safety History - Spills

Kothari acknowledge that there were 14 spills in 1st year of operation of TransCanada's Keystone Base pipeline.⁹ 7/30/15 (Kothari) EH:1005, 1006. Nevertheless, according to TransCanada, a pipeline which leaks 14 times in its first year is "safe" 7/30/15 (Kothari) EH:1007. Goulet admitted the number but described them all as only "minor" and were "associated with small diameter fittings and seals." 7/28/15 (Goulet) EH:355. Kothari admitted being "familiar generally we had a number of leaks at the pumping stations upon initial operations." 7/31/15 (Kothari) EH:1053.

Ludden spill

The largest spill the first year of operation of the Keystone Base pipeline was at Ludden Pump Station. *See DRA Exhibits 69, 70 and 172, attached hereto as Exhibits A, B and C.* Kothari's understanding was the problem involved a "small above-ground component, such as a fitting...some of the issues were" cause of leaks 7/31/15 (Kothari) EH:1053. "[I]t was threaded fitting," which leaked. 7/31/15 (Kothari) EH:1058. Despite her oversight responsibilities, she "wouldn't know the specific manufacturer" of the fitting. 7/31/15 (Kothari) EH:1058.

As to the Ludden Pump Station spill in May of 2001 of some 400 barrels of crude, Kothari knew that "reports are created" and was "aware there was a spill there, but...not...all the details." 7/31/15 (Kothari) EH:1197. She had not read the reports. 7/31/15 (Kothari) EH:1197-1198. She would not guarantee that a larger spill would not happen if the KXL pipeline was constructed. 7/31/15 (Kothari) EH:1199. Indeed, Kothari was unaware of Exponent's calculations that under the latest detection equipment plan given to the State Department, a spill of some 1,400 barrels of crude could take place within two hours before it was even detected electronically. 7/31/15 (Kothari) EH:1200-1201. See, also, 2014 FSEIS, Appendix B, Potential Releases & Pipeline Safety, Mitigation Measures Recommended, 3.0(1)(g), p. 28. As Kothari agreed, that is a "real lot of crude." 7/31/15 (Kothari) EH:1201.

⁹ Kothari may have been trying to distance herself from hard questions about TC's history of leaks, asserting that such leaks were "not within" her "scope of responsibility." 7/30/15 (Kothari) EH:1011, 1018-1019.

Gulf Coast Pipeline Weld Issues

Goulet testified that he was involved construction of the Gulf Coast segment of the Keystone pipeline system, his job being to make sure TransCanada had on-sight the "proper personnel, processes & systems." 7/27/15 (Goulet) EH:198. He was "accountable" for ensuring construction in compliance with TransCanada plans and agency regulations and conditions. 7/27/15 (Goulet) EH:198. For her part, Kothari was not involved in the detailed design of the Gulf Coast pipeline, "just coming in towards the very end." 7/30/15 (Kothari) EH:1012. Further, so-called operational problems with Gulf Coast were not within her ability to testify. 7/30/15 (Kothari) EH:1011.

Goulet was "personally aware" of two PHMSA warning letters [DRA Exhibits 69¹⁰ and 70¹¹]. "One associated with welding" and "one associated with...Coating," acknowledging there "might have even been one more than one feature that was talked about." 7/28/15 (Goulet) EH:344. Goulet denied that the PHMSA communications were "compliance letters," claiming they were mere an expression of "their opinions on some potential issues they've seen during their inspections of the pipeline." 7/28/15 (Goulet) EH:340.

Goulet did acknowledge that PHMSA inspectors had concerns over coating damage due to "weld splatter" and "concern over...welding rejection rate...in the early stages of one of the spreads that was

¹⁰ DRA Exhibit 69 was excluded by the Commission for disclosure three weeks prior to the hearing. It is not a PHMSA warning letter but refers a Warning Letter dated 9/26/13 and the finding of additional PHMSA regulation violations for "failing to perform welding on Spread 3 in accordance with a procedure qualified according to §5 of API 1104" and "failing to properly qualify welders on Spread 3 in accordance with §6 of API 1104." PHMSA Evaluation Report of Liquid Pipeline Construction, "Keystone Gulf Coast Pipeline, Inspection Dates: 2011-2011, p. 2, 5, 6. There was also found to be a failure to properly inspect "all external pipe coating...just prior to lowering the pipe into the ditch." *Ibid*, p. 8. The document noted the 36 inch diameter of the pipeline. *Ibid*, p. 3.

¹¹ DRA Exhibit 70 was also excluded, for which reconsideration and admission is requested. According to the 9/10/13 PHMSA Warning Letter, it was "as a result of the inspection" by PHMSA representative, that violations of PHMSA regulations were noticed during Gulf Coast construction. "TransCanada did not assure that its Keystone Pipeline was installed in the ditch in a manner that minimizes the possibility of damage to the pipe." These included dents "that appear to be caused by secondary stresses on the pipe." Proffered DRA EX-70, p. 1. "In reviewing the submitted anomaly reports and PHMSA inspections it demonstrates that TransCanada is not following their Construction Specifications." There were also violations related to the failure of TransCanada to "follow its written specification, protecting excisting coating from damage due to welding," particularly "weld splatter." *Ibid*, p. 2.

used in that pipeline," the weld rejection rate being "between 10 and 20 percent in the early stages of the project." 7/28/15 (Goulet) EH:345. He contended there was "no issue with our quality control program" which was "why we found out we had a high incidence of weld failures." 7/28/15 (Goulet) EH:346.

Testified Goulet: "We were using qualified and approved welding procedure" and that "All" of the welders "passed a welding qualification test." The "concern PHMSA had…was…that the welders did not have the skill to be able to perform that welding in a productive manner on a continuous basis."¹² 7/28/15 (Goulet) EH:390.

"Near Miss" Near St. Louis

In pre-filed testimony [¶9], there was only one reference to a Fusion Bonded Epoxy (FBE) problem, being an instance of cathodic protection system interference in the Keystone Pipeline in Missouri, which Kothari testified was only offered to support a proposed Finding of Fact change. 7/30/15 (Kothari) EH:1024. Thus, based upon the Commission's rulings, it fails to show compliance with any condition.

The segment of the Keystone pipeline in involved in the incident was constructed by TransCanada in a pipeline corridor, some 40 feet ("so quite close") from two other metal pipelines, one transporting gas, the other crude oil. 7/30/15 (Kothari) EH:1027

The "near miss" involved discovery on the walls of buried and in-service pipe of a number of corrosion anomalies. "[W]e had corrosion identified through an in-line inspection run." 7/30/15 (Kothari) EH:1026. Although Goulet, despite the duties of his corporate position and the purported

¹² To the contrary, as excluded DRA EX-69 would resolve, PHMSA gave TransCanada "unsatisfactory" ratings for violations of PHMSA regulations requiring that: "Welding must be performed by qualified welders using qualified welding procedures;" "Welding procedures are qualified in accordance with §5 of API 1104;" "Welding procedures must be qualified by destructive testing;" "Each welding must be accorded in detail,...;" "Welders must be qualified...;" "Welders may not weld with a particular welding process unless within the proceeding 6 calendar months, the welder has - (1) engaged in welding in that process and (2) Had one weld tested and found acceptable under §9 of API 1104." (Excluded) DRA EX-69, *supra*, p. 7.

Company ethos of learning from incidents to build better pipelines, was unfamiliar with the not familiar with his Company's own Study of Root Cause and Contributing Factors to the Keystone Pipeline Corrosion Anomaly - Final Report of TransCanada 2-13-13 [7/28/15 (Goulet) EH:362-363, 374]. He further could not even generally estimate how many corrosion anomalies were discovered in the necessary digging up of sections of the hazardous pipeline. 7/28/15 (Goulet) EH:320.

Goulet said he was aware of the cause, however, being "result of interference of another pipeline that runs in parallel to that particular portion of pipeline in Missouri. And, there's also electrical transmission line, I believe, in that area as well." 7/28/15 (Goulet) EH:293-294.

Goulet attempted to absolve himself of responsibility for the "near miss" by telling this Commission that he did "not" have oversight of TransCanada operation of pipeline after closeout of construction and transfer of operations. 7/27/15 (Goulet) EH:200. Kothari testified the "root cause" of the "corrosion anomaly was related to cathodic protection interference" [7/30/15 (Kothari) EH:1026, 1029].

When asked whether TransCanada construction oversite included ensuring proper cathodic protection in place when pipeline near foreign pipeline, Goulet responded that "under the regulations, the cathodic protection system doesn't have to be operational when a pipeline goes into service" [7/27/15 (Goulet) EH:222] adding it was "actually required to be in service within 6 months...of placing the project into operation" [7/27/15 (Goulet) EH:223]. He later characterized this as "very early into the operation." 7/28/15 (Goulet) EH:310 It was never explained by any TransCanada witness nor any plan produced that this incident changed TransCanada procedures that at least anywhere near another metal pipeline or high intensity powerline, that a cathodic protection inspection would be done immediately to detect and remedy problematic cathodic interference immediately, and not wait until fortune of timing of an agency required inspection schedule prevents a "near miss."

Goulet expressed that he was "aware" that in the "past", TransCanada buried pipe with line strikes and weld splatters. "But our quality assurance process prevented that system from going into operation and we subsequently repaired those coating problems" 7/27/15 (Goulet) EH:225-226. This evidence reveals, as DRA contends, serious questions about the quality assurance process of the Keystone projects.¹³

When questioned with the pictures and contents of DRA EX-153, Goulet responded that he was "not familiar with all the details" regarding one of the corrosion anomalies which suffered a 97% wall loss.¹⁴ 7/28/15 (Goulet) EH:362. However, he was somehow able to tell this Commission that the most problematic "feature, although it was as thick as a dime, it was also only the size of a dime in diameter." 7/28/15 (Goulet) EH:309. In other words, it was still safe. However, after being confronted with photographs of the anomalies with a ruler included in DRA Ex-153, Goulet agreed the feature shown in Figure 10 of TransCanada Study was "Maybe 1 3/4 average diameter." 7/28/15 (Goulet) EH:372. Challenging the idea of another anomaly having more than a 50% wall loss, he again had to agree that a photo of another anomaly on p.18 of TransCanada Report, Dig Site 2 had a "73.9%" wall loss 7/28/15 (Goulet) EH:375, 381.

TransCanada made limited acknowledgements of the pending impact of a corrosion anomaly(ies) of this depth and size if the last bit of wall went through the outer wall, then "obviously it would create a leak." 7/28/15 (Goulet) EH:362. Goulet said of what it claimed was an abnormal event, it "wouldn't **normally** result in a burst…even a full line pressure. The "feature would have to be…inches, if not feet longer for…burst." 7/28/15 (Goulet) EH:309, 361-362. Attempting to downplay the "near miss" that



¹³ In 2012, TransCanada whistle-blower Evan Vokes filed a complaint with the Canadian NEB. In her unrefuted testimony land owner along the proposed KXL pipeline route, individual Intervenor Bonnie Kilmurry told the Commission the NEB found: "Many of the allegations of regulatory noncompliance identified by the complainant were verified by TransCanada's internal audit'." 7/28/15 (Kilmurry) EH:496.

¹⁴ The TransCanada report indicated that a one dig site alone, "Dig Site 1," where the peak depth of one anomaly was "96.8%," there were 6 anomalies caused by external corrosion. 7/28/15 (Goulet) EH:366, 371.

caused an emergency shutdown of the pipeline for four days [7/28/15 (Goulet) EH:374], Goulet said: "I don't know if I'd call it an incident, but it was a feature that was found during the in-line inspection" [7/28/15 (Goulet) EH:318-319]. He then suggested that further questions regarding this incident be directed at TransCanada rebuttal witness King. 7/28/15 (Goulet) EH:319, 320.

Kothari encouraged the Commission to not worry, since "no similar situation could exist in South Dakota because there are no shared utility corridors." 7/30/15 (Kothari) EH:1025. Goulet initially gave a similar assurance. 7/28/15 (Goulet) EH:294. However, this was not correct, as Goulet himself apparently forgot, previously acknowledging being "aware" the proposed KXL route crosses a metal pipeline of the major water transportation system, the "Mni Wiconi Project." 7/27/15 (Goulet) EH:223-224; 7/29/15 (Schmidt) EH:633.

Post-Construction Failure to Reclaim Land

Sue Sibson testified on behalf of DRA. Her testimony shows that TransCanada cannot meet its requirements under the Amended Conditions to reclaim land. The Sibsons raise grain and soybeans, and have feeder cattle on a farm in Miner County. [EH: 1949] Native grasses important to how they make a living. The base Keystone pipeline crosses property. [EH: 1950]. The 2009 construction of the base Keystone tore up their land and it is still not fully reclaimed. [EH: 1956-58]. The initial reclamation work was shoddy, as contractors rushed and did not reseed properly. [EH: 1958-59]. In the summer of 2010, mainly noxious weeds and no grasses were growing on the pipeline easement area. [EH: 1959]. Ms. Sibson testified extensively about TransCanada's failures to comply with land reclamation requirements and notes that the same issues affect her neighbors where the pipeline crosses their lands. [EH: 1994]. After six years, the Sibson's property over the easement area has no native grasses. [EH 2010-2011]. TransCanada's failure to comply with reclamation requirements is indicative of its inability to comply with the Amended Conditions.

Pattern of Regulatory Non-Compliance

Finally, the Commission heard from former TransCanada employee Evan Vokes. We will not repeat his extensive testimony about welding technology and pipeline construction. However, the crucial components of Mr. Vokes's testimony were that on the base Keystone he, worked on inspecting welds. After uncovered problems, he reported to TransCanada management that between 1200-1300 welds had been inadequately inspected. Management reproached Vokes for creating "trouble" and wanted Vokes to ignore problems. [EH: 1619-24]. Critically, Vokes testified that he was asked "many times" by TransCanada management to ignore regulatory violations. [EH: 1627].

CONCLUSION

TransCanada failed to present substantial evidence that it could comply with or even continue to comply with the Amended Conditions of the 2010 Permit. In fact, such an incomplete record was presented that even an attempt at certification is premature. TransCanada has presented its case to the Commission before even being able to begin meeting its burden.

The record is remarkable for what it does not reveal. What is missing from the overall record is substantial evidence of compliance by TransCanada. What is on the record from TransCanada's own witnesses is a lack of willingness to take responsibility, a tremendous amount of buck-passing, and the consistent use of the phrase "that's not my responsibility" and "that's not in my scope."

TransCanada has failed to meet its burden. The Commission should deny its petition for certification.

Respectfully submitted,

/s/ Bruce Ellison

Bruce Ellison 518 6th Street #6

Rapid City, South Dakota 57701

Telephone: (605) 348-1117

Email: belli4law@aol.com

and

THE MARTINEZ LAW FIRM, LLC

By: <u>/s/ Robin S. Martinez</u> Robin S. Martinez, MO #36557/KS #23816 616 West 26th Street Kansas City, Missouri 64108 816.979.1620 phone Email: robin.martinez@martinezlaw.net

Attorneys for Dakota Rural Action

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Applicable N/C – Not Checked ort.

A completed **Standard Inspection Report** is to be submitted to the Director within 60 days from completion of the inspection. A **Post Inspection Memorandum (PIM)** is to be completed and submitted to the Director within 30 days from the completion of the inspection, or series of inspections, and is to be filed as part of the **Standard Inspection Report**.

J	Inspection Report			Post Inspection Memorandum					
		Inspector/	Submit Date:						
Inspector/Submit Date: Southwest Region		Peer Revie	ew/Date:						
			Director A	pproval/Date:					
POST INSPECTION MEMORANDUM (PIM)									
Name of Operator:	TransC	TransCanada Oil Pipeline Operations Inc.				32334			
Name of Unit(s):	Keystone Gulf Coast Pipeline North / Keystone Gulf Coast Pipeline South					74979,83245			
Records Location:	Transcanada Sharepoint site, Contractor offices, Transcanada Offic				Activity #	135840 & 140666			
Unit Type & Commodity: Interstate Liquids (Crude)						•			
Inspection Type:	Construction Inspection			Inspection Date(s): 2011-2014				
PHMSA Representat	ive(s):	Clint Stephens /Jon Mannir Arnold / Noah Matthews/Bar Bill Lowry/ Basim Bacent Elmer/ David Eng/ John Peppe	ng /James rry Small/ y/ Joseph r	AFO Days:	165.9				

Summary:

The final report consists of three parts:

- 1. Form 7
- 2. Appendix A: Construction Summary
- 3. Appendix B: Review of 57 Conditions

Transcanada Keystone Pipeline LP, notified PHMSA in a letter dated September 30, 2011 of the construction of the Keystone Gulf Coast Pipeline starting in Q1 of 2012. The construction of the Keystone began in 2011 and was commissioned in 2014. Since 2011 until the commissioning of the pipeline on January 22, 2014, PHMSA, Southwest Region conducted onsite inspections and reviewed documents which include construction specifications, construction inspection reports, welding qualifications,etc.,, submitted by Transcanada. A total of 165.9 AFO days and 53.35 non-AFO days were spent on the Transcanada construction project.

In addition, Transcanada ran an in-line inspection caliper/deformation tool and conducted a DCVG survey of their entire Keystone Gulf Coast Pipeline to access any pipeline or coating damage during construction and backfilling activities. Transcanada completed the tool run and DCVG survey and found anomalies which were repaired. PHMSA witnessed part of the tool run and DCVG survey and reviewed the repair methods and records.

Transcanada submitted their Commissioning Plan to PHMSA for review before commencing commissioning/line fill activities. Line fill began in December 2014 and commenced on January 21, 2014. PHMSA engineers/inspectors were onsite to verify commissioning plan was being followed and to witness the testing of pump station alarms, valve operation and SCADA operations. On January 22, 2014 Transcanada commissioned the pipeline.

Daily reports were submitted by each engineer/inspector to document the daily construction activities observed during the inspections. The engineers/inspectors moved around the various construction activities throughout the day depending on the logistics and activities being performed. The primary focus for the engineer/inspector is to observe construction activities and gather and compile all pertinent documentation to assure regulatory compliance with 49 CFR Part 195.

All daily reports, specifications, maps, and any other information gathered by PHMSA is located in the PHMSA "P" drive Construction Folder under "Transcanada Keystone Gulf Coast Pipeline North Final Construction Report".

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Findings:

There were two Warning Letters, 4-2013-5017W and 4-2013-5021W, sent to Transcanada for non-compliance issues. The issues were:

.202- Warning letter 4-2013-5017W was sent to Transcanada on September 10, 2013 for not following their Construction Specifications to protect the coating from damage due to welding spatter.

.246(a) – Warning letter 4-2013-5017W was sent to Transcanada on September 10, 2013 for not following Construction Specifications when installing foam pillows to minimize external stresses on the pipe.

.214(a) and (b) -Warning Letter 4-2013-5021W was sent to Transcanada on September 26, 2013, for failing to perform welding on Spread 3 in accordance with a procedure qualified according to Section 5 of API 1104. Procedure KXL-SMAW-ML had revisions to essential variables which was not requalified.

.222(a) and (b) – Warning Letter 4-2013-5021W was sent to Transcanada on September 26, 2013, for failing to properly qualify welders on Spread 3 in accordance with Section 6 of API 1104. Procedure KXL-SMAW-ML had revisions to essential variables which the welders were not qualified to perform.

Transcanada responded to the Warning Letters and are located in the CPF Southwest Region files.

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Name of Operator: TransCanada Oil Pipeline Operations Inc								
OP ID No. ⁽¹⁾ 32334			Unit ID No. ⁽¹⁾ 74979 and 83245					
HO Address:			System/Unit Name & Address: ⁽¹⁾					
717 Texas Street			717 Texas Street					
Houston, TX 77002			Houston, TX 770	02				
, , , ,			,,					
Co. Official:	Mr. Vern Me	eier	Activity Record ID No.: 140666 and 135840			5840		
Phone No.:	832-320-550	95	Phone No.:		832-320-5462			
Fax No.:	832-320-646	52	Fax No.:		832-320-6462			
Emergency Phone No.:	800-447-806	6	Emergency Phon	ne No.:	800-447-8066			
Persons Intervie	wed	Т	'itle		Phone No.			
Dan Cerkoney	/	Manager Regulator	y Compliance Majo	or	713-693-6466			
Transcanada Inspe	ectors		2 1 5					
Michels Pipeline Con	struction							
Personnel								
Sunland Construction I	Personnel							
Meera Kothar	i	Eng	gineer		713-6	593-6466		
PHMSA Representative(s) ⁽¹⁾ Jon M	lanning, Jim Arnold, Agusti ens Noah Matthews Barry	n Lopez, Clint Small	Inspect	ion Date(s) ⁽¹⁾	2011-2014		
Company System Maps (Copies for Re	gion Files): Maps are loca	ted in the PHMSA	"P" Drive	,			
Description of Construct	ion ⁽¹⁾	B						
The Keystone Gulf Coast	pipeline cons	ists of 485 miles of 36 inch	X70 pipe ranging	in wall th	nickness (.465,.5	515,.572,.618, and		
.748). The pipeline starts at the TransCanada Keystone Cushing Terminal in Lincoln County Oklahoma and terminates at the								
Terminal Facilities in Ned	lerland, Jeffers	son County Texas. The pipe	eline transports crud	le oil fror	n Cushing, OK	to Nederland, TX		
where it ties into the Sunoc	co Terminal.							
Spread 1 Contractor- Mich	els Pipeline C	onstruction, MP 0.00 to 195	.00					
Spread 2 Contractor- Mich	els Pipeline C	onstruction, MP 195.00 to 3	/1./0					
Spread 3 Contractor- Sunla	and Constructi	on, MP 3/1.70 to 484.57						
10 Dump Stations								
10 Pump Stations								
PS 33 Cromwell MP 40 2	0.00							
PS-34 Tupelo MP 95 70	-1							
PS-35 Bryan MP 147 77								
PS-36. Delta. MP 194.88								
PS-37. Winnsboro, MP 238.96								
PS-38. Lake Tyler. MP 284	4.62							
PS-39. Lufkin. MP 338.74								
PS-40, Corrigan, MP 380.9	Ð							
PS-41, Liberty, MP 435.52	2							
•								
The Southwest Region inspected the pipeline in accordance with both the 57 Special Permit conditions and according to 49 CFR								
Part 195 regulations.								

¹ Information not required if included on page 1.
EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report. N/A – Not Applicable

		PIP	E SPECIFICATIONS
.51	.112		Steel Pipe
	•	Manufacturer:	Welspun (Little Rock, AR) – spiral, llva (Taranto, IT) – long seam
	•	Manufacturing Standard:	API 5L PSL2 X70M 44 th Edition
	•	Pipe Grade:	X70
	•	Outside Diameter (D):	NPS 36
	•	Wall Thickness (t):	 0.465 – Line Pipe (FBE) (PMSA 57 Conditions 1-9) 0.515 – HCA (FBE) 0.572 – Downstream of Corrigan Pump Station (FBE) 0.618 – Road Bore (FBE/ARO) 0.748 – HDD (FBE/ARO)
	•	Type of Longitudinal Seam:	Long Seam and Spiral Seam
	•	Specified Min. Yield Strength (S):	70,000
	•	Joint Design - Bevel:	V groove
	•	External Coating:	FBE
	•	Internal Coating:	N/A
	•	Minimum Joint Length:	Minimum of 8' typical double joints 76'
	•	Footage or Miles:	485 miles

Comments:

Pipe was stamped with the specifications and was verified in the construction inspections. Mill test reports were submitted to PHMSA to verify pipe specifications.

.100		DESIGN REQUIREMENTS	S	U	N/A	N/C
	.102	Check temperature rating (particularly if this is a CO2 line).	X			
	.104	All components are consistent with pressure rating. (consider MOP changes along PL)	Х			
	.106	Pipeline design formula: $P = (2St/D) \times F \times E \times T$				
		F = .72 most cases				
		F = other, Special Permit (typically 0.8)	Х			
		F = 0.6 offshore platform, risers, inland navigable waters				
	100	F = 0.54 cold expanded to meet minimum SMYS				
	.108	External design pressure.	X			
	.110(a)	Design pipeline system to anticipated external loads, e.g., earthquakes, vibration, thermal expansion, and contraction. Follow section 419 of ASME/ANSI B31.4 for expansion and flexibility.	Х			
	.110(b)	Pipe/components supported in a manner to minimize localized stresses. Compute and compensate for stresses to the pipe wall caused by attachments to the pipe.				
	.111	CO2 lines must be designed to mitigate fracture propagation			Х	
	.112(b)	Pipe manufactured in accordance to API or ASTM.	Х			
	.112(c)	Mark each length of pipe $\geq 4\frac{1}{2}$ inches OD to indicate SMYS or grade, pipe size, and specification.	Х			
	.114	Used pipe installed in a pipeline system must comply with §195.112(a) and (b) and the following:				
		 Known API or ASTM specification, seam joint factor determined IAW .106(e), unknown yield or wall thickness IAW .106(b) or (c) as appropriate. 			X	
		 Free of buckles, cracks, grooves, gouges, dents, corroded areas, or other surface defects that exceed the maximum depth. 			X	
		 Depth of the corroded areas - is the remaining wall thickness equal to or greater than the minimum required by the tolerance in specifications, or MOP reduced. 			Х	
	.116	Valves installed in the pipeline system must comply with the following:				
		(a) ANSI/API Spec 6D, 23 rd edition April 2008, and errata 3 (2009)	Х			
		(b) Compatible with the pipe or fittings to which the valve is attached.	Х			
		(c) Compatible with carbon dioxide or each hazardous liquid the pipeline may carry.	Х			

N/C – Not Checked

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

N/C - Not Checked

.100		DESIGN REQUIREMENTS	S	U	N/A	N/C
		(d) Both hydrostatically shell and seat tested without leakage.(Sect. 11 API 6D)	Х			
		(e) Equipped with a means for clearly indicating valve position (open, closed, etc).	Х			
		(f) Marked on the body or nameplate with the following:				
		(1) Manufacturer's name or trademark.	Х			
		(2) Class designation or maximum working pressure.	Х			
		(3) Body material.	Х			
		(4) Nominal size.	Х			
	.118(a)	Butt-welding type fittings meet marking, end preparation, and bursting requirements of ANSI B16.9 , (December 2007 edition), or MSS SP-75-2004.	Х			
	.118(b)	Fittings must be free of any buckles, dents, cracks, gouges, or other defects that might reduce strength.	X			
	.118(c)	Fittings must suitable for the intended service and at least as strong as the pipe and other fittings in the pipeline system to which it is added.	X			
	.120	New and replaced line pipe, valve, fitting, or other line component designed and constructed to accommodate the passage of instrumented internal inspection devices.	X			

Comments:

.111- Pipeline is not a CO2 line.

.112(b) - Pipe was manufactured to API 5L 44th edition (PSL 2). A portion of the Gulf Coast Pipeline was manufactured at the Welspun facility in Little Rock, AR., and was inspected by PHMSA/Southwest.

.114 – There will be no used pipe installed on the Gulf Coast Pipeline.

Design of fittings and valves were verified during the field inspections. PHMSA examined the fitting and valves in the field at the pipe yard and after installation of the valves.

.200		CONSTRUCTION REQUIREMENTS	S	U	N/A	N/C
		SPECIFICATIONS				
	.202	Comprehensive written construction specifications.		Х		
	.204	Qualified inspector performing inspections.	Х			
	.206	Materials visually inspected at site of installation for damage or service impairment	Х			
	.207	Pipe transported in accordance with API RP 5L1 (6 th edition, July 2002), or 5LW (2 nd edition effective March 1, 1997), as applicable				X
	.208	Supports and braces not welded to the pipe operating above 100 p.s.i.	Х			
	.210(a)	Pipeline ROW selected to avoid areas containing private dwellings, industrial buildings, and places of public assembly.	X			
	.210(b)	Pipeline located within 50 feet of any private dwelling, industrial building, or place of public assembly provided with at least an additional 12 inches of cover .	X			
	.212(b)	Field bends cannot be wrinkle bends and made in compliance with:				
		(1) Not impair serviceability.	Х			
		(2) Smooth, free from buckles, cracks, or mechanical damage.	Х			
		(3) Longitudinal weld near neutral axis unless - an internal bending mandrel is used; or pipe is ≤ 12 ³ / ₄ inches or D/t ratio is less than 70%.	Х			
		INSTALLATION OF PIPE				
	.246(a)	Pipe installed to minimize stresses and protect the pipe coating from damage.		Х		
	.248(a)	Installed with appropriate cover and below cultivation (refer to table below)	Х			

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

N/C – Not Checked

.200	CONSTRUCTION REQUIREMENTS					U	N/A	N/C
			Cov	ver (inches)				
		Location	For Normal Excavation	For Rock Excavation ¹				
	Industrial, com	mercial, and residential areas	36	30				
	Crossings of in 100 ft from hig	land bodies of water with a width of at least h water mark to high water mark	48	18				
	Drainage ditche	es at public roads and railroads	36	36				
	Deepwater port	safety zone	48	24				
	Gulf of Mexico measured from	and its inlets in water less than 15 ft deep as the mean low tide.	36	18				
	Other offshore measured from	areas under water less than 12 ft deep as the mean low tide.	36	18				
	Any other area		30	18				
	Additional cove	er required by 195.210.	As Above + 12	As Above + 12				
	¹ Rock ex	scavation is defined as any excavation that requ	ires blasting or remova	al by equivalent means.				
	.248(b)	If minimum cover prescribed above can otherwise additional protection being pr	not be attained beca ovided as required	use it is impracticable to do	Х			
	.250	12 inches of clearance between the pipe	eline and any other u	nderground structure.	Х			
	.252	Backfilling performed in a manner that damage to the coating	provides firm suppo	rt for the pipe and does no	Х			
	.256	Pipe at each railroad or highway crossin dynamic forces exerted by anticipated th	ng installed so as to a raffic loads.	adequately withstand the	Х			
	•	VALVES						
	.258(a)	Install valve in a location, accessible to or tampering.	authorized employe	es and protected from damage	Х			
	.258(b)	Each submerged valve located offshore located by conventional survey techniqu the valve is required.	or in inland navigab les, to facilitate quic	le waters must be marked, or k location when operation of			X	
	.260	Valves installed at each of the following	g locations:					
		(a) On the suction end and discharge en isolation of the pump station equip	nd of a pump station ment in the event of	n in a manner that permits an emergency.	Х			
		(b) On each line entering or leaving a bisolation of the tank area from othe	oreakout storage tanl r facilities.	k area in a manner that permits	Х			
		(c) On each mainline at locations along pollution from accidental hazardou open country, for offshore areas, or	g the pipeline systen s liquid discharge, a for populated areas	n that minimizes damage or s appropriate for the terrain in	х			
		(d) On each lateral takeoff from a trunl lateral without interrupting the flow	k line in a manner th v in the trunk line.	at permits shutting off the	X			
		(e) On each side of a water crossing th to high-water mark unless a waiver not are justified.	at is more than 100 to has been granted for	feet wide from high-water mark or a particular case where valves	X			
		(f) On each side of a reservoir holding	water for human co	nsumption.	Х			

Comments:

.202- Warning letter 4-2013-5017W was sent to Transcanada on September 10, 2013 for not following their Construction Specifications to protect the coating from damage due to welding spatter.

.204 – The qualification records were checked for Chief Welding Inspector Ron Green.

.207 - TransCanada procedures for transporting pipe by rail is outlined in Condition 6 of the 57 Conditions, based on the Association of American Railroads (AAR) standard not API RP 5L1.

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

N/C - Not Checked

Comments:

.246(a) – Warning letter 4-2013-5017W was sent to Transcanada on September 10, 2013 for not following Construction Specifications when installing foam pillows to minimize external stresses on the pipe.

.258(b) - There are no offshore or submerged valves installed in the entire pipeline system.

.200		WELDING	S	U	N/A	N/C
	.214(a)	Welding must be performed by qualified welders using qualified welding procedures.		Х		
		Welding procedures are qualified in accordance with Sec. 5 of API 1104 or Section IX of ASME Boiler & Pressure Code		Х		
		Welding procedures must be qualified by destructive testing.		Х		
	.214(b)	Each welding procedure must be recorded in detail, including results of qualifying tests.		Х		
	.222(a)	Welders must be qualified in accordance with Section 6 of API Standard 1104 (20 th edition 2007, including errata 2008) or Section IX of the ASME Boiler and Pressure Vessel Code (2007 edition), except that a welder qualified under an earlier edition than listed in '195.3 may weld, but may not requalify under that earlier edition.		X		
	.222(b)	Welders may not weld with a particular welding process unless, within the preceding 6 calendar months, the welder has $-(1)$ Engaged in welding with that process; and (2) Had one weld tested and found acceptable under Section 9 of API 1104.		X		
	.224	Welding operations protected from weather conditions.	Х			
	.226(a)	Arc burns require repair.	Х			
	.226(b)	If a notch is not repairable by grinding, a cylinder of the pipe containing the entire notch must be removed. Do arc burn repair procedures require verification of the removal of the metallurgical notch by nondestructive testing? (Ammonium Persulfate).	X			
	.226(c)	Ground not welded to pipe.	Х			
	.228(a)	Welding must be inspected to insure compliance with the requirements of this subpart (line-up, pipe not in a bind, API 1104 requirements, welding procedures followed, etc). Visual inspections must be supplemented by nondestructive testing.	Х			
	.228(b)	Except for cracks, acceptability of welds per Section 9 or Appendix A, API 1104.	Х			
	.230(a)	Remove or repair cracks $\leq 8\%$, remove cracks longer than 8%.	Х			
	.230(b)	Welds repaired, remove defect down to clean metal, preheat pipe, and assure acceptability.	Х			
	.230(c)	Repairs in a previously repaired area must be in accordance with qualified written welding procedures and mechanical properties of the repaired weld equal to those specified for the original weld.	X			

Comments:

.214(a) and (b) -Warning Letter 4-2013-5021W was sent to Transcanada on September 26, 2013, for failing to perform welding on Spread 3 in accordance with a procedure qualified according to Section 5 of API 1104. Procedure KXL-SMAW-ML had revisions to essential variables which was not requalified.

.222(a) and (b) – Warning Letter 4-2013-5021W was sent to Transcanada on September 26, 2013, for failing to properly qualify welders on Spread 3 in accordance with Section 6 of API 1104. Procedure KXL-SMAW-ML had revisions to essential variables which the welders were not qualified to perform.

Welding qualifications, welder qualifications, and welding activities were reviewed by PHMSA either at the office or during the field inspections. Many locations were inspected during the construction of the pipeline in which welding was being performed.

.200		NONDESTRUCTIVE TESTING OF WELDS	S	U	N/A	N/C
	.228/.234	Detailed written procedure established and qualified for nondestructive testing.	Х			
	.234(b)	Nondestructive testing of welds must be performed:				
		(1) In accordance with written procedures for NDT .	Х			

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report.

N/C - Not Checked

.200		NONDESTRUCTIVE TESTING OF WELDS	S	U	N/A	N/C
		(2) Radiographer trained and qualified. (Level II or better).	Х			
		(3) By a process that will indicate any defects that may affect the integrity of the weld	Х			
	.234(c)	Procedures established for proper interpretation.	X			
	.234(d)	Nondestructively test 10% of each welder's welds per day.	Х			
	.234(e)	Test 100% or 90% , if impractical.				
		(1) Stream, river, lake, reservoir, or other body of water.	Х			
		(2) Within railroad or public road ROWs.	Х			
		(3) Overhead road crossings and within tunnels.	Х			
		(4) Within the limits of any incorporated subdivision.	Х			
		(5) Within populated areas such as residential subdivisions.	Х			
	.234(f)	100% of all girth welds nondestructively tested on used pipe.			Х	
	.234(g)	Test 100% of girth welds at tie-ins.	Х			

Comments:

.234(f) There is no used pipe being installed.

All welds were NDT. PHMSA inspected the NDT of many welds during the field inspections. Records were also reviewed during field inspections, office visits, and in the office.

		CORROSION PROTECTION REQUIREMENTS	S	U	N/A	N/C
	.557	Buried or submerged pipelines (constructed, relocated, replaced, or changed) must be externally coated prior to placing in service. See code for exceptions.	Х			
	.561(a)	All external pipe coating inspected just prior to lowering the pipe into the ditch		Х		
	.561(b)	Repair any coating damage discovered.	Х			
	.563(a)	Adequate cathodic protection of the system.	Х			
		Cathodic protection system installed 1 year. (refer. ADB note below)	Х			
	.567	Sufficient number of test leads properly installed.	Х			

Comments:

Transcanada reported to PHMSA that there were some pipe sections that may have had coating damage due to welding spatter when the pipe was lowered into the ditch. Transcanada became aware of the problem by reviewing Transcanada inspector reports. Transcanada excavated the approximately 23 identified pipe sections which may have had the damage and were examined. Transcanada examined the pipe sections and made appropriate repairs to the coating in accordance to their specifications. PHMSA witnessed some of the excavations and repairs. PHMSA issued Warning Letter-4-2013-5017W for not following their specifications.

.266	CONSTRUCTION RECORDS	S	U	N/A	N/C
	Complete records showing the following:				
	(a) Number of girth welds and number of nondestructively tested welds, including number and disposition of each rejected weld.	Х			
	(b) The amount, location, and cover of each size of pipe installed	Х			
	(c) The location of each crossing of another pipeline	Х			
	(d) The location of each buried utility crossing	Х			
	(e) The location of each overhead crossing	Х			
	(f) The location of each valve and corrosion test station	Х			

Comments:

PHMSA reviewed Transcanada's welding records and witnessed the NDT of many girth welds. Transcanada submitted documents and maps which displayed any pipe crossings, utilities and the size of pipe installed. Test stations are installed in accordance with Specification TES-CP-CS and standard drawings.

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable If an item is marked U, N/A, or N/C, an explanation must be included in this report. N/A – Not Applicable

N/C - Not Checked

.300		PRESSURE TESTING	S	U	N/A	N/C
	.302(a)	Hydrostatic testing required:		-		
		1. The entire buried portion tested without leakage for 8 hours	Х			
		2. The above ground portion tested for at least 4 hours (if visually inspected)	Х			
	.304	Test pressure at least 4 continuous hours at a pressure equal to 125 percent, or more, of the MOP. If not visually inspected, at least an additional 4 hours at 110 percent of MOP.	, X			
	.305	Hydrostatically test all pipe and attached fittings, including components, (unless - if a component is the only item being replaced or added - manufacturer certifies hydrostaticall tested at the factory)	y X			
	.306	Appropriate test medium	Х			
	.308	Pipe associated with tie-ins either pretested or hydrostatically tested in place	X			
	.310(a)	Hydrostatic test records retained for the life of the facility tested	Х			
	.310(b)	Do the hydrostatic test records include the following:				
		(1) Pressure recording charts	X			
		(2) Test instrument calibration data	X			
		(3) Operator's name, name of the person responsible for making the test, and the nam of the test company used, if any	e X			
		(4) Date and time of the test	Х			
		(5) Minimum test pressure	X			
		(6) Test medium	X			
		(7) A description of the facility tested and the test apparatus	X			
		(8) An explanation of any pressure discontinuities, including test failures, that appear on the pressure recording charts	X			
		(9) Where elevation differences in the test section exceed 100 feet , a profile of the pipeline showing the elevation and test sites over the entire length of the test section	on X			
		(10) Temperature of the test medium or pipe during the test period	Х			

Comments:

Pressure testing was conducted in accordance with Specification TES-PROJ-LPCS-US. PHMSA inspected the hydrostatic testing during the field inspections and reviewed records at the Transcanada office.

.501509	OPERATOR QUALIFICATION (OQ) FIELD VERIFICATION	S	U	N/A	N/C
	Operator Qualification - Use PHMSA Form 15 OQ Field Inspection Protocol Form if applicable.	Х			

Appendix A Construction Summary Report.

Contents

CONSTRUCTION SUMMARY	
CONSTRUCTION OVERVIEW	4
Design Requirements	4
Construction Requirements	6
Written Specifications	6
Installation of Pipe	6
Valves	8
Welding	
Corrosion Protection	12
Pressure Testing	13
Commissioning	
Issues identified during Construction	15
Welding	15
Dents	

CONSTRUCTION SUMMARY

TransCanada Keystone Pipeline LP, notified PHMSA in a letter dated September 30, 2011 of the construction of the Keystone Gulf Coast Pipeline starting in Q1 of 2012. PHMSA's construction oversight of the Keystone began in 2011 and the pipeline was commissioned in 2014. The Keystone Gulf Coast pipeline consists of 485 miles of 36 inch X70 pipe ranging in wall thickness .465, .515, .572, .618, and .748. The pipeline begins at the TransCanada Keystone Cushing Terminal in Lincoln County, Oklahoma and terminates at the Terminal Facilities in Nederland, Jefferson County Texas. The pipeline transports crude oil from Cushing, OK to Nederland, TX.

Since 2011 until the commissioning of the pipeline on January 22, 2014, PHMSA Southwest Region conducted onsite inspections and inspected documents which include: construction specifications, construction inspection reports, welding qualifications, pipe mill reports, hydrostatic test results, etc., submitted by TransCanada. A total of 165.9 AFO days and 53.35 non-AFO days were spent on the TransCanada construction project.

Daily reports were submitted by each engineer/inspector to document the daily construction activities observed during the inspections. The engineers/inspectors moved around the various construction activities throughout the day depending on the logistics and activities being performed. The primary focus for the engineer/inspector is to observe construction activities and gather and compile all pertinent documentation to assure regulatory compliance with 49 CFR Part 195.

All daily reports, specifications, maps, and any other information gathered by PHMSA are located in the PHMSA "P" drive Construction Folder under "TransCanada Keystone Gulf Coast Pipeline North Final Construction Report".

TransCanada submitted their Commissioning Plan to PHMSA for review prior to commencing commissioning line fill activities. Line fill began in December 2014 and concluded on January 21, 2014. PHMSA engineers/inspectors were onsite to verify that the commissioning plan was being followed and to witness the testing of pump station alarms, valve operation and SCADA operations. On January 22, 2014 TransCanada commissioned the pipeline.

CONSTRUCTION OVERVIEW

The Southwest Region performed a construction inspection of the TransCanada Keystone Gulf Coast Pipeline from 2011 to 2014. The construction inspection consisted of multiple visits to TransCanada's office for review of specifications, procedures, records and to discuss ongoing construction activities. TransCanada provided a link to their external SharePoint to PHMSA to review records and specifications. In addition, the construction inspection consisted of onsite field inspections of ongoing construction activities. Several SW Region Engineers/inspectors visited the pipeline construction from Cushing, OK to Nederland, TX.

Design Requirements

The pipeline used for the construction of the Keystone Gulf Coast project was manufactured by ILVA and Welspun in India and Little Rock, AR. PHMSA engineers/inspectors visited the Welspun pipe mill in Little Rock, AR to verify that the pipe was manufactured in accordance with API 5L and TransCanada's specifications. The inspection included a review of TransCanada's specifications and procedural QA/QC for pipe materials from the vendor (Welspun) at the mill location. Specifications, procedures & records were reviewed for completeness and compliance to pertinent regulatory and/or industry requirements/guidelines. TransCanada's specifications for coating, submerged arc welded pipe and double joined pipe were reviewed. The inspection team met with and directly observed TransCanada personnel and their assigned agents conducting third party monitoring on their behalf (D M Professional Services), who provided QA/QC for pipe materials being produced at the mill for the Keystone Gulf Coast project.

During the field inspections, the pipeline was verified for design specifications by examining the pipe for manufacturer stamping and reviewing manufacturer test reports (MTRs). Each pipe joint was marked with length, grade, pipe size, and specification. See Figures 1 and 2 for examples.



Figure 1: Pipe Specification Markings



Figure 2: Pipe Specification Markings

Pipe used for the construction had different wall thicknesses for different application locations such as: 0.465" for line pipe, 0.515" for HCAs, 0.572" downstream of pump station, 0.618" for road bores, and 0.748" for HDDs. HDD and road bore pipe also had abrasion resistant overcoat (ARO) which was verified during the field inspections as seen in Figure 3. Pipe joints were marked with the appropriate specifications, for example, API 5L



PSL2 36", 0.465", X70.

Figure 3: ARO Pipe with specification markings.

Valves and other pipeline components were also verified in the field. Valves were manufactured in accordance with API 6D and were stamped with manufacturer's name, maximum pressure rating, temperature rating, nominal size and body material. Fittings were



Figures 4, 5, 6: Manufacturer Stamp on Valve, and Flange

examined for damage such as buckles, dents, gouges, cracks or other defects that might reduce the strength. Pipe joints were tracked by a labeling system with a bar code. See Figures 4-6.

Labels were checked in the field for damage or nonreadable labels. See Figure 7. All components inspected were consistent with the pressure rating and in accordance with the established MOP.



Figure 7: Pipe Label

Construction Requirements

Written Specifications

PHMSA SW Region reviewed TransCanada's construction specifications throughout the construction project. Specifications were reviewed in PHMSA's or TransCanada's offices, through the SharePoint site, and during the field inspections. The field inspections focused on verification that the specifications were being applied and followed during the construction of the pipeline. These field verifications help assure PHMSA that the pipeline was being construction according to Part 195 and the operators specifications.

During the onsite construction inspections there were some potential non-compliance issues identified by PHMSA. The first involved TransCanada not following their specification dealing with backfilling and sand padding of the ditch/trench which was in violation of §195.246. This will be further discussed later in the report.

Installation of Pipe

During the field inspections, PHMSA inspected the pipeline ROW for any private dwellings, industrial buildings, and places of assembly. The ROW of the pipeline avoided and was not in close proximity to any of these structures or locations. The inspection of soil cover and depth of pipe was in compliance with the regulations. The pipeline had a cover of at least the minimum cover required at all locations inspected during the field inspections. Figure 8 shows the depth of the pipe. The Figure demonstrates the cover and depth of the pipeline and the remoteness of the pipeline ROW. Figure 9 shows the depth of pipeline is verified with a GPS system.



Figure 8: Typical Right of Way depicting Depth of Cover.



Figure 9: Depth of Cover check with GPS

To avoid many road and railroad crossings, other pipeline, bodies of water and any other encroachments, TransCanada horizontally directional drilled (HDD) the pipeline at these locations. The depth of the HDDs well exceeded the depth of cover required by the regulations. PHMSA witnessed and inspected HDD construction activities for any issues and to assure specifications were followed. The Figures demonstrate the inspection of the HDDs. Figure 10 shows pipe is being supported

by a boom as it is being pulled into the drill.



Figure 10: Boom holding Pipe

Field pipe bends were observed by PHMSA during many field inspections. There were no wrinkle bends identified during these inspections. Pipe bends were performed by a bending machine which utilized an internal bending mandrel to achieve smooth and undistorted bends. PHMSA witnessed pipe bending activities which are shown in Figures 11 and 12. There was no mechanical damage identified during the pipe bending activities.



Figure 11: Bending Machine



Figure 12: Bent Pipe

Valves

Federal regulations require that valves be installed "... at locations along the pipeline system that will minimize damage or pollution ...". PHMSA raised an issue with TransCanada concerning its valve spacing as to whether or not they were being placed to minimize the environmental impact in case of a release. TransCanada submitted additional studies and records which included a Pipeline Assessment and Environmental Consequence Analysis, Keystone Gulf Coast Valve Siting Rationale and Gulf Coast Corridor Schematic. In addition, TransCanada installed remotely operated valves, with back- up generators at all locations mentioned in their study. PHMSA reviewed and met with TransCanada to discuss the locations of the valves which resolved the issue with the valve spacing.

Valve locations and automation equipment were verified during the field inspections by PHMSA.



Figure 13: Typical Valve location



Figure 14: Remote Operation Equipment at Valve site.

Valves were inspected at the pipe yard on several occasions to verify the rating and condition of the valves. Figure 15 shows valves inspected at the pipe yard. Valves were stored away from the pipe to protect from any damage.



Figure 15: Valve Storage at Pipe Yard

Topography maps were submitted to PHMSA showing all water crossings and location of valves. Valves were located at every water crossing and in locations along the pipeline to minimize pollution and damage in populated areas.

There were also valves located at each discharge and suction side of the pump stations. Figure 16 depicts an example of a pump station valve installation.



Figure 16: Valve at Pump Station

All valves are motorized and remotely operational through SCADA. All valves had concrete foundation poured to handle any stresses the weight may put on the pipeline. Figure 17 is an example of concrete supports. Figure 18 demonstrates the protection from unauthorized personnel and vandalism. In addition, the photos show the satellite, electric power and generators for backup needed to operate the valves.



Figure 17: Concrete Pads for Valves.



Figure 18: Typical Fencing around Valve site

Welding

Throughout the construction project, PHMSA reviewed welding procedures, specifications and conducted field observations of welding activities. In addition, PHMSA witnessed the qualification of procedures and welders to assure welding was being performed to a qualified procedure and by qualified welders.

Welding was performed in accordance with API 1104, the federal regulations and TransCanada's specifications. TransCanada utilized automatic welding on spreads 1 and 2 and manual welding on Spread 3. Both automatic and manual welding was being performed while PHMSA was on site.



Figure20: Automatic Welding Shack



Figure 19: Welder Qualification Test



Figure 21: Automatic Welding Set up

Welding inspections also included the inspection of nondestructive testing of all welds. In the field PHMSA observed NDT of the welds and assured that NDT specifications were followed. TransCanada utilized both AUT and X-ray

methods for testing welds.

During the PHMSA field inspections and welding qualifications review, there were two issues and concern identified by PHMSA. One concern raised was the high welding repair/rejection rate. From the start of welding, TransCanada experienced a high weld rejection rate on Spread 3. A second issue identified by PHMSA was that TransCanada failed to properly qualify welders on Spread 3 of the



Figure 22: Manual Welding Set up

Keystone Gulf Coast Pipeline project. TransCanada performed welder qualifications using a welding procedure that had not been properly qualified and then allowed these welders to weld on a Part 195 regulated pipeline. These issues will be furthered discussed alter in the report.

Corrosion Protection

During the field inspections by PHMSA, the installation of corrosion control measures was verified. TransCanada provided corrosion control specifications which were reviewed by PHMSA. PHMSA witnessed the installation of many joints of pipe to assure that the coating was in good condition and was inspected (jeeped) for coating damage before burying the pipe. Any damage identified by this inspection technique was repaired. Each weld joint was coated and is seen in Figure 23. PHMSA also verified that there were a sufficient number of test leads installed throughout the pipeline.



Figure 23: Coating of field Joint

TransCanada conducted a Direct Current Voltage Gradient (DCVG) survey of the entire Keystone Gulf Coast Pipeline to check for any coating damage. After the survey, TransCanada submitted the findings of any coating damage found along with repairs made on anomalies. There were a total of 127 anomalies on Spread 1, 83 anomalies on Spread 2, and 43 anomalies on Spread 3 found by the survey. None of the anomalies found met the repair criteria of 35% IR, the highest was 32%. TransCanada performed verification digs on the highest IR readings on all three spreads to assure accuracy of the DCVG Survey. They made 8 digs in Spread 1, 8 digs in Spread 2, and 4 digs in Spread 3 and made repairs accordingly. The reports were reviewed by PHMSA to assure compliance with their procedures and the regulations. PHMSA conducted field inspections to verify dig sites identified by the DCVG survey. Figures 25 and 26 depict two locations identified by the DCVG survey during a PHMSA field inspection.



Figure 24: Typical Test Station



Figure 25 and 26: DCVG dig site (recoated)

Pressure Testing

Pressure testing of the TransCanada was performed in accordance with their Specification TES-PROJ-LPCS-US and with CFR 195. The specification and records of all hydrostatic pressure tests conducted by TransCanada were reviewed by PHMSA. In addition, PHMSA conducted field inspections of the hydrostatic testing on various locations of the pipeline.



Figure 27: Hydrotest in Progress



Figure 28: Hydrotest in Progress

The entire pipeline was hydrotested to at least 8 hours for all buried pipelines. In addition, TransCanada conducted a one hour pressure test on all HDD piping before pulling the pipe section. The one hour test is part of TransCanada's procedures to verify the integrity of the HDD pipe before pulling it through the drilled hole. The test medium used for all testing was water. All records reviewed had documented the appropriate pressure of 125% or more of MOP, test medium, instrument calibration, pressure recording charts, temperature, date and time and description of the facility being tested. TransCanada also provided elevation profiles of all test sections with hydraulic pressure profiles. There were no leaks or failures detected in the records review and during the field inspections.



Figure 29: Drying process after hydrotest

Commissioning

TransCanada notified PHMSA in December 2013 of the intent to start line fill and commissioning of the Keystone Gulf Coast Pipeline from Cushing, OK to Nederland, TX. TransCanada submitted their Commissioning Plan for approval from PHMSA to commence commissioning activities. PHMSA reviewed the commissioning plan and had no objections to start the commissioning process.

On December 7, 2013, TransCanada started line fill activities starting from the Cushing facility to their Nederland facility. TransCanada followed their commissioning plan and coordinated with personnel to monitor the line-fill to ensure the pipeline was operating safely and reliably. The plan included the commissioning of 485 miles of pipe, six pump

stations and the Nederland Delivery Station. Product was tracked utilizing three batch pigs to assure the location of the product. Each pig was tracked by Corrpro personnel and predetermined above ground markers (AGM). During the commissioning phase, each mainline valve was operated to assure no leaks and satisfactory operation of the valve. In addition each pump station was started up in stages. Each stage consisted of testing each leak detection system and alarms per pump before

starting up the next pump(4 pumps per station) at each station. On January 21, 2014



Figure 30: Pigs used during commissioning.

TransCanada notified PHMSA of the completion of the line-fill activities and the intent to start in-service operations. On January 22, 2014 TransCanada commissioned the pipeline and started in-service operations.

PHMSA received daily updates throughout the commissioning phase of all ongoing activities. In addition, PHMSA engineers/inspectors were onsite during the commissioning phase to witness and assure procedures were being followed by TransCanada personnel. PHMSA witnessed the line fill, testing of pump alarms and leak detection, valve testing and pig tracking operations. The Figures demonstrate the observations of the activities witnessed during the commissioning. The Figure 43 shows the pigs used to track the product while filling line. Figure 44 shows how the pigs were tracked from above ground.



Figure 31: Commissioning at Pump Station

Issues identified during Construction

Welding

TransCanada performed welder qualifications using a welding procedure that had not been properly qualified and then allowed these welders to weld on a Part 195 regulated pipeline.

During the first weeks of construction of spread 3 significant welding issues were noted. Approximately 26.8% of the welds required repairs in one week, 32.0% the second week, 72.2% the third week, and 45.0% the fourth week. On September 25, 2012, TransCanada stopped the Spread 3 welding after 205 of the 425 welds, or 48.2% required repairs. Through the welding procedure review, PHMSA found that TransCanada failed to perform welding on construction Spread 3 of the Gulf Coast Pipeline project in accordance with a procedure qualified according to Section 5 of API 1104.

A comparison of the procedure being used to weld the pipe on Spread 3 (KXL-SMAW-ML, revised February 10, 2011) with the PQR revealed inconsistencies between at least two essential variables as defined by API 1104, the Joint Design and the Speed of Travel. The joint design on the document KXL-SMAW-ML being used to weld the pipe on construction Spread 3 specified a Root Opening of $1/16" \pm 3/32"$ between pipe joints at the girth weld and the welding Speed of Travel for the Cap Pass to be 8.6 - 16.2 inches per minute. The PQR for the procedure that was actually qualified by destructive testing (PQR# KPS-RMS-SMAW-ML-PQR Rev 2) showed the root opening to be 1/16" to 3/32" and the Speed of Travel for the Cap Pass to be 6.6 - 16.2 inches per minute. The difference between the PQR and the welding procedure constituted a change in essential variables.

As a result, the welding procedure being used by TransCanada on Spread 3 of the Keystone Gulf Coast Pipeline project (KXL-SMAW-ML) had changes to essential variables that caused it to be different than the Procedure Qualifying Record. Because the procedure used to weld Spread 3 pipe was not re-qualified, TransCanada was using an unqualified procedure to weld Part 195 regulated pipeline.

A second issue identified by PHMSA was that TransCanada failed to properly qualify welders on Spread 3 of the Keystone Gulf Coast Pipeline project. TransCanada performed welder qualifications using a welding procedure that had not been properly qualified and then allowed these welders to weld on a Part 195 regulated pipeline. Paragraph 6.1 of API 1104, incorporated by reference states "the purpose of the welder qualification test is to determine the ability of welders to make sound butt or fillet welds using previously qualified procedures." Procedure KXL-SMAW-ML, Revised February 10, 2011 had changes to the essential variables of Joint Design and Speed of Travel from the Procedure Qualification Record, KPL-RMS-SMAW-ML-PQR Rev 2 but had not been re-qualified. Consequently, the welder qualification was not performed using a previously qualified procedure as required by Section 6 of API 1104. PHMSA issued Warning Letter 4-201305021W for both issues identified during the construction inspection. TransCanada responded to the Warning Letter stating that after more than twelve months of extensive meetings and discussion, comprehensive supplemental destructive testing and exhaustive records reviews, on November 25, 2013 a meeting held between PHMSA and TransCanada resulted in confirmation that the welder qualifications and manual welding procedures. In addition, The results of a root cause analysis performed by TransCanada to identify the cause of the high weld rejection rate on Spread 3 were documented in a paper titled "Girth Weld Repairs Due to Lack of Fusion in Root Pass," dated November 15, 2012. This analysis identifies the criticality of the essential variables of Joint Design and Speed of Travel by stating, "Weld fit up was increased to 3/32" which allowed the welders to decrease their travel speeds and welding amperages which is a key factor in reducing internal under cut and lack of fusion defects during the welding process. This modification improved the weld quality and reduced the overall weld defects. PHMSA witnessed the re-testing of the welding procedure to verify the modification of the procedure reduced the internal under cut and lack of fusion defects, at the RMS lab in Edmonton, Alberta, Canada.

Dents

TransCanada did not assure that its Keystone Pipeline was installed in the ditch in a manner that minimizes the possibility of damage to the pipe. The deformation tool identified dents on the pipe that appear to be caused by secondary stresses on the pipe. The ILI tool identified a total of 421 anomalies which required investigation per the specifications. There were a total of 236 dents, 56 pipe ovality and 129 anomalies with both dent and ovality. TransCanada verified the locations by excavating the anomalies and made repairs in accordance with their specifications. After excavating and examining the anomalies, there were a total of 350 anomalies within the specifications, 37 anomalies which required being cut-out and 34 anomalies with no indications of a dent or ovality. During the field inspections, PHMSA witnessed and examined anomaly investigations being conducted by TransCanada due to the results of the deformation tool run. In this report you can see examples of the types of dents identified with the inspection tools. Each dent was examined



Figure 32, 33, 34 Examples of dents found with inspection tool.

and measured and nondestructively tested with ultrasound testing equipment to check for cracks. All dents were either cutout or were below the repair criteria. Several anomaly reports stated that foam pillows and rocky terrain were present at the dig sites which may

attribute to the dents on the pipe. During the field inspections the PHMSA inspector verified the locations of several dents which were located in the same vicinity as the foam pillow supports.

TransCanada's TES-PROJ-LPCS-US Onshore Liquid Pipeline Construction Specification, Section 22.4 states "when foam pillows are installed, approved fill will be supplied to provide a uniform support along the underside of the pipe." Assuring a uniform fill underneath the pipe at all foam pillow locations will minimize external stresses on the pipe. In addition, Section 22.5 states that "rock, stone laden soil, or frozen material shall not be backfilled into the trench until the pipe has been surrounded by stone free soil."

In reviewing the anomaly reports and PHMSA inspections it demonstrated that TransCanada was not following their Construction Specifications, Section 22.4 and 22.5. PHMSA SW Region issued a Warning Letter, CPF 4-2013-5017W warning TransCanada to follow their procedures/specifications and assure that backfill is free of large rocks and have sufficient support at the foam pillows to minimize the external stresses on the pipe to be in compliance with 195.246.

Coating Damage

Another issue identified involved TransCanada not following their specifications during welding of the pipeline.

TransCanada did not follow its written specification, specifically, protecting existing coating from damage due to welding. In an email dated June 7, 2013, TransCanada notified PHMSA of a non-conformance issue involving coating damage on Spread 3 which TransCanada was in the process of investigating. The problem only occurred in Spread 3 due to the manual welding process with stick rods being utilized. Manual welding was used mainly due to the terrain and the number of water crossings. Spread 1 and 2 utilized the semiautomatic welding process. There were several locations in which the contractor did not follow TransCanada's coating specifications. Specifically, weld blankets were not being utilized to protect the existing coating on the pipe to prevent weld splatter from damaging the coating.

TransCanada's specification TES-WELD-PL- US Welding of Pipelines and Tie-ins, Section 8.11 states that "existing coatings on piping shall be protected to minimize damage that may result from the welding operations" which was not being followed by the contractor. After investigating 23 suspected locations, TransCanada confirmed the coating damage and repaired the coating per the specifications.

During the field inspections, PHMSA observed several girth welds had coating damage due to weld splatter. Figure 35 shows the coating repair on the girth welds due to damage of the weld



Figure 35: Repair of coating due to weld splatter.

splatter. The coating repair was made after the pipeline was exposed and examined. The pipe was coated and backfilled per the specifications. There were a total of 130 identified locations excavated in which TransCanada examined for damage and made repairs were necessary. All discovered damage was inspected and repaired to original specification criteria.

PHMSA issued a Warning Letter, CPF #4-2013-5017W, warning TransCanada to follow their specifications/procedures and assure that specification 8.11 is followed to be in compliance with 195.202.

TransCanada responded to the Warning Letter and assured that they were taking steps to enhance its design, specifications and inspection practices, by conducting a thorough review of their inspection practices, design, and construction specifications, and would implement changes to try to reduce the number of inspection digs that are required after the pipeline has been backfilled going forward, which included, but not limited to restricting the use of foam pillows, increased use of bedding material in rocky or hard pan conditions, and specifying the minimum size of weld splatter protection devices.

WARNING LETTER

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

September 10, 2013

Mr. Vern Meier Vice President, Field Operations TC Oil Pipeline Operations, Inc. 717 Texas Ave. Houston, TX 77002

CPF 4-2013-5017W

Dear Mr. Meier:

During the months of June and July 2013, a representative of the Pipeline and Hazardous Materials Safety Administration (PHMSA) pursuant to Chapter 601 of 49 United States Code inspected the construction of the Keystone Gulf Coast Project.

As a result of the inspection, it appears that you have committed probable violations of the Pipeline Safety Regulations, Title 49, Code of Federal Regulations. The items inspected and the probable violations are:

1. §195.246 Installation of pipe in a ditch.

(a) All pipe installed in a ditch must be installed in a manner that minimized the introduction of secondary stresses and the possibility of damage to the pipe

Transcanada did not assure that its Keystone Pipeline was installed in the ditch in a manner that minimizes the possibility of damage to the pipe. During the field inspections, PHMSA witnessed and examined anomaly investigations being conducted by Transcanada due to the results of a deformation tool run. The deformation tool identified dents on the pipe that appear to be caused by secondary stresses on the pipe. Several anomaly reports state that foam pillows and rocky terrain were present at the dig sites which may attribute to the dents on the pipe. During the field inspections of several dents which were located in the same vicinity as the foam pillow supports.

Transcanada's TES-PROJ-LPCS-US Onshore Liquid Pipeline Construction Specification, Section 22.4 states "when foam pillows are installed, approved fill will be supplied to provide a uniform support along the underside of the pipe." Assuring a uniform fill underneath the pipe at all foam pillow locations will minimize external stresses on the pipe. In addition, Section 22.5 states that "rock, stone laden soil, or frozen material shall not be backfilled into the trench until the pipe has been surrounded by stone free soil."

In reviewing the submitted anomaly reports and PHMSA inspections it demonstrates that Transcanada is not following their Construction Specifications, Section 22.4 and 22.5. Transcanada needs to assure the backfill is free of large rocks and have sufficient support at the foam pillows to minimize the external stresses on the pipe to be in compliance with 195.246.

2. §195.202 Compliance with specifications or standards.

Each pipeline system must be constructed in accordance with comprehensive written specifications or standards that are consistent with the requirements of this part.

Transcanada did not follow its written specification, specifically, protecting existing coating from damage due to welding. In an email dated June 7, 2013, Transcanada notified PHMSA of a non-conformance issue involving coating damage which Transcanada was in the process of investigating. There were several locations in which the contractor did not follow Transcanada's coating specifications. Specifically, weld blankets were not being utilized to protect the existing coating on the pipe to prevent weld splatter from damaging the coating. Transcanada's specification TES-WELD-PL- US Welding of Pipelines and Tie-ins, Section 8.11 states that "existing coatings on piping shall be protected to minimize damage that may result from the welding operations" which was not being followed by the contractor. After investigating 23 suspected locations, Transcanada confirmed the coating damage and repaired the coating per the specifications.

During the inspection, PHMSA observed several girth welds had coating damage due to weld splatter. There were a total of 98 identified locations excavated in which Transcanada made coating repairs. Transcanada needs to assure that specification 8.11 is followed to be in compliance with 195.202.

Under 49 United States Code, § 60122, you are subject to a civil penalty not to exceed \$200,000 per violation per day the violation persists up to a maximum of \$2,000,000 for a related series of violations. For violations occurring prior to January 4, 2012, the maximum penalty may not exceed \$100,000 per violation per day, with a maximum penalty not to exceed \$1,000,000 for a related series of violations. We have reviewed the circumstances and supporting documents involved in this case, and have decided not to conduct additional enforcement action or penalty assessment proceedings at this time. We advise you to correct the item(s) identified in this letter. Failure to do so will result in Transcanada being subject to additional enforcement action.

No reply to this letter is required. If you choose to reply, in your correspondence please refer to **CPF 4-2013-5017W**. Be advised that all material you submit in response to this enforcement action is subject to being made publicly available. If you believe that any portion of your responsive material qualifies for confidential treatment under 5 U.S.C. 552(b), along with the complete original document you must provide a second copy of the document with the portions you believe qualify for confidential treatment redacted and an explanation of why you believe the redacted information qualifies for confidential treatment under 5 U.S.C. 552(b).

Sincerely,

R. M. Seeley Director, Southwest Region Pipeline and Hazardous Materials Safety Administration

NOTICE: This report is required by 49 CFR Part 195. Failure to report can result in a exceed \$100,000 for each violation for each day that such violation persists except th penalty shall not exceed \$1,000,000 as provided in 49 USC 60122.	a civil penalty not to nat the maximum civil	OMB NO: 2137-0047 EXPIRATION DATE: 01/31	/2014
N	Original Report Date:	06/08/2011	l
U.S Department of Transportation	No.	20110171 - 16	6159
Pipeline and Hazardous Materials Safety Administration		(DOT Use Only	/)
ACCIDENT REPORT - HAZ PIPELINE SYS	ACCIDENT REPORT - HAZARDOUS LIQUID PIPELINE SYSTEMS		
A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0047. Public reporting for this collection of information is estimated to be approximately 10 hours per response (5 hours for a small release), including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Office of Player (PHDSA Office of Player) 1200 New, Jersey Avenue, SE. Washington, D.C. 20590.			
INSTRUCTIONS			
Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at http://www.phmsa.dot.gov/pipeline .			vide specific
Report Type: (select all that apply)	Original:	Supplemental:	Final:
Last Revision Date:	11/02/2011	163	103
1. Operator's OPS-issued Operator Identification Number (OPID):	32334		
2. Name of Operator	TC OIL PIPELINE	OPERATIONS INC	
3. Address of Operator:			
3a. Street Address			
30. Olly 30. State	Texas		
3d. Zip Code	77002		
4. Local time (24-hr clock) and date of the Accident:	05/07/2011 06:20		
5. Location of Accident:			
Latitude:	45.95307		
Longitude:	-97.9057		
6. National Response Center Report Number (if applicable):	975573		
7. Local time (24-hr clock) and date of initial telephonic report to the National Response Center (if applicable):	05/07/2011 09:55		
8. Commodity released: (select only one, based on predominant volume released)	Crude Oil		
- Specity Commodity Subtype: If "Other" Subtype Describe:			
 If Biofuel/Alternative Fuel and Commodity Subtype is Ethanol Blend, then % Ethanol Blend: 			
%:			
 If Biofuel/Alternative Fuel and Commodity Subtype is Biodiesel, then Biodiesel Blend (e.g. B2, B20, B100): 			
9. Estimated volume of commodity released unintentionally (Barrels):	400.00		
10. Estimated volume of intentional and/or controlled release/blowdown (Barrels):			
11. Estimated volume of commodity recovered (Barrels):	400.00		
12. Were there fatalities?	No		
- If Yes, specify the number in each category:			
12a. Operator employees			
12c. Non-Operator emergency responders			
12d. Workers working on the right-of-way, but NOT associated with this Operator			
12e. General public			
12f. Total fatalities (sum of above)			
13. Were there injuries requiring inpatient hospitalization?	No		
- If Yes, specify the number in each category:	1		
13a. Uperator employees			
13c. Non-Operator emproprior responders			

Tou. Workers working on the right-or-way, but NOT	
associated with this Operator	
13e. General public	
14. Was the pipelipe/facility shut down due to the Accident?	
- If No. Explain:	
- If Yes, complete Questions 14a and 14b: (use local time, 24-hr clock)	
14a. Local time and date of shutdown:	
14b. Local time pipeline/facility restarted:	
 Still shut down? (* Supplemental Report Required) 	
15. Did the commodity ignite?	No
16. Did the commodity explode?	No
17. Number of general public evacuated:	0
18. Local time Operator identified Accident:	05/07/2011 00:00
18b. Local time Operator resources arrived on site:	05/07/2011 09:00
	00/01/2011 00:00
PART B - ADDITIONAL LOCATION INFORMATION	
1 Was the origin of Accident onshore?	Yes
If Yes, Complete Ques	tions (2-12)
If No, Complete Questi	ons (13-15)
- If Onshore:	
2. State:	North Dakota
3. Zip Code:	58017
4. City	Brampton
5. County or Parish	Sargent
6. Operator-designated location:	Milepost/Valve Station
Specify:	MP ND 216.7
Pipeline/Facility hame. Sogmont name/ID:	Clacial Lakes
9 Was Accident on Federal land other than the Outer Continental Shelf	Glacial Lakes
(OCS)?	No
10. Location of Accident:	Originated on Operator-controlled property, but then flowed
11. Area of Accident (as found):	Aboveground
Specify:	Typical aboveground facility piping or appurtenance
- If Other, Describe:	
Depth-of-Cover (in):	
	N1-
12. Did Accident occur in a crossing?	NO
12. Did Accident occur in a crossing? - If Yes, specify below:	NO
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing –	NO
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing –	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled	N0
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing –	NO
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled	NO
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing –	NO
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - If Water crossing – - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - Nearest County/Parish: - Ver Point of Net (2020) - 2 = 10	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - On the Outer Continental Shelf (OCS) - Specify:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Nearest County/Parish: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Area: - Block #:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Approx. water depth (ft) at the point of the Accident: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - Nearest County/Parish: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Block #:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Approx. water depth (ft) at the point of the Accident: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Block #: 15. Area of Accident:	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - Nearest County/Parish: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Block #: 15. Area of Accident: PART C - ADDITIONAL FACILITY INFORMATION	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - Nearest County/Parish: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Block #: 15. Area of Accident: 1. Is the pipeline or facility: - In State pipeline	
12. Did Accident occur in a crossing? - If Yes, specify below: - If Bridge crossing – Cased/ Uncased: - If Railroad crossing – Cased/ Uncased/ Bored/drilled - If Road crossing – Cased/ Uncased/ Bored/drilled - If Water crossing – Cased/ Uncased - If Water crossing – Cased/ Uncased - Name of body of water, if commonly known: - Approx. water depth (ft) at the point of the Accident: - Select: - If Offshore: 13. Approximate water depth (ft) at the point of the Accident: 14. Origin of Accident: - In State waters - Specify: - State: - Area: - Block/Tract #: - Nearest County/Parish: - On the Outer Continental Shelf (OCS) - Specify: - Area: - Block #: 15. Area of Accident: PART C - ADDITIONAL FACILITY INFORMATION 1. Is the pipeline or facility: 2. Part of system involved in Accident:	NO Interstate Onshore Pump/Meter Station Equipment and Piping

3. Item involved in Accident:	Relief Line
- If Pipe, specify:	
3a. Nominal diameter of pipe (in):	
3b. Wall thickness (in):	
3c. SMYS (Specified Minimum Yield Strength) of pipe (psi):	
3d. Pipe specification:	
3e. Pipe Seam , specify:	
- If Other, Describe:	
3f. Pipe manufacturer:	
3g. Year of manufacture:	
3h. Pipeline coating type at point of Accident, specify:	
- If Other, Describe:	
 If Weld, including heat-affected zone, specify: 	
- If Other, Describe:	
- If Valve, specify:	
- If Mainline, specify:	
- If Other, Describe:	
3i. Manufactured by:	
3j. Year of manufacture:	
- If Tank/Vessel, specify:	
- If Other - Describe:	
- II UTNEF, GESCRIDE:	2000
4. Year item involved in Accident was installed:	ZUUY
5. Ivialenal Involved In Accident:	
- in Material other than Carbon Steel, specify:	
6. Type of Accident Involved.	LEAN
- If Mechanical Puncture – Specify Approx. size:	
In. (axial) by	
In. (circumferential)	Connection Failure
- IT Leak - Select Type:	Connection Failure
- If Other, Describe:	
- Il Ruplure - Select Orientation.	
- II Other, Describe.	
in (length circumferentially or axially)	
in: (longer broathered any of axially)	
- If Other - Describe:	
- If Other – Describe:	
- If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION	
- If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION	
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact:	No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply: Fish/aquatic	No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply: - Fish/aquatic - Birds	No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply: - Fish/aquatic - Birds - Terrestrial	No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION Wildlife impact: 1a. If Yes, specify all that apply:	No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION I. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes Yes Yes Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION I. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Yes Yes Yes Yes Yes Yes Yes Solution Yes Yes Solution Yes Yes Yes Solution Yes Yes Solution Solution
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes Station
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes No No
If Other – Describe: PART D - ADDITIONAL CONSEQUENCE INFORMATION 1. Wildlife impact: 1a. If Yes, specify all that apply:	No Yes No Yes No No No

 Commercially Navigable Waterway: 	
Was this HCA identified in the "could affect"	
determination for this Accident site in the Operator's	
Integrity Management Program?	
- High Population Area:	
Was this HCA identified in the "could affect"	
determination for this Accident site in the Operator's	
Integrity Management Program?	
- Other Populated Area	
Was this HCA identified in the "could affect" determination	
for this Accident site in the Operator's Integrity	
Management Program?	
- Unusually Sensitive Area (USA) - Diffiking Water	
for this Accident site in the Operator's Integrity	
Management Program?	
- Unusually Sensitive Area (USA) - Ecological	
Was this HCA identified in the "could affect" determination	
for this Accident site in the Operator's Integrity	
Management Program?	
8. Estimated Property Damage:	
8a. Estimated cost of public and non-Operator private property	¢ 4.000
damage	\$ 1,000
8b. Estimated cost of commodity lost	\$ 40,000
8c. Estimated cost of Operator's property damage & repairs	\$ 25,000
8d. Estimated cost of Operator's emergency response	\$ 250,000
8e. Estimated cost of Operator's environmental remediation	\$ 750,000
8f. Estimated other costs	\$ 250,000
Describe:	Repair costs to the faclity and other facilities
8g. Total estimated property damage (sum of above)	\$ 1,316,000
PART E - ADDITIONAL OPERATING INFORMATION	
4. Estimated pressure at the point and time of the Appident (poin):	4 007 00
Estimated pressure at the point and time of the Accident (psig):	1,097.00
2. Maximum Operating Pressure (MOP) at the point and time of the	1,440.00
Accident (neig):	
Accident (psig):	
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig):	Pressure did not exceed MOP
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations 	Pressure did not exceed MOP
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility 	Pressure did not exceed MOP
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure 	Pressure did not exceed MOP
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the 	Pressure did not exceed MOP No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? 	Pressure did not exceed MOP No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction?	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State?	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Valve Sites" OR "Offshore	Pressure did not exceed MOP No
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 22	Pressure did not exceed MOP No No
 Accident (psig): Describe the pressure on the system or facility relating to the Accident (psig): 	Pressure did not exceed MOP No No
 Accident (psig): Bescribe the pressure on the system or facility relating to the Accident (psig): Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? S. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of unstream valve used to initially isolate relaces.	Pressure did not exceed MOP No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source. 	Pressure did not exceed MOP No No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (Complete 5a. – 5e. below) 5a. Type of upstream valve used to initially isolate release source: 	Pressure did not exceed MOP No No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 	Pressure did not exceed MOP No No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 	Pressure did not exceed MOP No No No
 Accident (psig): Describe the pressure on the system or facility relating to the Accident (psig): Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: If Yes, Complete 4.a and 4.b below: Did the pressure exceed this established pressure restriction? Was this pressure restriction mandated by PHMSA or the State? Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (Complete 5a. – 5e. below) Type of upstream valve used to initially isolate release source: Sb. Type of downstream valve used to initially isolate release source: Sc. Length of segment isolated between valves (ft): Sd. Is the pipeline configured to accommodate internal 	Pressure did not exceed MOP No No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? 	Pressure did not exceed MOP No No No
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? 	Pressure did not exceed MOP No No No Select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves 	Pressure did not exceed MOP No No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends 	Pressure did not exceed MOP No No Select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) Extra thick pipe wall (applicable only for magnetic 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe bends Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) Extra thick pipe wall (applicable only for magnetic flux leakage internal inspection tools) 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) Other - UK off the pressing in the pipe internal inspection tools? 	Pressure did not exceed MOP No No (select all that apply)
 Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? If No, Which physical features limit tool accommodation? Changes in line pipe diameter Presence of unsuitable mainline valves Tight or mitered pipe bends Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) Extra thick pipe wall (applicable only for magnetic flux leakage internal inspection tools) Other - 	Pressure did not exceed MOP No No Select all that apply) Select all that apply)
Accident (psig): 3. Describe the pressure on the system or facility relating to the Accident (psig): 4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP? - If Yes, Complete 4.a and 4.b below: 4a. Did the pressure exceed this established pressure restriction? 4b. Was this pressure restriction mandated by PHMSA or the State? 5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2? - If Yes - (<i>Complete 5a. – 5e. below</i>) 5a. Type of upstream valve used to initially isolate release source: 5b. Type of downstream valve used to initially isolate release source: 5c. Length of segment isolated between valves (ft): 5d. Is the pipeline configured to accommodate internal inspection tools? - If No, Which physical features limit tool accommodation? - Changes in line pipe diameter - Presence of unsuitable mainline valves - Tight or mitered pipe bends - Other passage restriction, etc.) - Extra thick pipe wall (applicable only for magnetic flux leakage internal inspection tools) - Other - - If Other, Describe:	Pressure did not exceed MOP No No No Select all that apply)

- If Yes, Which operational factors complicate execution? (select all that ap	pply)
 Excessive debris or scale, wax, or other wall buildup 	
 Low operating pressure(s) 	
 Low flow or absence of flow 	
 Incompatible commodity 	
- Other -	
- If Other, Describe:	
5f. Function of pipeline system:	
6. Was a Supervisory Control and Data Acquisition (SCADA)-based	Voc
system in place on the pipeline or facility involved in the Accident?	163
If Yes -	
6a. Was it operating at the time of the Accident?	Yes
6b. Was it fully functional at the time of the Accident?	Yes
6c. Did SCADA-based information (such as alarm(s),	
alert(s), event(s), and/or volume calculations) assist with	Yes
the detection of the Accident?	
6d. Did SCADA-based information (such as alarm(s),	Ma a
alert(s), event(s), and/or volume calculations) assist with	Yes
the confirmation of the Accident?	
7. was a CPM leak detection system in place on the pipeline or facility	Yes
Involved in the Accident?	
- II 105.	Voc
7a. was it operating at the time of the Accident?	
7b. Was it fully functional at the time of the Accident?	Tes
7C. Did CPIVI leak delection system momation (such as	Vaa
with the detection of the Accident?	165
Zd. Did CPM leak detection system information (such as	
alarm(s) alert(s) event(s) and/or volume calculations) assist	Vas
with the confirmation of the Accident?	103
8. How was the Accident initially identified for the Operator?	Controller
- If Other Specify	
8a If "Controller" "Local Operating Personnel" including	
contractors". "Air Patrol". or "Guard Patrol by Operator or its	Operator employee
contractor" is selected in Question 8, specify the following:	
	No, the Operator did not find that an investigation of the
9. Was an investigation initiated into whether or not the controller(s) or	controller(s) actions or control room issues was necessary
Accident?	due to: (provide an explanation for why the Operator did not
Accident	investigate)
- If No, the Operator did not find that an investigation of the	due to the cause of the release resulted from a broken
controller(s) actions or control room issues was necessary due to:	fitting on the thermal relief valve, the controlled did not
(provide an explanation for why the operator did not investigate)	contrubute to the release.
 If Yes, specify investigation result(s): (select all that apply) 	
 Investigation reviewed work schedule rotations, 	
continuous hours of service (while working for the	
Operator), and other factors associated with fatigue	
 Investigation did NOT review work schedule rotations, continuous hours of convice (while working for the 	
Continuous nours of service (while working for the	
Drovide an evplanation for why not	
- Investigation identified no control room issues	
Investigation identified no controller issues	
- Investigation identified incorrect controller action or	
controller error	
- Investigation identified that fatigue may have affected the	
controller(s) involved or impacted the involved controller(s)	
response	
- Investigation identified incorrect procedures	
- Investigation identified incorrect control room equipment	
operation	
- Investigation identified maintenance activities that affected	
control room operations, procedures, and/or controller	
response	
 Investigation identified areas other than those above: 	
Describer	
Describe.	
PART F - DRUG & ALCOHOL TESTING INFORMATION	

1. As a result of this Accident, were any Operator employees tested		
under the post-accident drug and alcohol testing requirements of DOT's	No	
Drug & Alcohol Tacting regulations?	NO	
- If Yes:		
1a. Specify how many were tested:		
1b Specify how many failed		
2. As a result of this Accident, were any Operator contractor employees	l	
tested under the post-accident drug and alcohol testing requirements of	NO	
DOT's Drug & Alcohol Testing regulations?		
- If Yes:		
2a. Specify how many were tested:		
2b. Specify how many failed		
PART G – APPARENT CAUSE		
Select only one box from PART G in shaded column on left representing the APPARENT Cause of the Accident, and answer the questions on the right. Describe secondary, contributing or root causes of the Accident in the narrative (PART H).		
Apparent Cause:	G6 - Equipment Failure	
G1 - Corrosion Failure - only one sub-cause can be picked from sha	ded left-hand column	
External Corresion:		
Internal Corrosion:		
- If External Corrosion:		
 Results of visual examination: 		
- If Other, Describe:		
2. Type of corrosion: (select all that apply)		
- Galvanic		
- Atmospheric		
- Stray Current		
Mierobiological		
- Microbiological		
- Selective Seam		
- Other:		
- If Other, Describe:		
The type(s) of corrosion selected in Question 2 is based on the followir	ng: (select all that apply)	
- Field examination		
 Determined by metallurgical analysis 		
- Other:		
- If Other. Describe:		
4. Was the failed item buried under the ground?		
- If Yes -		
□ Ao Was failed item considered to be under asthedia		
44. Was falled item considered to be under cathodic		
protection at the time of the Accident?		
If Yes - Year protection started:		
4b. Was shielding, tenting, or disbonding of coating evident at		
the point of the Accident?		
4c. Has one or more Cathodic Protection Survey been		
conducted at the point of the Accident?		
If "Yes, CP Annual Survey" – Most recent year conducted:		
If "Yes, Close Interval Survey" - Most recent year conducted:		
If "Ves Other CP Sun/av" - Most recent year conducted:		
- II INU.		
40. was the ralled item externally coated or painted?		
5. vvas there observable damage to the coating or paint in the vicinity of		
the corrosion?		
- It Internal Corrosion:		
6. Results of visual examination:		
- Other:		
7. Type of corrosion (select all that apply): -		
- Corrosive Commodity		
- Water drop-out/Acid		
- Microbiological		
- If Other, Describe:		
δ. The cause(s) of corrosion selected in Question 7 is based on the follow	ving (select all that apply): -	
- Field examination		
 Determined by metallurgical analysis 		

- Other:	
- If Other, Describe:	
9. Location of corrosion (select all that apply): -	
- Low point in pipe	
- Elbow	
- Other:	
- If Other, Describe:	
10. Was the commodity treated with corrosion inhibitors or biocides?	
11. Was the interior coated or lined with protective coating?	
12. Were cleaning/dewatering pigs (or other operations) routinely	
utilized?	
13. Were corrosion coupons routinely utilized?	
Complete the following if any Corrosion Failure sub-cause is selected AND	the "Item Involved in Accident" (from PART C,
Question 3) is Tank/Vessel.	
14. List the year of the most recent inspections:	
14a. API Std 653 Out-of-Service Inspection	
- No Out-of-Service Inspection completed	
14b. API Std 653 In-Service Inspection	
- No In-Service Inspection completed	
Complete the following if any Corrosion Failure sub-cause is selected AND	the "Item Involved in Accident" (from PART C,
Question 3) is Pipe or Weld.	
15. Has one or more internal inspection tool collected data at the point of the	
Accident?	
15a. If Yes, for each tool used, select type of internal inspection tool and i	ndicate most recent year run: -
 Magnetic Flux Leakage Tool 	
Most recent year:	
- Ultrasonic	
Most recent year:	
- Geometry	
Most recent year:	
- Caliper	
Most recent year:	
- Crack	
Most recent year:	
- Hard Spot	
Most recent year:	
- Combination 1001	
Transverse Field/Trieviel	
- Hansverse Field/Hidxidi	
- Other	
Most recent year:	
Describe:	
16. Has one or more hydrotest or other pressure test been conducted since	
original construction at the point of the Accident?	
If Yes -	
Most recent vear tested:	
Test pressure:	
17. Has one or more Direct Assessment been conducted on this segment?	
- If Yes, and an investigative dig was conducted at the point of the Accident::	
Most recent year conducted:	
- If Yes, but the point of the Accident was not identified as a dig site:	
Most recent year conducted:	
18. Has one or more non-destructive examination been conducted at the	
point of the Accident since January 1, 2002?	a of non-dootructive oversignation and is directs must
18a. If Yes, for each examination conducted since January 1, 2002, select type	e of non-destructive examination and indicate most
Pediagraphy	
- Naulography Most recent year conducted:	
- Guided Wave Elltrasonic	
- Oulded wave Olliasonic Most recent year conducted:	
- Handheld Ultrasonic Tool	
Most recent year conducted	
- Wet Magnetic Particle Test	
Most recent vear conducted:	
- Dry Magnetic Particle Test	
Most recent vear conducted:	
- Other	
Most recent year conducted:	

Natural Force Damage - Sub-Cause: I Earth Movement, NOT due to Heavy Rains/Floods: 1. Specify: - If Other, Describe: - If Heavy Rains/Floods: 2. Specify: - If Other, Describe: - If Lightning: 3. Specify: - If Other, Describe: - If Temperature: 4. Specify: - If Other, Describe: - If High Winds: - If Other Natural Force Damage: 5. Describe: Complete the following if any Natural Force Damage sub-cause is selected. 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? 6a. If Yes, specify: (select all that apply) - Tropical Storm - Tropical Storm - Torpical Storm - If Excavation Damage - outy one sub-ca	G2 - Natural Force Damage - only one sub-cause can be picked from shaded left-handed column	
If Earth Movement, NOT due to Heavy Rains/Floods: Specify:	Natural Force Damage – Sub-Cause:	
1. Specify: If Other, Describe: - If Heavy Rains/Floods: . 2. Specify: - If Other, Describe: - If Lightning: . 3. Specify: - If Other, Describe: - If Temperature: . 4. Specify: - If Other, Describe: - If High Winds: - If Other, Describe: - If Other Natural Force Damage: - 5. Describe: - - If Other Natural Force Damage: - 5. Describe: - Complete the following if any Natural Force Damage sub-cause is selected. - 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? - 6a. If Yes, specify: (select all that apply) - - - Hurricane - - - Tropical Storm - - - Other - If Other, Describe: - G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column - Excavation Damage by Operator (First Party): - - - If Cher, Describe: - - - If Excavation Damage by Operator's Contractor (Second Party): - <td< td=""><td>- If Earth Movement, NOT due to Heavy Rains/Floods:</td><td></td></td<>	- If Earth Movement, NOT due to Heavy Rains/Floods:	
If Other, Describe: If Other, Describe: If Other, Describe: If Other, Describe: If Uphtning: Specify: If Other, Describe: If I Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Third Party: If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? If Nearonic Most recent year conducted: Ultrasonic Most recent year conducted: Other If Previous Damage Different Par	1. Specify:	
If newy tails/rodds. Specify: If Lightning: If Other, Describe: If I Other, Describe: If I Other, Describe: If Temperature: If Temperature: If Other, Describe: If Other, Network I Other, Describe: If Other, Describe: If Other Natural Force Damage: S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? Se. If Yes, Specify: (secoder all that apply) - If Other, Describe: G3 - Excavation Damage by Operator (First Party): - If Other, Describe: If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONL Y IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Other Mos	- If Other, Describe:	
If Upher, Describe: If Other, Describe: If Other, Describe: If Temperature: A. Specify: If Other, Describe: If Other, Describe: If Other Natural Force Damage: Solution: If Other Natural Force Damage: If Other Natural Force Damage: Solution: If Other Natural Force Damage: Solution: If Other Natural Force Damage sub-cause is selected. Solution: Accession: If Other Interval forces causing the Accident generated in conjunction with an extreme weather event? Ga. If Yes, specify: (select all that apply) -If Untercane - Tropical Storm - Tornado - Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Ultrasonic Most recent year conducted: - Ultrasonic	2. Specify:	
If Lightning: S. Specify: If Temperature: Secify: If Other, Describe: If Other, Describe: If Other Natural Force Damage: Secify: If Other Natural Force Damage: Secifie: S	- If Other, Describe:	
3. Specify: - If Other, Describe: - If High Winds: - If Other, Describe: - If Other Natural Force Damage: 5. Describe: Complete the following if any Natural Force Damage sub-cause is selected. 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? Ga. If Yes, specify: (select all that apply) - Hurricane - Tropical Storm - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage - Other Complete Questions 1-5 ONLY IF the "teem functioned in the accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate mos	- If Lightning:	
If High Winds: If Other, Describe: If Other Natural Force Damage: S. Describe: If Other Natural Force Damage: S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Describe: S. Describe: Secribe: Select all that apply) - Hurricane - Tropical Storm - Tornado - Other - If Other, Describe: S3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONL Y IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more intermal inspection tool and indicate most recent year run: - Mognetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Other more interval inspection colloced data at the point of the Accident? - Magnetic Flux Leakage	3. Specify:	
- If Other, Describe: - If Other, Describe: - If Other, Natural Force Damage: - If Other Natural Force Damage: - S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? Sa. If Yes, specify: (select all that apply) - Hurricane - Tropical Storm - Tornado - Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage by Operator (First Party): - If Excavation Damage by Operator (Second Party): - If Excavation Damage by Operator (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY If the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1. All Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted:	4. Specify	
- If High Winds: - If Other Natural Force Damage: 5. Describe: Complete the following if any Natural Force Damage sub-cause is selected. 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? 6a. If Yes, specify: (select all that apply) - Hurricane - Tropical Storm - Tropical Storm - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Dird Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? - Most recent year conducted: - Wost recent year conducted: - Geometry - Most recent year conducted: - Geometry - Most recent year conducted: - Complete Cuestions Conducted: - Complete Cuestions Conducted: - Geometry - Most recent year conducted: - Complete Cuestions Cuestions Cuestions Cuestions Cuestions Cuestions Cuestions Cuestions - Cuestions	- If Other, Describe:	
If Other Natural Force Damage: S. Describe: Complete the following if any Natural Force Damage sub-cause is selected. S. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? Sa. If Yes, specify: (select all that apply)	- If High Winds:	
In order training of the order of the second sec	- If Other Natural Force Damage:	
Complete the following if any Natural Force Damage sub-cause is selected. 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? 6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? 6. If Yes, specify: (select all that apply) - Tropical Storm - Tornado - Tornado - Other - Ulter - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1. Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	5. Describe:	
6. Were the natural forces causing the Accident generated in conjunction with an extreme weather event? 6a. If Yes, specify: (select all that apply) - Hurricane - Tropical Storm - Tornado - Other - Other - Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: - Geometry Most recent year conducted:	Complete the following if any Natural Force Damage sub-cause is sele	cted.
conjunction with an extreme weather event? 6a. If Yes, specify: (select all that apply) - Hurricane - Tropical Storm - Tornado - Other - Other - Bit Storm - Other - Starting Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	6. Were the natural forces causing the Accident generated in	
6a. If Yes, specify: (select all that apply) - Tropical Storm - Tornado - Other - Other - Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	conjunction with an extreme weather event?	
- Tropical Storm - Tornado - Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: Geometry	6a. If Yes, specify: (select all that apply)	
Tornado Other - If Other, Describe: - If Constant - If Other, Describe: - If Constant - If Other, Describe: - If Constant - If Other, Describe: - If Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: -	- Tropical Storm	
- Other - If Other, Describe: G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: -	- Tornado	
G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: If Excavation Damage by Operator (First Party): If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Third Party: If Excavation Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted:	- Other	
G3 - Excavation Damage - only one sub-cause can be picked from shaded left-hand column Excavation Damage - Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry	- If Other, Describe:	
Excavation Damage – Sub-Cause: - If Excavation Damage by Operator (First Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Operator's Contractor (Second Party): - If Excavation Damage by Third Party: - If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	G3 - Excavation Damage - only one sub-cause can be picked from s	naded left-hand column
If Excavation Damage by Operator (First Party): If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Third Party: If Excavation Damage by Third Party: If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? I. Has one or more internal inspection tool collected data at the point of the Accident? I. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted:	Excavation Damage – Sub-Cause:	
If Excavation Damage by Operator's Contractor (Second Party): If Excavation Damage by Third Party: If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: -	- If Excavation Damage by Operator (First Party):	
If Excavation Damage by Third Party: If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: -	- If Excavation Damage by Operator's Contractor (Second Party):	
If Excavation Damage by Third Party: If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. I. Has one or more internal inspection tool collected data at the point of the Accident? Ia. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: Outrasonic Most recent year conducted: Most recent year conducted: Most recent year conducted: Most recent year conducted:		
If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: Outrasonic Most recent year conducted: Outrasonic Most recent year conducted: Outrasonic Most recent year conducted:	- If Excavation Damage by Third Party:	
Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld. 1. Has one or more internal inspection tool collected data at the point of the Accident?	If Providuo Domogo due to Execution Activity	
1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted:	- If Previous Damage due to Excavation Activity:	
1a. If Yes, for each tool used, select type of internal inspection tool and indicate most recent year run: - - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from	PART C, Question 3) is Pipe or Weld.
Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident?	PART C, Question 3) is Pipe or Weld.
Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a	PART C, Question 3) is Pipe or Weld.
Most recent year conducted: Geometry Most recent vear conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. nd indicate most recent year run: -
- Geometry Most recent year conducted:	If Previous Damage due to Excavation Activity: Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: Ultrooppin	PART C, Question 3) is Pipe or Weld. nd indicate most recent year run: -
Most recent vear conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted:	PART C, Question 3) is Pipe or Weld.
	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry	PART C, Question 3) is Pipe or Weld.
- Caliper Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: Output	PART C, Question 3) is Pipe or Weld.
- Crack	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Caliper	PART C, Question 3) is Pipe or Weld. nd indicate most recent year run: -
Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted:	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
Hard Spot Most recent year conducted: Most recent year conducted: Ormbination Teal	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: Combination Tool	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage - Most recent year conducted: - Ultrasonic - Geometry - Most recent year conducted: - Caliper - Most recent year conducted: - Crack - Crack - Most recent year conducted: - Hard Spot - Combination Tool	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Hard Spot Most recent year conducted: Combination Tool Most recent year conducted: Combination Tool Most recent year conducted: Cransverse Field/Triaxial	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: Ombination Tool Most recent year conducted: Ombination Tool Most recent year conducted: Ombination Tool Most recent year conducted: Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
Hard Spot Most recent year conducted: Most recent year conducted: Combination Tool Most recent year conducted: Transverse Field/Triaxial Most recent year conducted: Other	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: Describe:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Transverse Field/Triaxial Most recent year conducted: Other	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Describe: Describe:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Crack Most recent year conducted: - Combination Tool Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: - Other Most recent year conducted: - Other	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained?	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Describe: Describe:	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: Other Other Most recent year conducted: Other	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Ot	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Other Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 3. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Accident? - If Yes:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Geometry Most recent year conducted: Other Most recent year conducted: Caliper Most recent year conducted: Other Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: O	PART C, Question 3) is Pipe or Weld.
- Crack	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper - Most recent year conducted: - Caliper	PART C, Question 3) is Pipe or Weld.
	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted:	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Hard Spot Most recent year conducted: Combination Tool	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: Ombination Tool Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Hard Spot Most recent year conducted: Combination Tool	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: Ombination Tool Most recent year conducted: Ombination Tool Most recent year conducted: Ombination Tool Ombination Tool Most recent year conducted: Ombination Tool	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Accident year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Other	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Accident year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Other Most recent year conducted: Other Most recent year conducted: Accident	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Describe:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Describe:	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: Describe: Describe:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other	PART C, Question 3) is Pipe or Weld. Ind indicate most recent year run: -
- Hard Spot Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed REFORE the damage was sustained?	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: Most recent year conducted: Combination Tool Most recent year conducted: Transverse Field/Triaxial Most recent year conducted: Other Most recent year conducted: Other Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 3. Has one or more hydrotest or other pressure test been conducted since	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Crack Most recent year conducted: - Crack Most recent year conducted: - Combination Tool Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: - Other Most recent year conducted: - Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? - Has one or more hydrotest or other pressure test been conducted since - Conducted of the damage was sustained? - Most recent year conducted of the	PART C, Question 3) is Pipe or Weld.
- Hard Spot Most recent year conducted: Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Other Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 3. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Accident? - If Yes:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a Magnetic Flux Leakage Most recent year conducted: Ultrasonic Most recent year conducted: Geometry Most recent year conducted: Caliper Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Crack Most recent year conducted: Combination Tool Most recent year conducted: Other Most recent year conducted: Ot	PART C, Question 3) is Pipe or Weld.
Hard Spot Most recent year conducted: Describe: 2. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 3. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Accident? Most recent year tested: Most recent year tested:	Complete Questions 1-5 ONLY IF the "Item Involved in Accident" (from 1. Has one or more internal inspection tool collected data at the point of the Accident? 1a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year conducted: - Ultrasonic Most recent year conducted: - Geometry Most recent year conducted: - Caliper Most recent year conducted: - Crack Most recent year conducted: - Crack Most recent year conducted: - Crack Most recent year conducted: - Transverse Field/Triaxial Most recent year conducted: - Other Most recent year conducted: - Other Most recent year conducted: - Other Most recent year conducted: - If Yes: Most recent year conducted since original construction at the point of the Accident? - If Yes: Most recent year tested:	PART C, Question 3) is Pipe or Weld.

4. Has one or more Direct Assessment been conducted on the pipeline	
segment?	
 If Yes, and an investigative dig was conducted at the point of the Acc 	dent:
Most recent year conducted:	
 If Yes, but the point of the Accident was not identified as a dig site: 	
Most recent year conducted:	
5. Has one or more non-destructive examination been conducted at the	
Four for the Accident since January 1, 2002?	acleat turns of non-destructive exemination and indicate most
5a. If res, for each examination, conducted since January 1, 2002, recent year the examination was conducted:	select type of non-destructive examination and indicate most
- Radiography	
Most recent year conducted:	
- Guided Wave Ultrasonic	
Most recent year conducted:	
- Handheld Ultrasonic Tool	
Most recent year conducted:	
- Wet Magnetic Particle Test	
Most recent year conducted:	
- Dry Magnetic Particle Test	
Most recent year conducted:	
- Other	
Most recent year conducted:	
Describe:	
Complete the following if Excavation Damage by Third Party is selected	ed as the sub-cause.
6. Did the operator get prior potification of the excavation activity?	
6a. If Yes. Notification received from: (select all that apply) -	1
- One-Call System	
- Excavator	
- Contractor	
- Landowner	
Complete the following mandatom: COA DIDT Program musetions if an	· Evenuetien Demons sub seven is calented
Complete the following mandatory CGA-DIR I Program questions if any	y Excavation Damage sub-cause is selected.
7. Do you want PHMSA to upload the following information to CGA-	
DIRT (www.cga-dirt.com)?	
8. Right-of-Way where event occurred: (select all that apply) -	
- Public	
- If "Public", Specify:	
- Private	
- If "Private", Specify:	
Discline Dresents //Economicst	
- Pipeline Property/Easement	
- Pipeline Property/Easement - Power/Transmission Line Railroad	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Litility Easement	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator:	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavation equipment:	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavation equipment: 11. Type of work performed:	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified?	
Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number:	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavation equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facilities marked correctly? 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavator: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? 12. Was the One-Call Center notified? 12. If Yes, specify ticket number: 12. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: Type of Locator: Were facilities marked correctly? Did the damage cause an interruption in service? If As If Yes, specify duration of the interruption (hours) 	
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavator: Type of excavation equipment: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? I2a. If Yes, specify ticket number: Type of Locator: Were facility locate marks visible in the area of excavation? Were facilities marked correctly? Did the damage cause an interruption in service? A. If Yes, specify duration of the interruption (hours) Description of the CGA-DIET Root Cause (select only the one proder 	ninant first level CGA-DIRT Poot Cause and then where
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavation equipment: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: Type of Locator: Were facility locate marks visible in the area of excavation? Were facilities marked correctly? Did the damage cause an interruption in service? A. If Yes, specify duration of the interruption (hours) Description of the CGA-DIRT Root Cause (select only the one predomant second level CGA-DIRT Root 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavation equipment: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: Type of Locator: Were facility locate marks visible in the area of excavation? Were facility locate marks visible in the area of excavation? Did the damage cause an interruption in service? A. If Yes, specify duration of the interruption (hours) Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predominant second level CGA-DIRT Root Root Cause: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavator: Type of excavation equipment: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: Type of Locator: Were facility locate marks visible in the area of excavation? Were facility locate marks visible in the area of excavation? Were facilities marked correctly? Did the damage cause an interruption in service? A. If Yes, specify duration of the interruption (hours) Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predorminant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient specify: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: 10. Type of excavator equipment: 11. Type of excavation equipment: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facility locate marks visible in the area of excavation? 16. Did the damage cause an interruption in service? 16a. If Yes, specify duration of the interruption (hours) 17. Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predormant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Locating Practices Not Sufficient. specify: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavator equipment: 11. Type of excavation equipment: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facilities marked correctly? 16. Did the damage cause an interruption in service? 16a. If Yes, specify duration of the interruption (hours) 17. Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predormant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Locating Practices Not Sufficient, specify: If Excavation Practices Not Sufficient, specify: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavator equipment: 11. Type of excavation equipment: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facilities marked correctly? 16. Did the damage cause an interruption in service? 16a. If Yes, specify duration of the interruption (hours) 17. Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predominant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Locating Practices Not Sufficient, specify: If Excavation Practices Not Sufficient, specify: If Other/None of the Above, explain: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavator equipment: 11. Type of excavation equipment: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facilities marked correctly? 16. Did the damage cause an interruption in service? 16a. If Yes, specify duration of the interruption (hours) 17. Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predorminant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Locating Practices Not Sufficient, specify: If Cother/None of the Above, explain: 	ninant first level CGA-DIRT Root Cause and then, where Cause as well):
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other Type of excavator: Type of excavator: Type of excavation equipment: Type of excavation equipment: Type of work performed: Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: Type of Locator: Were facility locate marks visible in the area of excavation? Were facilities marked correctly? Did the damage cause an interruption in service? I6a. If Yes, specify duration of the interruption (hours) Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predominant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Locating Practices Not Sufficient, specify: If Cother/None of the Above, explain: G4 - Other Outside Force Damage - only one sub-cause can be since the second level cause can be since the second level cause can be since the cause can be since the condition of the cause can be since the cause can be sinc	elected from the shaded left-hand column
 Pipeline Property/Easement Power/Transmission Line Railroad Dedicated Public Utility Easement Federal Land Data not collected Unknown/Other 9. Type of excavator: 10. Type of excavator equipment: 11. Type of work performed: 12. Was the One-Call Center notified? 12a. If Yes, specify ticket number: 12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified: 13. Type of Locator: 14. Were facility locate marks visible in the area of excavation? 15. Were facilities marked correctly? 16a. If Yes, specify duration of the interruption (hours) 17. Description of the CGA-DIRT Root Cause (select only the one predor available as a choice, the one predormant second level CGA-DIRT Root Root Cause: If One-Call Notification Practices Not Sufficient, specify: If Excavation Practices Not Sufficient, specify: If Other/None of the Above, explain: 	

- If Nearby Industrial, Man-made, or Other Fire/Explosion as Primary Cause of Incident:			
- If Damage by Car, Truck, or Other Motorized Vehicle/Equipment NO	- If Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Engaged in Excavation:		
1. Vehicle/Equipment operated by:			
- If Damage by Boats, Barges, Drilling Rigs, or Other Maritime Equipn Their Mooring:	nent or Vessels Set Adrift or Which Have Otherwise Lost		
2. Select one or more of the following IF an extreme weather event was a	factor:		
- Tropical Storm			
- Tornado			
- Heavy Rains/Flood			
- Uther - If Other Describe:			
- If Routine or Normal Fishing or Other Maritime Activity NOT Engage	d in Excavation:		
If Electrical Arcing from Other Equipment or Equility			
- If Electrical Arcing from Other Equipment or Facility:			
- If Previous Mechanical Damage NOT Related to Excavation:			
Complete Questions 3-7 ONLY IF the "Item Involved in Accident" (from	m PART C, Question 3) is Pipe or Weld.		
3. Has one or more internal inspection tool collected data at the point of the Accident?			
3a. If Yes, for each tool used, select type of internal inspection tool and in	dicate most recent year run:		
- Magnetic Flux Leakage			
- Ultrasonic			
Most recent year conducted:			
- Geometry			
Most recent year conducted:			
Most recent vear conducted:			
- Crack			
Most recent year conducted:			
- Hard Spot			
Most recent year conducted:			
Most recent year conducted:			
- Transverse Field/Triaxial			
Most recent year conducted:			
- Other Most report year conducted			
Describe:			
4. Do you have reason to believe that the internal inspection was			
completed BEFORE the damage was sustained?			
5. Has one or more hydrotest or other pressure test been conducted			
- If Yes:			
Most recent year tested:			
Test pressure (psig):			
o. ⊓as one or more Direct Assessment been conducted on the pipeline segment?			
- If Yes, and an investigative dig was conducted at the point of the Accident:			
Most recent year conducted:			
- If Yes, but the point of the Accident was not identified as a dig site:			
7. Has one or more non-destructive examination been conducted at the			
point of the Accident since January 1, 2002?			
7a. If Yes, for each examination conducted since January 1, 2002, se	elect type of non-destructive examination and indicate most		
- Radiography			
Most recent year conducted:			
- Guided Wave Ultrasonic			
Most recent year conducted:			
Most recent vear conducted:			
- Wet Magnetic Particle Test			
Most recent year conducted:			
- Dry Magnetic Particle Test			
- Other			
Most recent vear conducted:			
Describe:			
--	---		
- If Intentional Damage:			
8. Specify:			
- If Other, Describe:			
- If Other Outside Force Damage:			
9. Describe:			
G5 - Material Failure of Pipe or Weld - only one sub-cause can be	selected from the shaded left-hand column		
Use this section to report material failures ONLY IF the "Item Involve" "Weld."	d in Accident" (from PART C, Question 3) is "Pipe" or		
Material Failure of Pipe or Weld – Sub-Cause:			
 The sub-cause selected below is based on the following: (select all the - Field Examination 	at apply)		
- Determined by Metallurgical Analysis			
- Other Analysis			
- If "Other Analysis", Describe:			
- Sub-cause is Tentative or Suspected; Still Under Investigation			
(Supplemental Report required)			
- II Construction, Installation, or Fabrication-related:			
2. List contributing factors: (Select all that apply)			
- i aliyut ui vivialiuii-itilaltu Coosifu			
- Mechanical Stress:			
- Other			
- If Other. Describe:			
- If Original Manufacturing-related (NOT girth weld or other welds for	med in the field):		
2. List contributing factors: (select all that apply)			
- Fatigue or Vibration-related:			
Specify:			
- If Other, Describe:			
- Mechanical Stress:			
- Other			
- If Other, Describe:			
- If Environmental Cracking-related:			
3. Specify:			
- Other - Describe:			
Complete the following if any Material Failure of Pipe or Weld sub-cau	se is selected.		
A Additional factors: (select all that annly):			
- Dent			
- Gouge			
- Pipe Bend			
- Arc Burn			
- Crack			
- Lack of Fusion			
- Lack of Fusion - Lamination			
- Lack of Fusion - Lamination - Buckle			
- Lack of Fusion - Lamination - Buckle - Wrinkle			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other:			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - If Other, Describe: 5. Has one or more internal inspection tool collected data at the point of			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: 5. Has one or more internal inspection tool collected data at the point of the Accident?			
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: 5. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - Stas one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - Stas one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run:	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - Stass one or more internal inspection tool collected data at the point of the Accident? - Sa. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Ultrasonic	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Ultrasonic Most recent year run: - Geometry	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Geometry Most recent year run:	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Geometry Most recent year run: - Caliper	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Geometry Most recent year run: - Caliper	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Geometry Most recent year run: - Caliper Most recent year run: - Crack	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - S. Has one or more internal inspection tool collected data at the point of the Accident? 5a. If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage Most recent year run: - Ultrasonic Most recent year run: - Caliper Most recent year run: - Crack Most recent year run:	nd indicate most recent year run:		
- Lack of Fusion - Lamination - Buckle - Wrinkle - Misalignment - Burnt Steel - Other: - Other: - If Other, Describe: - Stasses - If Other, Describe: - Other: - If Other, Describe: - Stasses - If Other, Describe: - Stasses - If Yes, for each tool used, select type of internal inspection tool a - Magnetic Flux Leakage - Ultrasonic - Ultrasonic - Geometry - Geometry - Caliper - Caliper - Crack Most recent year run: - Crack Most recent year run: - Hard Spot	nd indicate most recent year run:		

- Combination Tool	
Most recent year run:	
- Transverse Field/Triaxial	
Most recent year run:	
- Other	
Most recent year run:	
Nost recent year run.	
6 Has one or more hydrotest or other pressure test been conducted since	
original construction at the point of the Accident?	
- If Voe:	
Most recent year tested:	
Test pressure (psig):	
7 Has one or more Direct Assessment been conducted on the pineline	
compart2	
If Voc. and an invoctigative dig was conducted at the point of the Acci	dont
- If Tes, and an investigative dig was conducted at the point of the Acci	
If Yee, but the point of the Appident was not identified as a dig site	
- If Yes, but the point of the Accident was not identified as a dig site -	
Most recent year conducted:	
8. Has one or more non-destructive examination(s) been conducted at the	
Point of the Accident since January 1, 2002?	plant type of non-deats until a symplection and indicate most
8a. If Yes, for each examination conducted since January 1, 2002, se	elect type of non-destructive examination and indicate most
Dediagraphy	
- Raulography Most recent user conducted	
Most recent year conducted:	
- Guided wave Ultrasonic	
Most recent year conducted:	
- Handheld Ultrasonic Tool	
Most recent year conducted:	
- Wet Magnetic Particle Test	
Most recent year conducted:	
- Dry Magnetic Particle Test	
Most recent year conducted:	
- Other	
Most recent year conducted:	
Describe:	
Describe:	
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t	he shaded left-hand column
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t	he shaded left-hand column
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure – Sub-Cause:	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure – Sub-Cause: - If Malfunction of Control/Relief Equipment:	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the selected fro	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the selected fro	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: Describe: G6 – Equipment Failure – only one sub-cause can be selected from the sele	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: Describe: G6 – Equipment Failure - only one sub-cause can be selected from the sele	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: Describe: G6 – Equipment Failure - only one sub-cause can be selected from the sele	ne shaded left-hand column Threaded Connection/Coupling Failure
Describe: Describe: G6 – Equipment Failure – only one sub-cause can be selected from the sele	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: Describe: G6 – Equipment Failure – only one sub-cause can be selected from the sele	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure – only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 - Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 - Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 - Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 - Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure - Sub-Cause: If Malfunction of Control/Relief Equipment: 1. Specify: (select all that apply) - - Control Valve - Instrumentation - SCADA - Communications - Block Valve - Check Valve - Relief Valve - Relief Valve - Stopple/Control Fitting - ESD System Failure - Other - If Other – Describe: - If Pump or Pump-related Equipment: 2. Specify: - If Other – Describe:	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure - Sub-Cause: If Malfunction of Control/Relief Equipment: 1. Specify: (select all that apply) - - Control Valve - Instrumentation - SCADA - Communications - Block Valve - Check Valve - Relief Valve - Relief Valve - Stopple/Control Fitting - ESD System Failure - Other - If Other – Describe: - If Pump or Pump-related Equipment: 2. Specify: - If Other – Describe:	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure - Sub-Cause: If Malfunction of Control/Relief Equipment: 1. Specify: (select all that apply) - - Control Valve - Instrumentation - SCADA - Communications - Block Valve - Check Valve - Check Valve - Relief Valve - Stopple/Control Fitting - ESD System Failure - Other - If Other – Describe: - If Pump or Pump-related Equipment: 2. Specify: - If Other – Describe: - If Other – Describe: - If Non-threaded Connection/Coupling Failure: 3. Specify: - If Other – Describe: - If Non-threaded Connection Failure: 4. Specify: - If Other – Describe:	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from t Equipment Failure – Sub-Cause: If Malfunction of Control/Relief Equipment: 1. Specify: (select all that apply) - - Control Valve - Instrumentation - SCADA - Communications - Block Valve - Check Valve - Check Valve - Relief Valve - Power Failure - Stopple/Control Fitting - ESD System Failure - Other - Other - If Other – Describe: - If Pump or Pump-related Equipment: 2. Specify: - If Other – Describe: - If Other – Describe: <t< td=""><td>he shaded left-hand column Threaded Connection/Coupling Failure</td></t<>	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 – Equipment Failure - only one sub-cause can be selected from the select	he shaded left-hand column Threaded Connection/Coupling Failure
Describe: G6 - Equipment Failure - only one sub-cause can be selected from to Equipment Failure - Sub-Cause: If Malfunction of Control/Relief Equipment: 1. Specify: (select all that apply) - - Control Valve - Instrumentation - SCADA - Communications - Block Valve - Check Valve - Relief Valve - Relief Valve - Stopple/Control Fitting - ESD System Failure - Other - If Other – Describe: - If Pump or Pump-related Equipment: 2. Specify: - If Other – Describe: - If Other – Describe: - If Non-threaded Connection/Coupling Failure: 3. Specify: - If Other – Describe: - If Non-threaded Connection Failure: 4. Specify: - If Other – Describe: - If Other – Chescribe: - If Other –	he shaded left-hand column Threaded Connection/Coupling Failure

Complete the following if any Equipment Failure sub-cause is selected	d.
6. Additional factors that contributed to the equipment failure: (select all t	hat apply)
- Excessive vibration	Yes
- Overpressurization	
- No support or loss of support	
- Manufacturing defect	-
- Loss of electricity	-
- Improper installation	
Mismatched items (different manufacturer for tubing and tubing	
fittings)	
- Dissimilar metals	
- Breakdown of soft goods due to compatibility issues with	
transported commodity	
- Valve vault or valve can contributed to the release	
- Alarm/status failure	
- Misalignment	
- Thermal stress	
- Other	
- If Other Describe:	
G7 - Incorrect Operation - only one sub-cause can be selected from	the shaded left-hand column
Incorrect Operation – Sub-Cause:	
Damage by Operator or Operator's Contractor NOT Related to	
Excavation and NOT due to Motorized Vehicle/Equipment Damage	
Tank, Vessel, or Sump/Separator Allowed or Caused to Overfill or	
Overriow	
1. Specify:	
- If Other, Describe:	
Valve Left or Placed in Wrong Position, but NOT Posulting in a	
Tank, Vessel, or Sump/Separator Overflow or Facility	
Overpressure	
Discharger Englander (Osennessen et al.	
Pipeline or Equipment Overpressured	
Equipment Not Installed Properly	
Wrong Equipment Specified or Installed	
Other Incorrect Operation	
2. Describe:	
Complete the following if any Incorrect Operation sub-cause is selected	ed.
3. Was this Accident related to (select all that apply): -	Т
- Inadequate procedure	
- No procedure established	
- Other:	
- If Other, Describe:	
4. What category type was the activity that caused the Accident?	
5. Was the task(s) that led to the Accident identified as a covered task	
in your Operator Qualification Program?	
5a. If Yes, were the individuals performing the task(s) qualified for the task(s)?	
G8 - Other Accident Cause - only one sub-cause can be selected fr	om the shaded left-hand column
Other Accident Cause – Sub-Cause:	
If Missellaneous	
- II Wilscenarieous:	
- If Linknown	

2. Specify:

PART H - NARRATIVE DESCRIPTION OF THE ACCIDENT

A release occurred at the Ludden Pump Station on the ³/₄" pipe nipple under the thermal relief valve located on the facility discharge piping. A root cause analysis has been conducted and the failed fitting investigation performed. The fatique failure of the 3/4" pipe nipple occurred as a result of excessive vibratio. Results have been provided to PHMSA.

File Full Name

PART I - PREPARER AND AUTHORIZED SIGNATURE

Preparer's Name	Daniel C Cerkoney
Preparer's Title	Compliance Engineer
Preparer's Telephone Number	701-483-1434
Preparer's E-mail Address	dan_cerkoney@transcanada.com
Preparer's Facsimile Number	701-483-1431
Authorized Signature's Name	Daniel C Cerkoney
Authorized Signature Title	Compliance Engineer
Authorized Signature Telephone Number	701-290-1176
Authorized Signature Email	dan_cerkoney@transcanada.com
Date	11/02/2011



November 18, 2011

Mr. Kris Roberts North Dakota Department of Health 918 E. Divide Avenue, 4th Floor Bismarck, North Dakota 58501-1947

Subject: Release Progress Report – Ludden Pump Station TransCanada – Keystone Pipeline, LP Brampton, North Dakota

Dear Mr. Roberts:

This report transmits the results of the October 2011 sampling of the land farmed area and surface water in the wetlands at the TransCanada Keystone Pipeline, LP Ludden Pump Station site near Brampton, North Dakota. This report is submitted in reference to your October 26, 2011 correspondence and the finalization of cleanup actions by TransCanada at this site.

Sampling and Analysis Results

Soil Sampling

The land farmed area was resampled on October 20, 2011. The sample locations are shown on Figure 1 and the results are summarized on Table 1. Analytical results continued to show total extractable hydrocarbon (TEH) concentrations in soils below North Dakota Department of Health (NDDH) clean-up levels at all sampling locations.

Water Sampling

The majority of the wetlands previously sampled were found to have no standing water on October 20, 2011, with the exception of the background sample location $\frac{1}{4}$ mile north of the pump station. The sample location is shown on Figure 2 and the results are summarized on Table 2.

Observed Site Conditions

The crops in the farmed area had been destroyed prior to the October 20, 2011 site visit and the field had been tilled. See attached aerial photograph from October 5, 2011 (Figure 3) showing site and land farm restoration condition.

Recommendation

Based on current conditions at the TransCanada Ludden Pump Station site and your correspondence dated October 26, 2011, we request that no further investigation or remediation be required and that the site be considered for closure.

URS Corporation Fifth Street Towers 100 South Fifth Street, Suite 1500 Minneapolis, MN 55402 612.370.0700 Tel 612.370.1378 Fax



Mr. Kris Roberts North Dakota Department of Health November 18, 2011 Page 2

If you have any questions, please contact Robert Baumgartner of TransCanada Keystone Pipeline at (832) 320-5538 or myself at (612) 373-6849.

Sincerely,

Bruek 6 26

Bruce R. Galer, PG Senior Geologist

cc: Robert Baumgartner, TransCanada Keystone Pipeline

Table 1Summary of Laboratory Analysis-Wetland Water SamplesLudden Pump Station, Brampton, ND-October 20, 2011

					WTLD-026-			1/4 MI-N-	PS-ADJ-	
Location	Units	WTLD-025	WTLD-26-N	WTLD-026-S	Trench	WTLD-027	1/2 Mi-WILD	WTLD	WTLD	Human Health
Sample Date		10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	Limit Class III
								Background-		Water
Туре		NA	NA	NA	NA	NA	NA	Grab	NA	
Analyte										
TEH(C09-C40)	mg/L	NA	NA	NA	NA	NA	NA	0.11	NA	
TEM (C09-C40)	mg/L	NA	NA	NA	NA	NA	NA	0.11	NA	
Benzene	μg/L	NA	NA	NA	NA	NA	NA	<1	NA	71
Ethylbenzene	μg/L	NA	NA	NA	NA	NA	NA	<1	NA	2,900
Toluene	μg/L	NA	NA	NA	NA	NA	NA	<1	NA	200,000
Xylene (Total)	μg/L	NA	NA	NA	NA	NA	NA	<3	NA	10,000*

NOTES: mg/L=Milligrams per liter

µg/L= Micrograms per liter

<x = Not detected to reporting limits of x

TEM=total extractable range hydrocarbons without silica gel preparation

TEH=total extractable range hydrocarbons with silica gel preparation

* None listed for Class III water, value represents Class II water, wetlands unlisted are considered Class III waters

--- = No applicable standard

NA = No surface water present at sample location

Location	Unite				WTLD-26-			1/4 MI-N-	PS-ADJ-	A mustice Life	Amustia Life
Comple Date	Unita	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	Value Acute	Value Chronie
Sample Date	-	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	Background-	10/20/11	value Acute	value chilonic
Туре		NA	NA	NA	NA	NA	NA	Grab	NA		
Analyte											
Aluminum, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<200	NA		
Antimony, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<10	NA		640**
Arsenic, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<10	NA	340	150
Barium, dissolved	μg/L	NA	NA	NA	NA	NA	NA	56.5	NA		
Beryllium, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<5.0	NA		
Boron, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<150	NA		
Cadminum, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<1	NA	2.1	0.27
Chromium, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<10	NA	1,800	86
Copper, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<10	NA	14.0	9.3
Lead, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<3	NA	82	3.2
Nickel, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<20	NA	470	52
Selenium, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<15	NA	20	5.0
Silver, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<10	NA	3.8	
Thallium, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<15	NA		0.47**
Zinc, dissolved	μg/L	NA	NA	NA	NA	NA	NA	<20	NA	120	120
Ammonia Nitrogen	mg/L	NA	NA	NA	NA	NA	NA	0.13	NA		

NOTES: mg/L=Milligrams per liter

µg/L= Micrograms per liter

<x = Not detected to reporting limits of x

** Class III Steam Human Health Standard, no aquatic standard listed

*** Some values may be adjusted based on hardness and pH.

NA = No surface water present at sample location

Table 2 Summary of Laboratory Analysis-Land Farming Ludden Pump Station, Brampton, ND

May 15, 2011

Location	Units	LF-A	LF-B	LF-C	LF-D	LF-BKG-A	LF-BKG-B	Clean-up
Sample Date		5/15/11	5/15/11	5/15/11	5/15/11	5/15/11	5/15/11	Level
Sample Type		Composite	Composite	Composite	Composite	Composite	Composite	
Chemical of Concern				•		•		
% Moisture	%	29.3	28	21.6	18.9	20.7	20.7	
TEH(C09-C40)	mg/kg	228	3.1	4.9	143	3.0	3.5	100
TEM(C09-C40)	mg/kg	214	13	10.7	198	13.7	9.2	100
pН	Std. Units	7.2	5.4	7.1	7.1	5.6	5.9	
Nitrate as N	mg/kg	<5.7	9.4	5.1	<4.9	8.1	7.2	
Total Phosphorus	mg/kg	348	388	349	332	428	337	
Total Organic Carbon	mg/kg	3530	5630	6980	10300	4070	4140	

August 2, 2011

Location	Units	LF-A	LF-B	LF-C	LF-D	LF-E*	LF-BKG-A	LF-BKG-B	Clean-up
Sample Date		8/2/11	8/2/11	8/2/11	8/2/11	8/2/11	8/2/11	8/2/11	Level
Sample Type		Composite							
Chemical of Concern			•	•	•				
% Moisture	%	6.4	12.4	21.1	11.8	23.4	36.2	10.1	
TEH(C09-C40)	mg/kg	4.6	4.2	4.1	5.6	7.7	6.8	4.3	100
TEM(C09-C40)	mg/kg	8.8	9.1	5.3	15.2	11.2	10.3	8.9	100
pН	Std. Units	5.3	5.2	5.5	5.0	7.5	7.7	8.2	
Nitrate as N	mg/kg	<4.3	4.6	<5.1	5.9	<5.2	<6.3	<4.5	
Total Phosphorus	mg/kg	274	287	329	340	273	404	307	
Total Organic Carbon	mg/kg	3810	7300	6670	4810	2810	8670	2870	

October 20, 2011

Location	Units	LF-A	LF-B	LF-C	LF-D	LF-BKG-A	LF-BKG-B	Clean-up
Sample Date		10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	10/20/11	Level
Sample Type		Composite	Composite	Composite	Composite	Composite	Composite	
Chemical of Concern								
% Moisture	%	14.4	7	12.6	9.5	17.5	8.7	
TEH(C09-C40)	mg/kg	8.6	4.1	8.4	74.2	6.2	5.6	100
TEM(C09-C40)	mg/kg	14.2	6.5	10.8	87.4	6.8	9.7	100
pН	Std. Units	7	5	6.3	6.0	8.3	7.9	
Nitrate as N	mg/kg	18.6	10.2	31.2	12.4	6.7	4.3	
Total Phosphorus	mg/kg	347	344	363	327	406	348	
Total Organic Carbon	mg/kg	12100	8030	7040	5640	7100	6690	

NOTES:

TEM=total extractable range hydrocarbons without silica gel preparation TEH=total extractable range hydrocarbons with silica gel preparation

* In August 2 sampling, the portion of the field that was scraped to remove surficial oil was separated from sample areas LF-A and LF-B and sampled as sample LF-E.

TransCanada Ludden Pump Station

Figure 1. Land Farm Sample Locations - October 20, 2011





- Toe of Slope Continuous = 91-100% coverage CS Pond Broken = 51-90% coverage
 - Patchy = 11-50% coverage
- Sporadic-Low = 1-5% coverage
- Trace = <1% coverage

- 2011.
- Projection: NAD83 UTM Zone 14N



029656

TransCanada Ludden Pump Station

Figure 2. Off-Site Water Sampling Locations - October 20, 2011

Fifth Street Towers 100 South Fifth Street, Suite 1500 Minneapolis, MN 55402 612.370.0700 Tel 612.370.1378 Fax



Fifth Street Towers 100 South Fifth Street, Suite 1500 Minneapolis, MN 55402 612.370.0700 Tel 612.370.1378 Fax





029658

Environmental Incident Report This report has been submitted.

North Dakota Department of Health Environmental Health Section 1.701.328.5210 or 1.701.328.5166 North Dakota Department of Emergency Services 1.701.328.8100 1.800.472.2121 State Radio 24-Hour Hotline

If this is an emergency, or for additional assistance, please call the Health or Emergency Services Department at the numbers shown above

This form is NOT for RCRA-exempt oilfield related incidents (for RCRA-exempt oilfield incidents click here) (if you are not sure which form to use click here)

Fill out information as completely as possible Error messages appear to the right of the field Use the Tab key or mouse to move between fields Pressing the Enter key while in the form will submit the report Required fields are shown in Red

Location Information:

County	Sargent	
Township	129	
Range	58	
Section	26	
Quarter		
QQSection		
QQQSection		2.

Location Description (911 address or location from nearest town) 10075 119th Ave SE

Brampton, ND 58017

Distance to Nearest Residence or Occupied Building 1.3 Units Miles

Incident Information:

Date 5/7/2011

(mm/dd/yyyy) If unknown, enter date of discovery Time

http://www.ndhealth.gov/ehs/eir/NonOilField/Default.aspx

0605							
hhmm 24-hour time, no	colon						
Type Other (fill in box)							
Pipeline Pump Station Equipment							
Estimated Duration	30	Units	minutes				
Estimated Volume	500	Units	barrels				
Substance released or of Crude Oil	f concern (inc	lude tra	rade and/or chemical name if applicable)				
Agriculture Related? No Is this substance on EPA To find out if this substance	o	Hazard	dous Substance list? No				
Describe Cause							
Small diameter piping fail	ure.						
Action Taken and Record (how spill was contained to burn contaminant, evo Pipeline system shutdowr Company and contractor Oil contained and controll earthen dam were used to Where will recovered w Recovered crude oil/wate Excavated oil impacted go	mmended/Pla d, soil excava acuation of ne and pump sta spill response ed onsite by ea collect sheen astes be disport ravel/soil will be	anned Fu ted, emo earby pe ation isola crews mo arthen be and con osed? red to Lel e transpo	Future Action nergency approval bersonnel, etc.) blated. mobilized to the facility. berm. Offsite oil mist delineated. Absorbent boom and bortrol flow from bonded water on adiacent property to the ePier Oil, Fosston, MN for recycling. ported to Veolia LF, Buffalo MN				
Impact Information							
Fatalities 0	I						
Injuries 0			_				
Medium affected 04 - w	ater and soil						
Immediate Risk Evaluat NA - work conditions were	ion (explosiv e monitored thr	e atmos roughout	osphere, immediate health hazards, etc.) ut response/cleanup activities.				
Potential Environmental	l Impacts						

(describe impacts to, or likelihood of impacts, to surface water, ground water, soils, etc.)

Soils - oil saturated soils were excavated as described above. Residual oil impacts will be treated using insitu landfarming techniques.

Surface water - oil sheen was collected utilizing absorbent boom. Potential dissolved impacts are being monitored.

Responsible Party Information:

Responsible Party	TransCanada
Address (Line 1)	13710 FNB Parkway
Address (Line 2)	Suite 300
City	Omaha
State/Province	NE - Nebraska
Zip	68154
Contact First Name	Robert
Contact Last Name	Baumgartner
Contact Telephone	832-320-5538
Contact Email	robert_baumgartner@trai
Property Owner if not th	e Responsible Party

Has or will the incident be reported to property owner? Unknown

Reporting Information:

First Name	Robert
Last Name	Baumgartner
Date Reported	5/7/2011
(mm/dd/yyyy)	
Time Reported	1015
hhmm 24-hour time	e, no colon

Other agencies that have or will be notified

NDDES

State Fire Marshal

State Highway Patrol

✓ Local Fire Department

✓ Local Law Enforcement

✓ Local Emergency Manager

Other

To see if this incident is required to be reported to the National Response Center (NRC) Click Here

Has or will the incident be reported to the NRC ?? 1-800-424-8802 Yes		
Additional E-Mail Recipients to send reproduct robert_baumgartner@transcanada	port to	

Official Use Only:		
State Agency Person Who Received Call First Name		
Last Name		
Department of Emergency Services Incident Number		
Send this email to Department of Mineral Resources No		

Pressing the submit button will send an E-Mail version of this completed Environmental Incident Report to NDDH Environmental Health Section and ND Dept. of Emergency Services personnel Submit

CERTIFICATE OF SERVICE

I hereby certify that on this 1st day of October 2015, Dakota Rural Action filed the foregoing on the Public Utilities Commission of the State of South Dakota e-filing website. Also on this day, a true and accurate copy of the foregoing was transmitted via email to the following:

Patricia Van Gerpen Executive Director South Dakota Public Utilities Commission 500 E. Capitol Ave. Pierre, SD 57501 patty.vangerpen@state.sd.us

Brian Rounds Staff Analyst South Dakota Public Utilities Commission 500 E. Capitol Ave. Pierre, SD 57501 brian.rounds@state.sd.us

James E. Moore Woods, Fuller, Shultz and Smith P.C. PO Box 5027 Sioux Falls, SD 57117 james.moore@woodsfuller.com Attorney for TransCanada Keystone Pipeline, LP

Paul F. Seamans 27893 249th St. Draper, SD 57531 jacknife@goldenwest.net

Elizabeth Lone Eagle PO Box 160 Howes, SD 57748 bethcbest@gmail.com

Viola Waln PO Box 937 Rosebud, SD 57570 walnranch@goldenwest.net

Benjamin D. Gotschall Bold Nebraska 6505 W. Davey Rd. Kristen Edwards Staff Attorney South Dakota Public Utilities Commission 500 E. Capitol Ave. Pierre, SD 57501 <u>Kristen.edwards@state.sd.us</u>

Darren Kearney Staff Analyst South Dakota Public Utilities Commission 500 E. Capitol Ave. Pierre, SD 57501 <u>darren.kearney@state.sd.us</u>

William G. Taylor Taylor Law Firm 2921 E. 57th St. #10 Sioux Falls, SD 57108 <u>bill.taylor@williamgtaylor.com</u> *Attorney for TransCanada Keystone Pipeline, LP*

John H. Harter 28125 307th Ave. Winner, SD 57580 johnharter11@yahoo.com

Tony Rogers Rosebud Sioux Tribe - Tribal Utility Commission 153 S. Main St. Mission, SD 57555 tuc@rosebudsiouxtribe-nsn.gov

Jane Kleeb Bold Nebraska 1010 N. Denver Ave. Hastings, NE 68901 jane@boldnebraska.org

Byron T. Steskal & Diana L. Steskal 707 E. 2nd St. Stuart NE 68780 prairierose@nntc.net

Raymond, NE 68428 ben@boldnebraska.org

Cindy Myers, R.N. PO Box 104 Stuart, NE 68780 csmyers77@hotmail.com

Lewis GrassRope PO Box 61 Lower Brule, SD 57548 wisestar8@msn.com

Robert G. Allpress 46165 Badger Rd. Naper, NE 68755 bobandnan2008@hotmail.com

Louis T. Genung 902 E. 7th St. Hastings, NE 68901 tg64152@windstream.net

Nancy Hilding 6300 W. Elm Black Hawk, SD 57718 nhilshat@rapidnet.com

Bruce & RoxAnn Boettcher Boettcher Organics 86061 Edgewater Ave. Bassett, NE 68714 boettcherann@abbnebraska.com

William Kindle President Rosebud Sioux Tribe PO Box 430 Rosebud, SD 57570 William.Kindle@rst-nsn.gov

Paula Antoine Sicangu Oyate Land Office Coordinator Rosebud Sioux Tribe PO Box 658 Rosebud, SD 57570 wopila@gwtc.net paula.antoine@rosebudsiouxtribe-nsn.gov

Harold C. Frazier Chairman Arthur R. Tanderup 52343 857th Rd. Neligh, NE 68756 atanderu@gmail.com

Carolyn P. Smith 305 N. 3rd St. Plainview, NE 68769 peachie_1234@yahoo.com

Peter Capossela, P.C. Attorney at Law PO Box 10643 Eugene, OR 97440 pcapossela@nu-world.com Attorney for Standing Rock Sioux Tribe

Gary F. Dorr 27853 292nd Winner, SD 57580 gfdorr@gmail.com

Wrexie Lainson Bardaglio 9748 Arden Rd. Trumansburg, NY 14886 wrexie.bardaglio@gmail.com

Eric Antoine Attorney Rosebud Sioux Tribe PO Box 430 Rosebud, SD 57570 ejantoine@hotmail.com

Chris Hesla South Dakota Wildlife Federation PO Box 7075 Pierre, SD 57501 sdwf@mncomm.com

Bonny Kilmurry 47798 888 Rd. Atkinson, NE 68713 jackiekilmurry@yahoo.com

Amy Schaffer PO Box 114 Cheyenne River Sioux Tribe PO Box 590 Eagle Butte, SD 57625 haroldcfrazier@yahoo.com

Debbie J. Trapp 24952 US HWY 14 Midland, SD 57552 mtdt@goldenwest.net

Joye Braun PO Box 484 Eagle Butte, SD 57625 jmbraun57625@gmail.com

Thomasina Real Bird Fredericks Peebles & Morgan LLP 1900 Plaza Dr. Louisville, CO 80027 <u>trealbird@ndnlaw.com</u> *Attorney for Yankton Sioux Tribe*

Tom BK Goldtooth Indigenous Environmental Network (IEN) PO Box 485 Bemidji, MN 56619 <u>ien@igc.org</u>

Robert P. Gough, Secretary Intertribal Council on Utility Policy PO Box 25 Rosebud, SD 57570 bobgough@intertribalCOUP.org

Tracey Zephier Fredericks Peebles & Morgan LLP 910 5th Street, Suite 104 Rapid City, SD 57701 tzephier@ndnlaw.com Attorney for Cheyenne River Sioux Tribe

Ms. Mary Turgeon Wynne, Esq. Rosebud Sioux Tribe - Tribal Utility Commission 153 S. Main St Mission, SD 57555 <u>tuc@rosebudsiouxtribe-nsn.gov</u> Louisville, NE 68037 amyannschaffer@gmail.com

Gena M. Parkhurst 2825 Minnewasta Place Rapid City, SD 57702 gmp66@hotmail.com

Robert Flying Hawk, Chairman Yankton Sioux Tribe PO Box 1153 Wagner, SD 57380 Robertflyinghawk@gmail.com

Chastity Jewett 1321 Woodridge Dr. Rapid City, SD 57701 <u>chasjewett@gmail.com</u>

Dallas Goldtooth 38371 Res. HWY 1 Morton, MN 56270 goldtoothdallas@gmail.com

Terry & Cheryl Frisch 47591 875th Rd. Atkinson, NE 68713 tcfrisch@q.com

Matthew L. Rappold Rappold Law Office 816 Sixth Street PO Box 873 Rapid City, SD 57709 <u>Matt.rappold01@gmail.com</u> *Attorney for Rosebud Sioux Tribe, Intervenor*

Ms. Kimberly E. Craven 3560 Catalpa Way Bouleder, CO 80304 <u>kimcraven@gmail.com</u> Attorney for Indigenous Environmental Network



Mr. James P. White Attorney TransCanada Keystone Pipeline, LP Ste. 225 1250 Eye St., NW Washington, DC 20005 jim_p_white@transcanada.com Mr. Travis Clark - Representing: Fredericks Peebles & Morgan LLP Ste. 104 910 5th St. Rapid City, SD 57701 tclark@ndnlaw.com Attorney for Cheyenne River Sioux Tribe

And a true and accurate copy of the foregoing was mailed via U.S. Mail, first class postage prepaid, to the following:

Jerry Jones 22584 US HWY 14 Midland SD 57552

Elizabeth Lone Eagle PO Box 160 Howes, SD 57748 Ronald Fees 17401 Fox Ridge Rd. Opal, SD 57758

/s/ Robin S. Martinez

Attorney for Dakota Rural Action