

SD/ND Conference March 2025

Accident Investigation
Division (AID)

Darren Lemmerman

The history of Sioux Falls revolves around the cascades of the Big Sioux River. The Falls was created about 14,000 years ago when the last glacial ice sheet redirected the flow of the river into the large looping bends of its present course. The lure of the falls has been a powerful influence. Prehistoric people who inhabited the region before 500 B.C. left numerous burial mounds on the high bluffs near the river...





Outline

- **Who is AID?**
- **State Accidents**
- **National Accident/Incident Trends**
- **Leak Survey and Grading**
- **Atmos Dallas Case Study**



Accident Investigation Division




Accident Investigation Division

- AID was established on April 1, 2017
- Review, Evaluate, and Circulate NRC Notifications
- Manage Investigation from Initial NRC Notification through Cause Determination
- Conduct Onsite Accident Investigations: Support NTSB and State Investigations
- Review Operator 30-Day Accident/Incident Reports
- Publish State and Federal Monthly Accident Report Summaries (SMARS/MARS)
- Analyze Data to Identify Emerging Trends
- Capture and Share Lessons Learned (SAFE Bulletins, State Conferences, etc.)




Accident Investigation Division Deployments 2018-2024





SD and ND Gas Distribution Incidents

2010 - 2024 Distribution Incidents



National Reportable Incidents 2010-2024


SD and ND 2010 – 2024 Gas Distribution Incidents




Outside the Box - Assigning Risk Factors

Cathodic Protection	Communication/Hazard Assessment
Construction	Control Room
Design	Distracted Employee
Human Error	Integrity Assessment Methods
Integrity Threat Identification	Leak Detection
Manufacturing Defect	Maps/Records
Preventative Maintenance	Training
Repair/Maintenance Work	Software Logic
Procedures – Incorrect, Not Developed, or Not Followed	Risk Factor – Undefined, Unknown, or Not Yet Determined


All Risk Factors 2018 - 2024




GD Risk Factors 2018-2024




SD and ND Gas Distribution Risk Factors




All HL Sub-Causes




All GT Sub-Causes




ALL GD Sub-Causes



HL Failures Resulting in 108 Ruptures




GT Failures Resulting in 184 Ruptures




Close Interval Survey

Was a CIS ever done on the HL pipeline rupture with external below grade corrosion failure?



Was a CIS ever done on the GT pipeline rupture with external below grade corrosion failure?



Cathodic Protection

- Test stations only provide data at the test point. There are 5279 feet of pipe with unknown potentials to the next one-mile test station. Only a close interval survey can reveal the protection between test points.
- Minimum CP potential of rusted mild steel, as noted in the Galvanic Series, is -200mv and any reading taken less negative is being influence by outside sources, such a being shorted to the electrical grid or critical interference. (heavily rusted steel can be as low as -200mv)
- CP stops corrosion with -1100mv of potential. O₂ has been eliminated at the surface of the pipe.
O₂ Reduction Formula $O_2 + H_2O + 4e^- > 4 OH^-$
- Potentials above -1100mv are achievable with a maximum of -1200mv, all energy beyond goes to splitting water and additional potential is not possible. Known as “Excess CP”
H₂O Reduction Formula $2H_2O + 4e^- > H_2 + 2 OH^-$
- Survey potentials must be -200mv to -1200mv anything else is influenced and does not demonstrate a criteria.



Inadequate Compaction

Girth weld failures and where do they occur?

- New construction at tie-ins
- Repairs
- Earth movement
- Installation of other utilities


Prevention

- Compaction procedures
- Compaction testing
- Oversight




External Corrosion after Tool Run

HL Reportable External Corrosion Failures after Tool Run




GT Reportable External Corrosion Failures after Tool Run



Leak Investigation




- Determine leak location using Flame Ionization (FI) Unit
- Pinpoint leak: determine leak spread by bar holing until 0% gas obtained in all directions
- Check several nearby houses
 - If no one is home, check doors and windows
 - If a positive reading is obtained, evacuate
- Check nearby manholes
- If you find any positive gas reads, continue your investigation.



Leak Investigation



Current Understanding from Experiments Example: Effect of Surface Cover




LEL = 50,000 ppm (5% CH₄ V/V)

14 UEL = 150,000 ppm (15% CH₄ V/V)

Jayarathne, Smits, Zimmerle., 2022, METEC Research Alert
Zimmerle, Smits, Jayarathne, 2022, METEC Research Alert




Leak Investigation



* Each bar represents 1-hour. 5 hours of heavy rain capped the gas plume. Leak was graded 3 months prior to explosion.





Case Study
Atmos Energy
Dallas, Texas
Gas Migration
One Fatality and
Three Injuries
February 23, 2018

- February 21, 2018 – Day 1
- House 3527 has an incident at 5:49 a.m.
- Homeowner heard a popping noise in the attic where the heater unit is located. He investigated and found the steel cover to the furnace not on the unit.
- When the cover was reinstalled, the furnace operated the pilot-light igniter, and an explosion occurred throwing him backwards. He never smelled any gas odor.
- Arson investigators responded and determined the cause as “undetermined”.
- Gas company was also on site but not allowed to test service due to structure damage.
- Ground saturated from exceptionally heavy rains





- February 22, 2018 – Day 2
- House 3515 has an incident at 10:21 a.m.
- Homeowner was alone and began to boil some water when the flames acted erratically and began to grow out of control and engulfed him.
- Fire traveled to attic causing additional damage.
- Arson investigators interviewed the witness and determined that it was an appliance issue.
- No gas odor detected by resident
- Rain continuing

- February 23, 2018 – Day 3
- House 3534 has an incident at 6:38 a.m., with a fatality and 3 injured, 1 released
- Lived in home one month after full renovation. Including new gas and sewer service lines to alley.
- Homeowner heard a loud pop in kitchen around 11 p.m. but found no source.
- No gas smell prior to explosion
- TX-RRC, NTSB and PHMSA launched to investigate.



Leak surveys were performed after each explosion, with RMLD and CGI.



Pressure testing of mains and services with air will establish the integrity of the distribution piping, or not. Also, customer piping is often tested, but piping can be damaged during fires and explosions.

- Develop a pressure test protocol
 - Where to cut and cap main and services
 - Maximum test pressure and duration
 - If a leak is identified, then flow test to determine the size of the failure(s)
 - Large sections that fail test will need to be broken up



Mains and services capped and ready for pressure testing.





Leaks at service tee and stopcock. Some leaks will cause test pressure failures but are not hazardous. The flow rate will be inadequate to migrate any distance. Flow rate testing pipelines that fail pressure tests should be performed prior to exposing buried leaks.




During excavation pay close attention to what is being dug up. Evidence can be anywhere. Sand bedding for sewer line was conduit for gas migration. Test and document to confirm theory. CGI shows 35% LEL, 9 days after the gas was shut-off.



Evidence can be anywhere. Soil will discolor from the release of natural gas, dry out and scrub odorant. A dated coke bottle found next to main failure. Date corresponds to sewer installation.




Source of the gas was identified at a location where a sewer main was installed in 1995, with only 2-inches of clearance. The line was dented and gouged with excavation equipment and failed 23 years later as a circumferential crack.



Overview of gas main and service in alley between Espanola and Durango Updated March 7, 2018

Document the details as it paints a picture. 664 feet of pipe tested with multiple leaks identified. Only one was large enough to result in the migration.



- Green main segments passed pressure test
- Red main segment has not held pressure.
- Blue - Customer Owned services
- Yellow—not pressure tested and cut out

4 pieces of evidence collected on 2/26/18:
 Main/ tap and service to 3531 Durango;
 Leaking Main/tap and Service to 3524 Espanola;
 36" of main between both services.

2 pieces of evidence collected on 3/5/18:
 Segment of Main:
 (1) Between 3539 & 3535 Durango
 (1) Between 3539 Durango & 3534 Espanola

11 pieces of evidence collected on 3/5/18:
 3534 Espanola Service Line
 3534 Espanola Segment E3
 3534 Espanola Segment W4
 3534 Espanola Segment W5
 3534 Espanola Riser
 3534 Espanola ABN Service South
 3534 Espanola ABN Service North
 3539 Durango Segment 1 (failed piping)
 3539 Durango Segment 3
 3539 Durango Segment 4
 3539 Durango Segment 2

Be safe while working, What is wrong with this picture. A pressure test cap will be welded on for pressure testing in a few minutes. A compression coupling can be seen by support block.





Questions



NPIC Hotline (888) 719-9033

PHMSAAccidentInvestigationDivision@dot.gov

PHMSAAID@dot.gov

Darren.Lemmerman@dot.gov

(816) 807-2606

