

Ferebee Service Hill City South Dakota




Table of Contents

- Description of Service
- Area Map w/Cable Route
- Trouble Ticket Details 2013, 2014, 2015 & 2016
- Electrical Influences
- 2014 Lightning Remediation



Customer Service Description

Circuit Number: 6055742637

Product Family: RES PRIMARY

CLLI Code: HLCYSDCO

Customer Address: 11495 GILLETTE PRAIRIE RD

MAPQUEST HILL CITY, SD 57745-6512


GIS Cordinates: 44.004104 -103.790364

Billing Name: GEORGE FEREBEE

- The Ferebee's are served digital carrier system which is 77,980 feet or 14.76 miles from the Hill City Central Office located at 205 Walnut St.
- There are four carrier systems on this cable route serving 241 customers today.



Cable Route / Map





5 Trouble Tickets Total

- 2 No Trouble Found
- 2 Electronics
- 1 Cable Repaired

Report Date & Time	Commitment Date	Ticket Closed	Repair Notes
Friday July 20, 2013 - 12:10PM	7/22/2013	7/22/2013 - 12:50PM	Found OK - Suspect Cable Plant
Tuesday October 1, 2013 - 10:06AM	10/1/2013	10/1/2013 - 1:40PM	Replaced Digital Channel Card
Wednesday October 2, 2013 - 10:38AM	10/2/2013	10/2/2013 - 3:50PM	Replaced Digital Channel Card
Monday October 21, 2013 - 12:53PM	10/21/2013	10/21/2013 - 12:54PM	FE Closed Ticket - No Dispatch
Saturday December 7, 2013 - 8:40PM	12/9/2013	12/9/2013 - 4:20PM	Cable Trouble - Repaired



9 Trouble Tickets

- 3 No Trouble Found
- 2 Cable Issue
- 3 Lightning
- 1 Customer Issue

Report Date & Time	Commitment Date	Ticket Closed	Repair Notes
Monday January 20, 2014 - 8:12AM	1/21/2014	1/21/2014 - 4:20PM	Found OK - Supected Cable Plant
Sunday January 26, 2014 - 5:11PM	1/28/2014	1/28/2014 - 4:04PM	Repaired Ground in Go-Digital Control Pair
Wednesday February 5, 2014 - 7:47AM	2/5/2014	2/5/2014 - 4:25PM	Customer's Inside Wiring - Repaired (Rodents)
Saturday June 14, 2014 - 10:38PM	6/15/2014	6/15/2014 - 2:08AM	Line Tests OK - Left Message for Customer
Sunday June 15, 2014 - 4:01PM	6/17/2014	6/17/2014 - 1:05PM	Good To Home - Intermittent / Came Clear
Thursday June 26, 2014 - 10:22PM	6/27/2014	6/27/2014 - 2:26PM	Lightning Crashed Go Digital
Saturday June 28, 2014 - 6:34PM	7/1/2014	7/1/2014 - 12:00PM	Replaced Office Card and Fuses Remote Terminal
Saturday August 30, 2014 - 8:18PM	9/3/2014	9/3/2014 - 1:30PM	Replaced Office Card and Fuses Remote Terminal
Friday October 3, 2014 - 4:49PM	10/6/2014	10/6/2014 - 2:30PM	Grounded BSW at Terminal - fixed cable



8 Trouble Tickets

- 3 Go Digital
- 3 Cable Issues
- 2 No Problems Found

CenturyLink at no charge to the Ferebee's ran a 2nd line to their home in July and August while waiting on parts



Report Date & Time	Commitment Date	Ticket Closed	Repair Notes
Monday May 11, 2015 - 8:34AM	5/11/2015	5/11/2015 - 9:09AM	No Trouble Found
Tuesday June 9, 2015 - 10:30AM	6/10/2015	6/10/2015 - 6:19AM	Repaired F1 Cable
Thursday June 11, 2015 - 1:16PM	6/15/2015	6/19/2015 - 2:28PM	Washed Out Cable - Remote Area - No Truck Access
Friday June 26, 2015 - 10:42AM	6/26/2015	6/26/2015 - 2:46PM	
Monday June 29, 2015 - 10:02AM	7/2/2015	7/2/2015 - 2:00PM	Cable Issue BSW - Moved Cust to Different Channel
Tuesday July 14, 2015 - 12:25PM	7/17/2015	7/17/2015 - 6:20PM	Replaced Powered Repeater
Monday July 27, 2015 - 7:25AM	7/28/2015	8/14/2015 - 5:52PM	2 Problems - 1 Add/Drop repeater at the Ferebee home and 1 after the home. Odd that a repeater after the home was causing issues - we had to order parts was the cause of the delay; all other customers working before and after the Ferebee's
Tuesday August 18th - 8:54AM	8/18/2015	0/21/13-3.2/AIVI	One of the repeaters replaced on 8/14/2015 died - replaced out of spares.



Report Date - 3/1/2016 737am


Commit Date - 3/7/2016

Ticket Closed – 3/1/2016 at 10:30am


Repairs Made – Replaced Blown Fuse in Power Cabinet
Thunderstorm



Lightning Area & Remediation Actions




Radar Coverage – Pennington County






Historic Lightning Strike Map








2005 – 2014 Lightning Strike / Stroke Map Enlarged



According to NOAA: Black Hills storms produce twice the amount of ground strikes per year compared to the surrounding region (besides Colorado).





June 26, 2014 Outage Detail - Lightning Strikes





LIAS Report ID: 439 Delivery Date: 25 Apr 201

USPLN LIAS - Lightning Incident Archival Search Report

The United States Precision Lightning Network has provided the following lightning stroke dete information for the LIAS report.

LIAS Summary

Customer Information

Kevin Ancell

kevin.ancell@centurylink.com

Search Parameters

Time: 06/25/2014, 00:00:00 to 06/28/2014, 00:00:00

Time Zone: Mountain

Coords: 43.97098 lat, -103.75970 lon


Address: 11495 Gillette Prairie Road, Hill City SD 57745

Results

690 cloud-to-ground events were detected by the USPLN

Please viait our FAQ for answers to frequently asked questions. If you require further assistance, please contact the USPLN at www.uspin.com/contact.html or call 978-963-664

LIAS Stroke Map



13
Copyright (g) TO Systems. Inc. 2015. All rights reserved. USPLN and United States Precision Lightning Network are trademarks of TOA Systems. This report is intended for the sole use customet(s) named feeten, Report may not be copied, modified or distributed in part or he entirely willout the express written consent of TOA see with. Disappsiams. Comfega. Item for full indicatement in effects.

TOA

LISPLN

LIAS Report ID: 439 Delivery Date: 25 Apr 2016

IAS	Ev	ent	Tin	neline	•						
	- 1º	6.3 kA									
	Kagnitude						h			Ŧ	
							#				
	Stroke										
	1									1	
	06/25/2014 00:00-	07:12	14:24-	21:36-	94:48	12:00	19:12-	02:24-	-9:36-	16:48-	00:00
	72014	06/25/2014 07:12	06/25/2014 14:24	06/25/2014 21:36-	06/26/2014 04:48	06/26/2014 12:00-	06/26/2014 19:12	06/27/2014	06/27/2014 09:36-	06/27/2014	06/28/2014 00:00-
		10	IC.	10	90	90	9	12	12	12	28
	06/25,	2/90	06/2	2/90	2/90	2/9	2/90	/90	/90	/90	2/90

LIAS	Result	Paramete	rs			
LIAS	Stroke	Data				
Date	Time	<u>Latitude</u>	Longitude	Amplitude(kA)	Distance(Miles)	
06/25/2014	03:16:10	43.82631	-103.80508	-7.8	10.3	
06/25/2014	03:16:10	43.82037	-103.82482	-13.0	10.9	
06/25/2014	03:29:02	43.79428	-103.75191	-23.9	12.3	
06/25/2014	03:29:17	43.77084	-103.81628	-35.1	14.2	
06/25/2014	03:31:37	43.76030	-103.76224	-8.8	14.6	
06/25/2014	03:37:04	43.78205	-103.79595	-26.1	13.2	
06/25/2014	03:38:54	43.79919	-103.75630	-9.0	11.9	
06/25/2014	03:38:54	43.80377	-103.77942	-14.0	11.6	
06/25/2014	03:54:19	43.82013	-103.73507	-26.8	10.5	
06/25/2014	03:54:19	43.83104	-103.73039	-19.4	9.8	
06/25/2014	03:55:15	43.82266	-103.72807	-18.6	10.4	
06/25/2014	03:56:34	43.83145	-103.71702	-25.5	9.9	
06/25/2014	04:11:58	43.88653	-103.71441	-23.6	6.3	
06/26/2014	18:59:01	44.11700	-103.97393	54.1	14.7	
06/26/2014	19:00:49	43.95338	-104.04853	-7.0	14.5	
06/26/2014	19:01:48	43.98603	-104.04940	34.6	14.5	
06/26/2014	19:01:51	43.90253	-104.02841	-9.3	14.2	
06/26/2014	19:02:54	43.96070	-104.04786	-7.6	14.4	
06/26/2014	19:03:35	44.08091	-104.01346	-7.2	14.8	
06/26/2014	19:03:44	43.85334	-104.00189	-9.3	14.6	

Copyright (c) TOA Systems, Inc. 2015. All rights reserved. USPLN and United States Precision Lighting Network are trademarks of TOA Systems. This report is intended for the sole use of the custometris) named herein. Report may not be copied, modified or distributed in part or its entirety without the express written consent of TOA see www.foesystems.com/legal.html for full warranty declarance is included.

Grounding Study

Problem Description

- The customer: George Ferebee of Hill City, SD has reported frequent loss of voice service during severe weather. Mr. Ferebee is served by a Go-Digital pair gain system. The Go-Digital pair gain system is an electronic system that provides multiple voice circuits from a limited number of copper lines. One factor that contributes to the loss of voice service over digital systems is a failure to dissipate voltage caused by lightning strikes.
- To address the issues raised by Mr. Ferebee, CenturyLink sent Curt Erickson a bonding and grounding subject matter expert to test the ground field within the field and the Central Office.

Field Testing

• During the audit, Ohm readings were taken at each repeater site. During testing the repeater ground is disconnected to test the ground field.

RESULTS NEXT PAGE



Grounding Study Results

The results from each of the 6 sites are as follows:

- RPTR #1 = 70 Ohms.
- RPTR #2 = 44 Ohms.
- RPTR #3 = 81 Ohms Total Bar with AC power connected 13 Ohms.
- RPTR #4 = 60 Ohms.
- RPRT #5 = 69 Ohms.
- RPTR #6 = Gate Locked and Chained, No Trespassing Signs.
- Ground reading should be under 25 Ohms. In each of these sites, the ground reading is significantly higher than specifications. Proper grounding allows high voltage impacts (lighting) a path to discharge to the ground field and a path back to CenturyLink's electronic equipment.

Central Office (CO) Testing

 Examine ground bar connectivity within the CO to ensure stray voltage was not being introduced into the CO. During the audit, it was discovered that additional grounding was necessary between the cable entrance ground and the main CO Ground Bar.



Grounding Recommendations

Field Recommendation

Due to the area's rocky soil and high elevation, a traditional ground field may not be
effective enough at power dissipation. To mitigate this geographic nuance, the
ground field should consist of a 40 foot linear trench 40" deep. Using LOW OHMS
CONCRETE (6 bags per Reaper) and # 2 solid tined copper conductor. The Low
Ohm concrete should provide a more robust ground field at each repeater and
reduce the Ohm reading closer to the standard of <25 Ohms. Once the ground field
updates are complete, employ the High Voltage Protection plan for Go-Digital
utilized to resolve a similar issue in New Mexico.

Central Office (CO)

 In the Central Office a new 2/0 ground cable should be placed from the Cable Entrance Ground Bar to the OPGP Bar (Central Office Ground Bar). This path allows any current fowling on the cable sheath to go directly out of the central office to the ground field or the main ground natural of the power CO.

Conclusion

While these solutions do not address all the past trouble issues encountered by Mr.
Ferebee, they should significantly improve the reliability of the Go-Digital system that
currently serves Mr. Ferebee.

Hours and Investments

- Technician Hours 178
- Technician Expense = \$15,130
- Grounding Remediation 40ft trench, 40 inches deep, 18 inches wide, with 8 inches of Low Ohm Concrete in the bottom of the trench and a #2 solid copper tinned wire placed in the center of the low ohm concrete mix

Date	CMS#	Description		Invoice
12/9/2014	14279284	George Ferebee's Terminal – Grounding	\$	2,101.00
12/9/2014	14279303	Castle Creek Road – Grounding	\$	2,209.17
12/9/2014	14279315	East Slate Road – Grounding	\$	2,149.98
12/9/2014	14279320	Williams Draw – Grounding	\$	2,028.55
12/9/2014	14279326	12180 Deerfield Road (Wilsons) – Grounding	\$	2,120.39
12/9/2014	14279336	Ground Enhancing Material	\$	4,415.27
6/26/2015	15136679	Gillette Prairie Forestry Road (Ped Washed in Creek)	\$	232.00
Noise/Powe		pecialist @\$550.00/day 8 days	\$	4,400.00
	Total For	Grounding and Pedestal Washout	• \$	19,656.36
			Ce	enturyLin