

Aeronautical Study No. 2018-WTE-3877-OE Prior Study No. 2018-WTE-3740-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine 18-S-0841.010 T1

Location: Avon, SD

Latitude: 43-07-43.00N NAD 83

Longitude: 98-03-53.42W

Heights: 1870 feet site elevation (SE)

590 feet above ground level (AGL) 2460 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3877-OE.

Signature Control No: 362641194-408981103

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3877-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T2

Location: Avon, SD

Latitude: 43-07-58.76N NAD 83

Longitude: 98-03-27.25W

Heights: 1802 feet site elevation (SE)

590 feet above ground level (AGL) 2392 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3741-OE.

Signature Control No: 362188459-408981020

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3741-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T3

Location: Avon, SD

Latitude: 43-07-48.87N NAD 83

Longitude: 98-04-31.54W

Heights: 1810 feet site elevation (SE)

590 feet above ground level (AGL) 2400 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3742-OE.

Signature Control No: 362188460-408981018

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3742-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T4

Location: Avon, SD

Latitude: 43-08-11.75N NAD 83

Longitude: 98-02-45.89W

Heights: 1752 feet site elevation (SE)

590 feet above ground level (AGL) 2342 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3743-OE.

Signature Control No: 362188461-408981017

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3743-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T5

Location: Avon, SD

Latitude: 43-07-06.92N NAD 83

Longitude: 98-04-26.73W

Heights: 1781 feet site elevation (SE)

590 feet above ground level (AGL) 2371 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3744-OE.

Signature Control No: 362188462-408981019

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3744-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T6

Location: Avon, SD

Latitude: 43-08-04.96N NAD 83

Longitude: 98-03-09.02W

Heights: 1770 feet site elevation (SE)

590 feet above ground level (AGL) 2360 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3745-OE.

Signature Control No: 362188463-408981021

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3745-OE



Aeronautical Study No. 2018-WTE-3878-OE Prior Study No. 2018-WTE-3746-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T7

Location: Avon, SD

Latitude: 43-07-08.43N NAD 83

Longitude: 98-05-07.44W

Heights: 1764 feet site elevation (SE)

590 feet above ground level (AGL) 2354 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3878-OE.

Signature Control No: 362641195-408981104

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3878-OE



Aeronautical Study No. 2019-WTE-3767-OE Prior Study No. 2018-WTE-3747-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine 8

Location: Avon, SD

Latitude: 43-07-49.70N NAD 83

Longitude: 98-07-14.76W

Heights: 1771 feet site elevation (SE)

590 feet above ground level (AGL) 2361 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2019-WTE-3767-OE.

Signature Control No: 402994547-408981110

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2019-WTE-3767-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T9

Location: Avon, SD

Latitude: 43-07-21.11N NAD 83

Longitude: 98-06-45.67W

Heights: 1766 feet site elevation (SE)

590 feet above ground level (AGL) 2356 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3748-OE.

Signature Control No: 362188466-408981014

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3748-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T10

Location: Avon, SD

Latitude: 43-04-42.51N NAD 83

Longitude: 98-03-18.11W

Heights: 1740 feet site elevation (SE)

590 feet above ground level (AGL) 2330 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3749-OE.

Signature Control No: 362188467-408981015

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3749-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T11

Location: Avon, SD

Latitude: 43-04-12.67N NAD 83

Longitude: 98-03-15.38W

Heights: 1742 feet site elevation (SE)

590 feet above ground level (AGL) 2332 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.


This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3750-OE.

Signature Control No: 362188468-408981022 (MAL -WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3750-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T12

Location: Avon, SD

Latitude: 43-07-17.66N NAD 83

Longitude: 98-05-46.46W

Heights: 1740 feet site elevation (SE)

590 feet above ground level (AGL) 2330 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3751-OE.

Signature Control No: 362188469-408981031

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3751-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T13

Location: Avon, SD

Latitude: 43-08-32.31N NAD 83

Longitude: 98-01-30.53W

Heights: 1733 feet site elevation (SE)

590 feet above ground level (AGL) 2323 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3752-OE.

Signature Control No: 362188470-408981016

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3752-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T14

Location: Avon, SD

Latitude: 43-03-20.39N NAD 83

Longitude: 98-03-24.67W

Heights: 1700 feet site elevation (SE)

590 feet above ground level (AGL) 2290 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3753-OE.

Signature Control No: 362188471-408981025

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3753-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T15

Location: Avon, SD

Latitude: 43-07-06.59N NAD 83

Longitude: 98-07-28.38W

Heights: 1758 feet site elevation (SE)

590 feet above ground level (AGL) 2348 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3754-OE.

Signature Control No: 362188472-408981027 (MAL -WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3754-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T16

Location: Avon, SD

Latitude: 43-07-26.64N NAD 83

Longitude: 98-07-53.76W

Heights: 1764 feet site elevation (SE)

590 feet above ground level (AGL) 2354 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3755-OE.

Signature Control No: 362188473-408981034

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3755-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T17

Location: Avon, SD

Latitude: 43-06-32.78N NAD 83

Longitude: 98-05-05.84W

Heights: 1719 feet site elevation (SE)

590 feet above ground level (AGL) 2309 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3756-OE.

Signature Control No: 362188474-408981028

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3756-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T18

Location: Avon, SD

Latitude: 43-09-23.74N NAD 83

Longitude: 98-01-22.94W

Heights: 1714 feet site elevation (SE)

590 feet above ground level (AGL) 2304 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3757-OE.

Signature Control No: 362188475-408981023

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3757-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T20

Location: Avon, SD

Latitude: 43-09-39.37N NAD 83

Longitude: 98-01-11.93W

Heights: 1712 feet site elevation (SE)

590 feet above ground level (AGL) 2302 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3759-OE.

Signature Control No: 362188477-408981029

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3759-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T21

Location: Avon, SD

Latitude: 43-07-55.31N NAD 83

Longitude: 98-01-00.99W

Heights: 1694 feet site elevation (SE)

590 feet above ground level (AGL) 2284 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3760-OE.

Signature Control No: 362188478-408981030

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3760-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T22

Location: Avon, SD

Latitude: 43-06-53.89N NAD 83

Longitude: 98-07-51.54W

Heights: 1737 feet site elevation (SE)

590 feet above ground level (AGL) 2327 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3761-OE.

(MAL-WT)

Signature Control No: 362188479-408981032

Lan Norris Specialist

Additional information for ASN 2018-WTE-3761-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T23

Location: Avon, SD

Latitude: 43-06-33.86N NAD 83

Longitude: 98-08-07.93W

Heights: 1734 feet site elevation (SE)

590 feet above ground level (AGL) 2324 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3762-OE.

Signature Control No: 362188480-408981024

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3762-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T24

Location: Avon, SD

Latitude: 43-05-05.92N NAD 83

Longitude: 98-05-33.47W

Heights: 1687 feet site elevation (SE)

590 feet above ground level (AGL) 2277 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3763-OE.

Signature Control No: 362188481-408981037

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3763-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T25

Location: Avon, SD

Latitude: 43-10-13.48N NAD 83

Longitude: 98-00-49.28W

Heights: 1698 feet site elevation (SE)

590 feet above ground level (AGL) 2288 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3764-OE.

Signature Control No: 362188482-408981038

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3764-OE



Aeronautical Study No. 2018-WTE-3879-OE Prior Study No. 2018-WTE-3765-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T26

Location: Avon, SD

Latitude: 43-08-44.66N NAD 83

Longitude: 98-09-04.10W

Heights: 1694 feet site elevation (SE)

590 feet above ground level (AGL) 2284 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3879-OE.

Signature Control No: 362641196-408981105

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3879-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T27

Location: Avon, SD

Latitude: 43-03-36.94N NAD 83

Longitude: 98-01-08.21W

Heights: 1671 feet site elevation (SE)

590 feet above ground level (AGL) 2261 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3766-OE.

Signature Control No: 362188484-408981039

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3766-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T29

Location: Avon, SD

Latitude: 43-06-30.21N NAD 83

Longitude: 98-05-42.07W

Heights: 1720 feet site elevation (SE)

590 feet above ground level (AGL) 2310 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3768-OE.

Signature Control No: 362188486-408981041

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3768-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T30

Location: Avon, SD

Latitude: 43-10-50.68N NAD 83

Longitude: 98-00-48.69W

Heights: 1693 feet site elevation (SE)

590 feet above ground level (AGL) 2283 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3769-OE.

(MAL-WT)

Signature Control No: 362188487-408981042

Lan Norris Specialist

Additional information for ASN 2018-WTE-3769-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T31

Location: Avon, SD

Latitude: 43-03-48.74N NAD 83

Longitude: 98-02-23.73W

Heights: 1688 feet site elevation (SE)

590 feet above ground level (AGL) 2278 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3770-OE.

Signature Control No: 362188488-408981045

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3770-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T32

Location: Avon, SD

Latitude: 43-08-00.76N NAD 83

Longitude: 98-09-02.57W

Heights: 1703 feet site elevation (SE)

590 feet above ground level (AGL) 2293 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3771-OE.

Signature Control No: 362188489-408981046

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3771-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T33

Location: Avon, SD

Latitude: 43-07-38.67N NAD 83

Longitude: 98-00-23.59W

Heights: 1664 feet site elevation (SE)

590 feet above ground level (AGL) 2254 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3772-OE.

Signature Control No: 362188490-408981048

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3772-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T34

Location: Avon, SD

Latitude: 43-03-38.63N NAD 83

Longitude: 98-02-44.03W

Heights: 1675 feet site elevation (SE)

590 feet above ground level (AGL) 2265 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3773-OE.

Signature Control No: 362188491-408981049

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3773-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T35

Location: Avon, SD

Latitude: 43-04-19.90N NAD 83

Longitude: 98-00-24.46W

Heights: 1664 feet site elevation (SE)

590 feet above ground level (AGL) 2254 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.


This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3774-OE.

Signature Control No: 362188492-408981062 (MAL -WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3774-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T36

Location: Avon, SD

Latitude: 43-08-52.87N NAD 83

Longitude: 98-00-46.64W

Heights: 1695 feet site elevation (SE)

590 feet above ground level (AGL) 2285 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3775-OE.

Signature Control No: 362188493-408981063

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3775-OE



Aeronautical Study No. 2018-WTE-3880-OE Prior Study No. 2018-WTE-3776-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T37

Location: Avon, SD

Latitude: 43-05-42.15N NAD 83

Longitude: 98-06-38.22W

Heights: 1662 feet site elevation (SE)

590 feet above ground level (AGL) 2252 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3880-OE.

Signature Control No: 362641197-408981106

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3880-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T38

Location: Avon, SD

Latitude: 43-02-03.79N NAD 83

Longitude: 98-02-32.41W

Heights: 1626 feet site elevation (SE)

590 feet above ground level (AGL) 2216 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3777-OE.

Signature Control No: 362188495-408981064

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3777-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T39

Location: Avon, SD

Latitude: 43-05-41.48N NAD 83

Longitude: 98-07-29.56W

Heights: 1720 feet site elevation (SE)

590 feet above ground level (AGL) 2310 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3778-OE.

Signature Control No: 362188496-408981066

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3778-OE



Aeronautical Study No. 2018-WTE-3881-OE Prior Study No. 2018-WTE-3779-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T40

Location: Avon, SD

Latitude: 43-07-53.82N NAD 83

Longitude: 98-09-19.62W

Heights: 1684 feet site elevation (SE)

590 feet above ground level (AGL) 2274 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3881-OE.

Signature Control No: 362641198-408981107

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3881-OE



Aeronautical Study No. 2018-WTE-3882-OE Prior Study No. 2018-WTE-3780-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T41

Location: Avon, SD

Latitude: 43-04-45.96N NAD 83

Longitude: 98-07-00.47W

Heights: 1690 feet site elevation (SE)

590 feet above ground level (AGL) 2280 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3882-OE.

Signature Control No: 362641199-408981108

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3882-OE



Aeronautical Study No. 2019-WTE-3768-OE Prior Study No. 2018-WTE-3781-OE

Issued Date: 06/19/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine 42

Location: Avon, SD

Latitude: 43-02-52.29N NAD 83

Longitude: 98-01-13.98W

Heights: 1643 feet site elevation (SE)

590 feet above ground level (AGL) 2233 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2019-WTE-3768-OE.

Signature Control No: 402994548-408981111

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2019-WTE-3768-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T43

Location: Avon, SD

Latitude: 43-02-28.90N NAD 83

Longitude: 98-01-57.86W

Heights: 1626 feet site elevation (SE)

590 feet above ground level (AGL) 2216 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3782-OE.

Signature Control No: 362188500-408981067

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3782-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T44

Location: Avon, SD

Latitude: 43-02-42.79N NAD 83

Longitude: 98-01-36.97W

Heights: 1642 feet site elevation (SE)

590 feet above ground level (AGL) 2232 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3783-OE.

Signature Control No: 362188501-408981069

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3783-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T45

Location: Avon, SD

Latitude: 43-04-20.54N NAD 83

Longitude: 98-06-52.86W

Heights: 1690 feet site elevation (SE)

590 feet above ground level (AGL) 2280 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3784-OE.

Signature Control No: 362188502-408981070

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3784-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T46

Location: Avon, SD

Latitude: 43-09-22.15N NAD 83

Longitude: 98-00-03.58W

Heights: 1652 feet site elevation (SE)

590 feet above ground level (AGL) 2242 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3785-OE.

Signature Control No: 362188503-408981071

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3785-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T47

Location: Avon, SD

Latitude: 43-09-41.91N NAD 83

Longitude: 97-59-41.21W

Heights: 1632 feet site elevation (SE)

590 feet above ground level (AGL) 2222 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3786-OE.

Signature Control No: 362188504-408981072

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3786-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T48

Location: Avon, SD

Latitude: 43-06-47.24N NAD 83

Longitude: 98-09-16.57W

Heights: 1674 feet site elevation (SE)

590 feet above ground level (AGL) 2264 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3787-OE.

Signature Control No: 362188505-408981073

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3787-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T49

Location: Avon, SD

Latitude: 43-05-12.57N NAD 83

Longitude: 98-08-02.41W

Heights: 1688 feet site elevation (SE)

590 feet above ground level (AGL) 2278 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3788-OE.

Signature Control No: 362188506-408981078

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3788-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T50

Location: Avon, SD

Latitude: 43-08-56.90N NAD 83

Longitude: 98-00-24.45W

Heights: 1662 feet site elevation (SE)

590 feet above ground level (AGL) 2252 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3789-OE.

Signature Control No: 362188507-408981080

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3789-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T51

Location: Avon, SD

Latitude: 43-10-19.52N NAD 83

Longitude: 98-00-15.14W

Heights: 1661 feet site elevation (SE)

590 feet above ground level (AGL) 2251 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3790-OE.

Signature Control No: 362188508-408981081

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3790-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T52

Location: Avon, SD

Latitude: 43-03-43.44N NAD 83

Longitude: 98-00-10.00W

Heights: 1622 feet site elevation (SE)

590 feet above ground level (AGL) 2212 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3791-OE.

Signature Control No: 362188509-408981082

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3791-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T53

Location: Avon, SD

Latitude: 43-03-54.46N NAD 83

Longitude: 97-59-47.05W

Heights: 1625 feet site elevation (SE)

590 feet above ground level (AGL) 2215 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3792-OE.

Signature Control No: 362188510-408981083

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3792-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T54

Location: Avon, SD

Latitude: 43-07-59.08N NAD 83

Longitude: 98-00-16.05W

Heights: 1653 feet site elevation (SE)

590 feet above ground level (AGL) 2243 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3793-OE.

Signature Control No: 362188511-408981085

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3793-OE



Issued Date: 12/04/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION ** (REVISED)

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T55

Location: Avon, SD

Latitude: 43-11-20.13N NAD 83

Longitude: 98-00-23.54W

Heights: 1645 feet site elevation (SE)

590 feet above ground level (AGL) 2235 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

Action will be taken to ensure aeronautical charts and records are updated to reflect the marking/lighting changes which exist at this time.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3794-OE.

Signature Control No: 362188512-424377998

(MAL-WT)


Lan Norris Specialist

Additional information for ASN 2018-WTE-3794-OE

Our review of your request to utilize an Aircraft Detection Lighting System to operate the lights for this wind farm was conducted without regard to whether the final lighting plan approved includes lighting this turbine. Unless changed or amended, this determination, as it applies to the use of this type system, is valid for this turbine whether it requires a light now or at some point in the future.

NOTE: The sponsor is responsible for ensuring the ADLS provides complete detection for aircraft that enter a three-dimensional volume of airspace, or coverage area, around the obstruction(s). In accordance with AC 70/7460-1L, Change 2, Chapter 14.2.1, the aircraft vertical detection coverage extends from the ground to 1000 feet above the highest part of the obstruction(s) and within a 3 NM perimeter of the obstruction(s). To ensure adequate aircraft detection, lights that are not controlled by the ADLS may be required for areas where the 3 NM perimeter is not achievable.





Issued Date: 12/04/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION ** (REVISED)

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T56

Location: Avon, SD

Latitude: 43-11-05.17N NAD 83

Longitude: 98-00-29.23W

Heights: 1656 feet site elevation (SE)

590 feet above ground level (AGL) 2246 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

Action will be taken to ensure aeronautical charts and records are updated to reflect the marking/lighting changes which exist at this time.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3795-OE.

Signature Control No: 362188513-424377999

(MAL-WT)

Lan Norris Specialist


Additional information for ASN 2018-WTE-3795-OE

Our review of your request to utilize an Aircraft Detection Lighting System to operate the lights for this wind farm was conducted without regard to whether the final lighting plan approved includes lighting this turbine. Unless changed or amended, this determination, as it applies to the use of this type system, is valid for this turbine whether it requires a light now or at some point in the future.

NOTE: The sponsor is responsible for ensuring the ADLS provides complete detection for aircraft that enter a three-dimensional volume of airspace, or coverage area, around the obstruction(s). In accordance with AC 70/7460-1L, Change 2, Chapter 14.2.1, the aircraft vertical detection coverage extends from the ground to 1000 feet above the highest part of the obstruction(s) and within a 3 NM perimeter of the obstruction(s). To ensure adequate aircraft detection, lights that are not controlled by the ADLS may be required for areas where the 3 NM perimeter is not achievable.

Sectional Map for ASN 2018-WTE-3795-OE





Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T57

Location: Avon, SD

Latitude: 43-06-57.58N NAD 83

Longitude: 98-09-03.58W

Heights: 1680 feet site elevation (SE)

590 feet above ground level (AGL) 2270 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3796-OE.

Signature Control No: 362188514-408981086

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3796-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T58

Location: Avon, SD

Latitude: 43-05-28.29N NAD 83

Longitude: 98-07-49.97W

Heights: 1701 feet site elevation (SE)

590 feet above ground level (AGL) 2291 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3797-OE.

Signature Control No: 362188515-408981087

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3797-OE



Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Wind Turbine T60

Location: Avon, SD

Latitude: 43-03-46.00N NAD 83

Longitude: 98-07-20.42W

Heights: 1664 feet site elevation (SE)

590 feet above ground level (AGL) 2254 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, white paint/synchronized red lights - Chapters 4,12&13(Turbines).

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.


If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-3799-OE.

Signature Control No: 362188517-408981088

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-3799-OE



Issued Date: 08/22/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Lighting Study for Met Tower ADLS Tower (PW 18-S-0841.010)

Location: Avon, SD

Latitude: 43-05-46.28N NAD 83

Longitude: 98-04-03.13W

Heights: 1711 feet site elevation (SE)

152 feet above ground level (AGL) 1863 feet above mean sea level (AMSL)

Based on this evaluation, marking and lighting are not necessary for aviation safety. However, if marking/lighting are accomplished on a voluntary basis, we recommend it be installed in accordance with FAA Advisory Circular 70/7460-1 L Change 2.

Action will be taken to ensure aeronautical charts and records are updated to reflect the marking/lighting changes which exist at this time.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

In order to ensure proper conspicuity of turbines at night during construction, all turbines should be lit with temporary lighting once they reach a height of 200 feet or greater until such time the permanent lighting configuration is turned on. As the height of the structure continues to increase, the temporary lighting should be relocated to the uppermost part of the structure. The temporary lighting may be turned off for periods when they would interfere with construction personnel. If practical, permanent obstruction lights should be installed and operated at each level as construction progresses. An FAA Type L-810 steady red light fixture shall be used to light the structure during the construction phase. If power is not available, turbines shall be lit with self-contained, solar powered LED steady red light fixture that meets the photometric requirements of an FAA Type L-810 lighting system. The lights should be positioned to ensure that a pilot has an unobstructed view of at least

one light at each level. The use of a NOTAM (D) to not light turbines within a project until the entire project has been completed is prohibited.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2019-WTE-7493-OE.

Signature Control No: 415031787-415065886

(MAL-WT)

Lan Norris Specialist

Attachment(s) Additional Information Map(s)

cc: FCC

Additional information for ASN 2019-WTE-7493-OE

Marking and lighting for this structure will not be necessary for aviation safety so as long as the adjacent structures in close proximity exist. If at any point in the future, the adjacent structures are relocated, dismantled or abandoned, marking of this structure will be immediately required. The proponent for this study is responsible for monitoring the situation. In the event where marking would be required, the proponent will promptly initiate a marking and lighting study by E-filing FAA form 7460-1, "Notice of Proposed Construction or Alteration" at the FAA public website https://oeaaa.faa.gov.

In the interest of aviation safety, the FAA recommends voluntarily marking of METs less than 200 feet (61 m) AGL in accordance with AC 70/7460-1L, Change 2, as follows:

Painting.

The meteorological evaluation tower (MET) should be painted in accordance with the criteria contained in Chapter 3, paragraphs 3.1 through 3.4, specifically, with alternate bands of aviation orange and white paint. In addition, paragraph 3.5 states that all markings should be replaced when faded or otherwise deteriorated.

High-Visibility Sleeves.


It is recommended that several high-visibility sleeves be installed on the MET's outer guy wires. One high-visibility sleeve should be installed on each guy wire, as close to the anchor point as possible, but at a height well above the crop or vegetation canopy. A second sleeve should be installed on the same outer guy wires midway between the location of the lower sleeve and the upper attachment point of the guy wire to the MET. The use of sleeves should not impact the placement of spherical marker balls.

Spherical Markers.

It is also recommended that high-visibility aviation orange spherical marker (or cable) balls be attached to the guy wires. The FAA recommends a total of 8 high visibility spherical marker (or cable balls) of aviation orange color attached to the guy wires; 4 marker balls should be attached to guy wires at the top of the tower no further than 15 feet from the top wire connection to the tower, and 4 marker balls at or below the mid point of the structure on the outer guy wires.

The FAA recognizes that various weather conditions and manufacturing placement standards may affect the placement and use of high-visibility sleeves and/or spherical markers. Thus, some flexibility is allowed when determining sleeve length and marker placement on METs.

Sectional Map for ASN 2019-WTE-7493-OE





Issued Date: 06/20/2019

Peter Pawlowski S Power 2180 South 1300 East Salt Lake City, UT 84106

** MARKING & LIGHTING RECOMMENDATION **

The Federal Aviation Administration has completed an evaluation of your request concerning:

Structure: Met Tower (w/WT Farm) PM3

Location: Avon, SD

Latitude: 43-07-55.86N NAD 83

Longitude: 98-03-14.25W

Heights: 1780 feet site elevation (SE)

377 feet above ground level (AGL) 2157 feet above mean sea level (AMSL)

Based on this evaluation, we have no objection to the change provided the structure is marked/lighted in accordance with FAA Advisory Circular 70/7460-1, L Change 2, Obstruction Marking and Lighting, paint/red lights - Chapters 3(Marked),4,5(Red),&12.

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

So that aeronautical charts and records can be updated, it is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed when the new system is installed and operational.

Your request for consideration to utilize an Aircraft Detection Lighting System to operate the recommended lighting is approved. See attached for additional condition(s) or information.

Obstruction marking and lighting recommendations for wind turbine farms are based on the scheme for the entire project. ANY change to the height, location or number of turbines within this project will require a reanalysis of the marking and lighting recommendation for the entire project. In particular, the removal of previously planned or built turbines/turbine locations from the project will often result in a change in the marking/lighting recommendation for other turbines within the project. It is the proponent's responsibility to contact the FAA to discuss the process for developing a revised obstruction marking and lighting plan should this occur.

This evaluation concerns the effect of the marking/lighting changes on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

If we can be of further assistance, please contact our office at (404) 305-6645, or Lan.norris@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2018-WTE-11552-OE.

Signature Control No: 391210997-409148210

(MAL-WT)

Lan Norris Specialist

Additional information for ASN 2018-WTE-11552-OE

As a condition of this marking and lighting letter, the sponsor certifies that the proposed ADLS for the project will be continuously monitored in accordance with the current version of AC 70/7460-1 Obstruction Marking and Lighting, and the Technical Note issued for the system. The sponsor will insure this responsibility is specifically transferred to any subsequent owners of the project.

As a condition to this Determination, the structure should be lighted with red obstruction lights and marked as noted below:

Painting.

The meteorological evaluation tower (MET) should be painted in accordance with the criteria contained in Chapter 3, paragraphs 3.1 through 3.4, specifically, with alternate bands of aviation orange and white paint. In addition, paragraph 3.5 states that all markings should be replaced when faded or otherwise deteriorated.

High-Visibility Sleeves.

It is recommended that several high-visibility sleeves be installed on the MET's outer guy wires. One high-visibility sleeve should be installed on each guy wire, as close to the anchor point as possible, but at a height well above the crop or vegetation canopy. A second sleeve should be installed on the same outer guy wires midway between the location of the lower sleeve and the upper attachment point of the guy wire to the MET. The use of sleeves should not impact the placement of spherical marker balls.

Spherical Markers.

It is also recommended that high-visibility aviation orange spherical marker (or cable) balls be attached to the guy wires. The FAA recommends a total of 8 high visibility spherical marker (or cable balls) of aviation orange color attached to the guy wires; 4 marker balls should be attached to guy wires at the top of the tower no further than 15 feet from the top wire connection to the tower, and 4 marker balls at or below the mid point of the structure on the outer guy wires.

The FAA recognizes that various weather conditions and manufacturing placement standards may affect the placement and use of high-visibility sleeves and/or spherical markers. Thus, some flexibility is allowed when determining sleeve length and marker placement on METs.