

Waterbody Data Form

S500 HA007
Trib to Wolf Creek

Centerline Re-Route Access Road Ancillary Facility Transmission Line Other RV179


Centerline ID: 3/26/10 Project Designated Name: Keystone XL - Phase IV

Date: 4/2/10 Client/Project Name: TransCanada-Trow-KXL Milepost Enter/Exit: NA RV179

Team: B500 State/County: SD - Harding Quad Name: NA

Logbook No.: 1 Logbook Page No.: 11 Tract No.: ML-SD-HA-0666

Drawing (Please provide orientation arrow, all features identified, location to centerline, etc.) Photos: 001 NE, 002 NW, 003 SW



Waterbody Type: Lake Pond Borrow Pit Stream Ag. Ditch Other

Stream Flow: Fast Moderate Slow Very Slow None

Flow Type: Perennial (Flows year round) Intermittent (Flows <3 month) None
 Seasonal (Continuous flow ≥ 3 months) Ephemeral (Flows only in response to rainfall)

Direction of Flow: N NE E SE S SW W NW No Flow

OHWM Width (ft.): 6'

Sinuosity: Braided Meandering Straight N/A

Stream Width (ft.): ≈ 12' TOB Water Surface (At Crossing Location) 6'

Stream Depth (ft.): 0 1-3 3-6 6-12 12-18 18-24 24-36 36-48 48-60 60+

OHWM Indicators: *Bent veg, Scour*

Bank Height (ft.): (Looking Downstream)
 Left: 0-2 2-4 4-6 6-8 8+
 Right: 0-2 2-4 4-6 6-8 8+

Bank Slope: (Looking Downstream)
 Left: 4:1 3:1 2:1 1:1 Vertical
 Right: 4:1 3:1 2:1 1:1 Vertical

S 500 HA007

Qualitative Attributes

Water Appearance:

Clear Turbid Sheen on Surface Floating Algal Mats

Slightly Turbid Very Turbid Greenish Color Obvious Surface Scum

No Flow Other:

Stream Substrate %: *Silty Clay loam*

Aquatic Habitats:

Sand Bar Gravel Riffle In-stream Emergent Plant % Cover: *60%*

Gravel Bar Deep Pools In-stream Submerged Plant % Cover:

Mud Bar Bank Root Systems Fringing Wetlands Characteristics: *Hydrophytic veg*

Undercut Banks Overhanging Trees/Shrubs None *Hydric Soils, Hydrology*

Aquatic Organisms Observed: *None*

Riparian Zone:

Width of Natural Vegetation Zone from Edge of Active Channel out to Flood Plain (ft): Left - *10'* Right - *10'*

Vegetative Layers: Herbs Shrubs Trees Multiple

Significant Bare Areas Within Riparian Zone Yes No Unknown

Evidence Of Non-Buffered Concentrated Flows: Yes No Unknown

Tributary Condition: Natural Artificial (Man-Made) Manipulated

Channel Condition:

Channelization/Braiding Unnatural Straightening Downcutting

Dikes/Berms Excessive Bank Erosion N/A

Disturbances:

Livestock Access to Riparian Zone Manure In Stream or On Banks

Waste Discharge Pipes Present

Other:

Habitat Characteristics, Aquatic, and Terrestrial Diversity Description:

Habitat ID Number: *MA*

Comments: *fringe wetland on Left Descending Bank. Saline, Saltgrass, Carex sp. - Mottled soils, Salt crust. Only ~ 20 wide along bank.*

Stream Quality: High Moderate Low

↳ Buffalo/Cattle access.