Waterbody Data Form

S500 HA009 Torb to Walf Creek

Centerline Re-Route Access Road Ancillary Facility Transmission Line Other Other					
2 / N ID:	Project Designated Name: Rev Store XL Phase IX				
Centerline ID: 3/26/10					
Date: 11/2/10 Client/Project Name: Translanada	-Trow -KN Milepost Enter/Exit:				
Team: 15500 State/County: SO - Hard N	Quad Name: 1/4				
Logbook No.: 1 Logbook Page No.: 13 Tract No.:	-SD-HA-02612				
Drawing (Please provide orientation arrow, all features identified, local	tion to centerline, etc.) Photos: 001 W,002N,003E				
A (4) Posture N Sphotos 200	Downstream 1242 81 3111111 13:11 41 3:11 1 241 241				
Waterbody Type: Lake Pond Borrow Pit Stream Ag. Ditch Other					
Stream Flow: Fast Moderate Slow	/ery Slow None				
Flow Type: Perennial (Flows year round) ☐ Seasonal (Continuous flow ≥ 3 mont)	Intermittent (Flows <3 month None None hs) Ephemeral (Flows only in response to rainfall)				
Direction of Flow: N NE ME SE					
OHWM Width (ft.): 4/	· · · · · · · · · · · · · · · · · · ·				
	Straight N/A				
Stream Width (ft.): TOB 78	Surface (At Crossing Location)				
Stroom Donth (#1):	☐ 12-18 ☐ 18-24 ☐ 24-36 ☐ 36-48 ☐ 48-60 ☐ 60+				
OHWM Indicators: Bent reg, Scour					
Bank Height (ft.): Left: 0-2 2-4 4-6	□ 6-8 □ 8+				
(Looking Downstream) Right: 0-2 2-4 4-6	□ 6-8 □ 8+				
Bank Slope: Left: 4:1 3:1 2:1	1:1 Vertical				
(Looking Downstream) Right: 4:1 3:1 2:1	1:1 Vertical				

				2		
Qualitatíve Attribut	es			3500 HA009		
Water Ap pearance:	提供到2·60 下次2·5					
Clear	Turbid	Sheen on Surfac	☐ Floating A	Igalmats		
Slightly Turbid	Very Turbid	Greenish Color	Obvious S	Surface Scum		
☐ No Flow	Other:					
Stream Substrate %:	Sandy Clay					
Aquatic Habitats:						
Sand Bar	☑ Gravel Riffle	🕅 In-stream	Emergent Plant	% Cover: 30%		
Gravel Bar	Deep Pools	In-stream	☐ In-stream Submerged Plant % Cover:			
Mud Bar	Bank Root Systems	Fringing W	etlands Char	acteristics:		
Undercut Banks	Overhanging Trees/S	hrubs None				
Aquatic Organisms Ob	served: Grogs					
Riparian Zone:				,		
Width of Natural Ve	getation Zone from Edge of	of Active Channel out	to Flood Plain	(ft): Left - 5 Right - 51		
Vegetative Layers:	M Herbs Shrubs	Trees Multiple				
	eas Within Riparian Zone		Jnknown			
	uffered Concentrated Flow	_				
Tributary Condition:				& Fence bisects Stre		
Channel Condition:	Channelization/Braidin			Downcutting		
Shream L	Dikes/Berms	Excessive E		□ N/A		
Disturbances: Xive						
-	Livestock Access to Ri		anure in Stream	or On Banks		
	Waste Discharge Pipe					
	Other Stream X	ng				
Habitat Characteristics	, Aquatic, and Terrestrial Diver	reity Description:				
Habitat ID Number:	A A	any besomption.				
Table 15 Tallborr	10A					
Comments:	continuous in al	acen (BodiA)	a. K din	(X-1)		
0000	1	(Oco. p1)	and owne	ypted).		
Cattle	astron - Bill	1 lagran	311	10 may Sa - 20 2-		

Stream Quality:

☐ High ☐ Moderate ☐ Low