## WATERBODY DATA FORM



 □ Centerline ☐ Re-Route ☐ Access Road ☐ Ancillary Facility ☐ Other: Feature ID #: S7AME001 Stream/Waterbody Name (if known): PINE CREEK Associated Wetland ID #: H7AME002 Project Name & No.: Keystone XL-10623-007-803A Date: 6/24/08 Milepost: 383.3 **Investigators: 7A NOVAK** State/County: SD/ ME **Quad Name: OPAL WEST** Tract No.: ML-SD-ME-00260.000 Logbook No.:7A-1 Logbook Page No.: 98 Picture No.: S7AME001\_N,W,S PHYSICAL ATTRIBUTES Waterbody Sketch Plan Please include: Directional & North Arrow, Centerline, Length of feature, Distances from Centerline, Photo Locations, and ine will Survey corridor Crt Pine Jarrow band photos · Cultonwoods /ash (50-70') along both sides - along entire for ida · willow / Snowborry Shrubs-1070 & Angle of Crossing at Centerline: . Nerbs . w. what I seedle a thrad grasses - 80%. left Bank Right Bunk Outhonwood y ash range/grasslan man sedge ~15 Pond ☐ Borrow Pit River Waterbody Type ☐ Lake Ag. Ditch Other: Stream Flow Perennial (Flows year round) Direction of Flow where Flow ☐ Fast ☐ Slow ☐ Seasonal (Continuous flow ≥ 3 months) it crosses CL: S (N, NE, type ☐ Intermittent (Flows <3 months) E, SE, S, SW, W, NW) ✓ Very Slow ■ None ☐ Ephemeral (Flows only in response to rainfall) Subsurface Flow? ☐ No □ Unknown ☐ Yes OHWM Width (ft.): 8-12' AVG. = 10' Sinuosity ☐ Straight Meandering Stream Width (ft.) Top of Bank (at crossing location): 50 Water Surface (at crossing location): 10 Stream Depth (in.) □ 0-3 3-6 □ 6-12 12-18 18-24 **24-36** 36-48 □ 48-60 □ 60+ **OHWM Indicator** ☐ Wrack line ☐ Shelving ☐ Scour Abrupt plant community change ☐ Bent, matted or missing ☐ Wrested vegetation ☐ Water staining vegetation ☐ Soil character changes ☐ Sediment deposition ☐ Sediment sorting Litter and debris ☐ Leaf litter disturbed Other: 2-4 Bank Height (ft.) Left: 0-2 ⊠ 8+ □ 4-6 □ 6-8 (looking downstream) □ 2-4 Right: **⊠** 0-2 □ 4-6 □ 6-8 □ 8+ Bank Slope (looking Left: 4:1 □ 3:1 2:1 □ 1:1 ☐ Vertical downstream) 4:1 ⊠ 3:1 2:1 1:1 ☐ Vertical Right:



Page 2 of 2 Feature ID #: S7AME001

Date: 6/24/08	Project Name & No.: Keystone XL-10623-007-803A	Milepost: 383.3
QUALITATIVE AT		
Water Appearance (check all that apply)	Clear ☐ Turbid ☐ Sheen on surface ☐ Floating algal m Slightly Turbid ☐ Very Turbid ☐ Greenish color ☐ Obvious surface Other:	
Stream Substrate %	Silts 30% Cobbles Bedrock Sands 60% Concrete Muck Vegetation:	Gravel 10%
	Other: Explain:	
Aquatic Habitats (check all that apply)	Sand Bar ☐ Gravel Riffles ☐ In-stream emergent plants: ☐ In-stream submerged plants: ☐ In-stream emergent plants: ☐ In-stream submerged plants: ☐ In-stream emergent plants: ☐	
Aquatic Organisms Observed (check all that apply)	Waterfowl ☐ Fish (adult) ☐ Turtles ☐ Other:  Snakes ☑ Fish (juvenile) ☐ Frogs ☑ SAW A N. SPOTTED LEOPARD FROG  Invertebrates: CAN'T SEE	
Riparian Zone	Width of natural vegetation zone from edge of active channel out onto flood plain (FT):  Circle vegetative layers: trees ⊠ shrubs ⊠ herbs ⊠  □Significant bare areas within riparian zone □Evidence of non-but	ffered concentrated flows
Tributary is	Natural ☐Artificial (Man-Made) ☐Manipulated	
Channel Condition:	Channelization Unnatural straightening Downcutting Dikes/Berms   or Braiding	Bank erosion Other
Disturbances	Livestock access to riparian zone  Waste discharge pipes present  Other: NO SIGN OF CATTLE	
HIGH TERRESTRIA	racteristics, Aquatic & Terrestrial Diversity:  AL SPP. DIVERSITY & QUALITY HABITAT  AQUATIC INVERTS OR FISH SPP.	lo.:
Comments (e.g. pipeline crossing angle, construction constraints, erosion potential, existing disturbances, and meanders)		
CROSSES @ STEEP ERODING BANK		
STREAM QUALITY H	igh ☐ Moderate ⊠ Low	П