From: Tim Lindgren

Sent: Tuesday, August 16, 2022 9:58 PM

To: PUC-PUC < PUC@state.sd.us >

Subject: Re: [EXT] Docket EL 19-003 Sound Study

Please post to Docket Public comments

Commissioners:

Re: Docket 19-003

Please post to Docket

Our home was one of the five properties tested in the most recent sound study. We have been waiting for the Commission to discuss the sound study at one of the regularly scheduled meetings. We were left out of the first sound study which was conducted during more typical South Dakota winter weather conditions.

The most recent sound study conducted during milder conditions than the first study shows Crown Ridge 1 out of compliance at our home. We read the docket and see that Crown Ridge 1 claimed that they are in compliance. They are not! They are out of compliance by at least one db at our home. One db is a 26% difference in sound energy. This was in mild fall weather conditions.

What is causing the delay in discussing the sound study at a Commission meeting? We are in the middle of the turbines and the turbines surrounding our home are not in compliance. This matter needs to be addressed as soon as possible. Winter is coming soon and a new sound study should ideally be made this winter when the wind turbines are at their worst.

We (Tim and Linda) would appreciate being included in the Commission's discussion of the recent sound study.

Sincerely,

Tim and Linda Lindgren

South Shore, SD

From: Tim Lindgren

Sent: Monday, August 15, 2022 10:55 PM

To: PUC-PUC PUC@state.sd.us

Subject: Re: [EXT] Docket 19-003 Sound Study

Commisioners: Re: Docket 19-003

Our home was one of the five properties tested in the most recent sound study. We have been waiting for the Commision to discuss the sound study at one of the regularly scheduled meetings. We were left out of the first sound studywhich was conducted during more typical South Dakota winter weatherconditions.

The most recent sound study conducted during milder conditions than the first study shows Crown Ridge 1 out of compliance at our home. We read the docket and see that Crown Ridge 1 claimed that they are in compliance. They are not! They are out of compliance by at least one db at our home. One db is a 26% difference in sound energy. This was in mild fall weather conditions.

What is causing the delay in discussing the sound study at a Commision meeting? We are in the middle of the turbines and the turbines surrounding our home are not in compliance. This matter needs to be addressed as soon as possible. Winter is coming soon and a new sound study should ideally be made this winter when the wind turbines are at their worst.

We (Tim and Linda) would appriciate being included in the Commision's discussion of the recent sound study.

Sincerely,

Tim and Linda Lindgren