

Index of Pictures Provided  
to  
Kiefner and Associates

| File Name    | Brief Description                                                                                                                                                                                                           |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| DSC01419.JPG | Pipe and area around point of break. Initial exposre. (Taken from S side of bellhole)                                                                                                                                       |
| DSC01420.JPG | Excavating soil from around are of leak.(Taken from S side of bellhole)                                                                                                                                                     |
| DSC01421.JPG | Close-up of pipe and area around leak. (Taken from S side of bellhole)                                                                                                                                                      |
| DSC01422.JPG | Close-up of pipe and area around leak. (Taken from S side of bellhole)                                                                                                                                                      |
| DSC01423.JPG | Patch in asphalet pavement on South side of bellhole.                                                                                                                                                                       |
| DSC01424.JPG | View of pipe in bellhole. Pipe stub sticking up in upper right hand portion of picture is for water service shut-off valve. (Taken from NE corner of bellhole)                                                              |
| DSC01425.JPG | View of pipe in bellhole. Pipe stub sticking up in lower right hand portion of picture is for water service shut-off valve. (Taken from N side of bellhole)                                                                 |
| DSC01426.JPG | View of pipe in bellhole. Water service shut-off valve is in bootom-center of picture. Picture shows location on west edge of bellhole where pipe was cut with cutoff saw prior to removal. (Taken from N side of bellhole) |
| DSC01427.JPG | Damaged area pipe. (Taken shortly after removal from bellhole)                                                                                                                                                              |
| DSC01429.JPG | Gas main with replacement pipe in place. (Taken from S side of bellhole)                                                                                                                                                    |
| DSC01430.JPG | Gas main with replacement pipe in place. (Taken from S side of bellhole)                                                                                                                                                    |
| DSC01431.JPG | Gas main with replacement pipe in place. (Taken from S side of bellhole)                                                                                                                                                    |
| DSC01432.JPG | Patched area of pavement and bellhole. (Taken from S side of bellhole)                                                                                                                                                      |
| DSC01433.JPG | Gas main with replacement pipe in place. (Taken from N side of bellhole)                                                                                                                                                    |
| DSC01444.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01445.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01446.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01447.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01448.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01449.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01450.JPG | Various views of pipe (Taken four days after pipe was removed from bellhole)                                                                                                                                                |
| DSC01589.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |
| DSC01590.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |
| DSC01591.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |
| DSC01592.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |
| DSC01593.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |
| DSC01594.JPG | Various views of pipe (Taken on June 1, 2007)                                                                                                                                                                               |