Dakota Access Pipeline Quarterly Report to PUC July – September 2019

Table of Contents

| 1. Liaison Activity | .3 |
|---|----|
| 2. Status of Land Acquisition | .3 |
| 3. Status of Construction | 4 |
| 4. Status of Permits | .4 |
| 5. Physical Completion | 5 |
| 6. Major Design Changes | .5 |
| 7. Consultations | 5 |
| 8. Other information | .5 |
| 5. Physical Completion 6. Major Design Changes 7. Consultations | .5 |

1. Liaison Activity

The Liaison had 4 contacts by phone calls and emails in the third quarter of 2019.

The categories of contacts are as follows:

2 regarding seeding and vegetation issues

2 requesting report on open issues

2. Status of Land Acquisition

Dakota Access has indicated they have executed easements on all of the private property it plans to cross in South Dakota.

3. Status of Construction

Construction has been completed on all 3 spreads in South Dakota:

Spread 4: 100 % Grading 100 % Ditching 100 % Lowering-In/Backfill 100 % Topsoil Replaced 100 % Seeding

Spread 5: 100 % Grading

100 % Ditching 100 % Lowering-In/Backfill 100 % Topsoil Replaced 100 % Seeding

Spread 6: 100 % Grading 100 % Ditching 100 % Lowering-In/Backfill 100 % Topsoil Replaced 100 % Seeding

4. Status of Permits

100% of Right to Occupy and temporary & permanent approach permits have been acquired. All haul road agreements have been reached. Army Corps of Engineers has issued necessary permits. Water uptake and discharge permits have been acquired for hydrostatic testing. DAPL has with US Fish and Wildlife to have mutual understanding on relevant issues. USFW has been allowed to inspect all USFW easement areas after final reclamation.

5. Physical Completion

The Mainline in all spreads are mechanically complete.

6. Major Design Changes

There have been no major re-routes or design changes.

7. Consultations

Dakota Access has been consulted with DENR on reclamation issues.

8. Other information

There are currently 4 known open issues with Dakota Access.

2 issues are being monitored for proper re-vegetation

2 issues are related to improper water drainage, ponding and crop yield loss. DAPL has paid for drain tile to be installed in the fall of 2019.