

3 - YEAR OUTAGE REPORT

EVENTID	OUT_DTS_UT	MINUTES	EVENT_TYPE	CUST	CAUSE_DESC	NWE_COMP_REMARKS	WEATHER	SOURCE	FEEDER	SUBSTATION	PLANNED	EVENTNUM
YEAR: 2013 FEEDER: Y8105												
65832	6/23/2013 11:09 PM	70	FEEDER OUTAGE	231	Public - Vehicle Hit	Comment - Under current and future system configuration Dakota Plains would have been affected.	NONE	BREAKER	8105	YANKTON JCT	N	E0000065832
YEAR: 2015 FEEDER: Y0132 & Y1333												
521951	12/16/2015 11:12 AM	337	FEEDER OUTAGE	102	System - Equipment Failure	MCCLOUDJ: SNOW/ICE ON LINE. ICE STORM OVERNIGHT. SEVERAL FLOATERS ON TRANSMISSION LINE. Comment - Under current system configuration Dakota Plains would have been affected. The proposed design of the facilities to feed Dakota Plains, this outage would not have interrupted their service.	STRONG WIND	CONDUCTOR	0132	LESTERVILLE	N	E00000103271
521952	12/16/2015 10:19 AM	382	FEEDER OUTAGE	142	System - Equipment Failure	MCCLOUDJ: RESTORED BY SCADA SWITCHING. ICE STORM OVER NIGHT. LOSS OF TRANSMISSION. Comment - Under current system configuration Dakota Plains would have been affected. The proposed design of the facilities to feed Dakota Plains, this outage would not have interrupted their service.	SNOW/ICE	CONDUCTOR	1333	LESTERVILLE	N	E00000103272