

**Individual Report for Docket Number : PS07-002**

**Docket Title:**

IN THE MATTER OF THE FILING OF THE INVESTIGATION OF THE NATURAL GAS INCIDENT OF MARCH 8, 2007 IN MITCHELL, SOUTH DAKOTA.

**Open Date :** 07/13/2007

**Close Date :** 10/24/2008

**Days Open :** 469

**Filing Type :**

PS

**Tax ID # :**

**Attorney :**

KS

**Staff :**

NS

**Primary Appeal Information**

**Appeal Date :**

**Appellant :**

**Decision Date :**

**Appeal Location :**

**Current Status :**

**Description of Above Decision :**

**Secondary Appeal Information**

**Appeal Date :**

**Appellant :**

**Decision Date :**

**Appeal Location :**

**Current Status :**

**Description of Above Decision :**

IN THE MATTER OF THE FILING OF THE INVESTIGATION OF THE NATURAL GAS INCIDENT OF MARCH 8, 2007 IN MITCHELL, SOUTH DAKOTA. Filed 07-13-2007; Pending.

Irregular

**Irregular's E-Mail Addresses:**

shanson@dehs.com

**Irregular's Fax Numbers:**

(605) 335-3639

## Individual Report for Docket Number : PS07-002

### Docket Notes :

07/13/07 - Letter to Commission Regarding Investigation - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/071307.pdf

07/19/07 - Weekly Filings - M:puc/weeklyfiling/2007/0712-0718.htm

07/23/07 - Petition of Arden Lemke d/b/a Lemke Digging & Geothermo Drilling to Intervene - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/072307.pdf

07/24/07 - Petition to Intervene by Dennis Burnham - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/072407.pdf

07/25/07 - Petition to Intervene by Robert and Jeanne Lorenz - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/072507.pdf

07/25/07 - Letter, Notice of Appearance and Certificate of Service - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/072507ltrcos.pdf

07/25/07 - Letter and Petition to Intervene by Ann and Arend Kuyper and Darla and Carl Johnson - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/shanks.pdf

07/27/07 - Petition to Intervene by Bailey's Plumbing - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/baileypet.pdf

08/03/07 - Letter from Kara Semmler - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/080307.pdf

08/07/07 - Petition of American Family Insurance to Intervene - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/080707.pdf

08/13/07 - Letter to Brett Koenecke from Roy A. Wise - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/081307.pdf

08/23/07 - Response to Staff's Proposed Expert Procedure - M:puc/commission/dockets/pipelinesafety/2007/PS07-002M/082307.pdf

08/24/07 - Letter from Kara Semmler regarding Proposed Scope of Services - M:puc/commission/dockets/pipelinesafety/2007/PS07-001/semmlerltr.pdf

09/18/07 - Order Granting Intervention - M:puc.sd.gov/commission/orders/pipelinesafety/2007/ps07-002ogi1.pdf

09/18/07 - Order Granting Intervention- Order Authorizing Physical Inspection and Order Permitting Hiring an Expert Witness - M:puc.sd.gov/commission/orders/pipelinesafety/2007/ps07-002ogi.pdf

02/20/08 - Letter from Kara Semmler regarding lab results from Stork Twin City Testing Corporation - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/ltr022008.pdf

02/20/08 - CD Index - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/cdindex.pdf

02/20/08 - List of Attendees - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/listofattendees.pdf

02/20/08 - Chemical Analysis - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/chemicalanalysis.pdf

02/20/08 - Grain Structure Examination - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/grainstructureexamination.pdf

02/20/08 - Qualitative Chemical Analysis of Surface Deposits - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/qualitativechemicalanalysis.pdf

02/20/08 - Tensile Test - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/tensiletest.pdf

02/20/08 - Visual Examination - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/testresults/visualexamination.pdf

02/20/08 - Grain Structure Examination (GSE) Photos - G- OD Surface metallography at 50X 0 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse1.jpg

02/20/08 - G- OD Surface metallography at 50X 1 - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

## Individual Report for Docket Number : PS07-002

002/gse/gse2.jpg

02/20/08 - G- OD Surface metallography at 50X 2 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse3.jpg

02/20/08 - Isometric close-up view of groove at crack -

M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse4.jpg

02/20/08 - Isometric view of exposed crack end - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse5.jpg

02/20/08 - Isometric view of exposed crack end\_edited-1 - M:

puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse6.jpg

02/20/08 - Left of weld at 50X cropped - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse7.jpg

02/20/08 - Left of weld at 50X - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse8.jpg

02/20/08 - Macro of cross section of surface groove at fracture -

puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse9.jpg

02/20/08 - NG- OD surface metallography at 50X 0 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse10.jpg

02/20/08 - NG- OD surface metallography at 50X 1 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse11.jpg

02/20/08 - NG- OD surface metallography at 50X 2 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse12.jpg

02/20/08 - Right of weld at 50X cropped - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse13.jpg

02/20/08 - Right of weld at 50X - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse14.jpg

02/20/08 - surface groove at fracture close-up - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse15.jpg

02/20/08 - surface groove at fracture overall - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse16.jpg

02/20/08 - Weld at 50X cropped - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse17.jpg

02/20/08 - Weld at 50X - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/gse/gse18.jpg

02/20/08 - Weld seam inside surface M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/gse/gse19.jpg

02/20/08 - Mitchell Incident Pipe Picture Index - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/index.pdf

02/20/08 - On-site DSC01419 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01419.jpg

02/20/08 - On-site DSC01420 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01420.jpg

02/20/08 - On-site DSC01421 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01421.jpg

02/20/08 - On-site DSC01422 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01422.jpg

02/20/08 - On-site DSC01423 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01423.jpg

02/20/08 - On-site DSC01424 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

002/onsite/dsc01424.jpg

02/20/08 - On-site DSC01425 - M: puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-

## Individual Report for Docket Number : PS07-002

002/onsite/dsc01425.jpg

02/20/08 - On-site DSC01426 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01426.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01426.jpg)

002/onsite/dsc01426.jpg

02/20/08 - On-site DSC01427 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01427.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01427.jpg)

002/onsite/dsc01427.jpg

02/20/08 - On-site DSC01429 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01429.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01429.jpg)

002/onsite/dsc01429.jpg

02/20/08 - On-site DSC01430 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01430.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01430.jpg)

002/onsite/dsc01430.jpg

02/20/08 - On-site DSC01431 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01431.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01431.jpg)

002/onsite/dsc01431.jpg

02/20/08 - On-site DSC01432 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01432.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01432.jpg)

002/onsite/dsc01432.jpg

02/20/08 - On-site DSC01433 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01433.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01433.jpg)

002/onsite/dsc01433.jpg

02/20/08 - On-site DSC01444 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01444.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01444.jpg)

002/onsite/dsc01444.jpg

02/20/08 - On-site DSC01445 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01445.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01445.jpg)

002/onsite/dsc01445.jpg

02/20/08 - On-site DSC01446 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01446.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01446.jpg)

002/onsite/dsc01446.jpg

02/20/08 - On-site DSC01447 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01447.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01447.jpg)

002/onsite/dsc01447.jpg

02/20/08 - On-site DSC01448 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01448.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01448.jpg)

002/onsite/dsc01448.jpg

02/20/08 - On-site DSC01449 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01449.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01449.jpg)

002/onsite/dsc01449.jpg

02/20/08 - On-site DSC01450 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01450.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01450.jpg)

002/onsite/dsc01450.jpg

02/20/08 - On-site DSC01589 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01589.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01589.jpg)

002/onsite/dsc01589.jpg

02/20/08 - On-site DSC01590 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01590.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01590.jpg)

002/onsite/dsc01590.jpg

02/20/08 - On-site DSC01591 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01591.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01591.jpg)

002/onsite/dsc01591.jpg

02/20/08 - On-site DSC01592 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01592.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01592.jpg)

002/onsite/dsc01592.jpg

02/20/08 - On-site DSC01593 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01593.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01593.jpg)

002/onsite/dsc01593.jpg

02/20/08 - On-site DSC01594 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01594.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/onsite/dsc01594.jpg)

002/onsite/dsc01594.jpg

02/20/08 - SEM EDS Photos Data SEM BEI Sample 1 at 100X - M:

[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem1.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem1.jpg)

02/20/08 - SEM BEI Sample 2 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem2.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem2.jpg)

002/semeds/sem2.jpg

02/20/08 - SEM BEI Sample 3 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem3.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem3.jpg)

**Individual Report for Docket Number : PS07-002**

- 002/semeds/sem3.jpg
- 02/20/08 - SEM BEI Sample 4 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem4.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem4.jpg)
- 02/20/08 - SEM BEI Sample 5 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem5.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem5.jpg)
- 02/20/08 - SEM BEI Sample 6 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem6.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem6.jpg)
- 02/20/08 - SEM BEI Sample 7 at 100X - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem7.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem7.jpg)
- 02/20/08 - SEM BEI Sample 8 at 100X M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem8.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem8.jpg)
- 02/20/08 - SEM EDS Sample 1 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem9.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem9.jpg)
- 02/20/08 - SEM EDS Sample 2 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem10.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem10.jpg)
- 02/20/08 - SEM EDS Sample 3 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem11.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem11.jpg)
- 02/20/08 - SEM EDS Sample 4 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem12.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem12.jpg)
- 02/20/08 - SEM EDS Sample 5 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem13.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem13.jpg)
- 02/20/08 - SEM EDS Sample 6 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem14.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem14.jpg)
- 02/20/08 - SEM EDS Sample 7 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem15.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem15.jpg)
- 02/20/08 - SEM EDS Sample 8 dark - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem16.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem16.jpg)
- 02/20/08 - SEM EDS Sample 8 - M:
- 02/20/08 - SEM EDS Sample 8 -M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem17.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/semeds/sem17.jpg)
- 02/20/08 - Visual Examination Photos Coating at combined 7 and 13+ - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep1.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep1.jpg)
- 02/20/08 - Coating condition 7 in. from End A after - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep2.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep2.jpg)
- 02/20/08 - Coating condition 7 in. from End A - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep3.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep3.jpg)
- 02/20/08 - Coating condition 13+ in. from End A after - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep4.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep4.jpg)
- 02/20/08 - Coating condition 13+ in. from End A - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep5.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep5.jpg)
- 02/20/08 - Coating condition 42 in. from End A - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep6.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep6.jpg)
- 02/20/08 - Coating condition at 21 in. from End A at right - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep8.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep8.jpg)
- 02/20/08 - Crack 1 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep8.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep8.jpg)
- 02/20/08 - Crack 2 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep9.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep9.jpg)

**Individual Report for Docket Number : PS07-002**

- 02/20/08 - Crack 3 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep10.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep10.jpg)
- 02/20/08 - Crack 4 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep11.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep11.jpg)
- 02/20/08 - Crack 6 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep13.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep13.jpg)
- 02/20/08 - Crack 6A - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep14.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep14.jpg)
- 02/20/08 - Crack 7 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep15.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep15.jpg)
- 02/20/08 - Crack 8 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep16.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep16.jpg)
- 02/20/08 - Crack 9 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep17.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep17.jpg)
- 02/20/08 - Crack 10 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep18.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep18.jpg)
- 02/20/08 - Crack 11 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep19.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep19.jpg)
- 02/20/08 - Crack 12 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep20.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep20.jpg)
- 02/20/08 - Crack at 28 in. from End A -M : [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep21.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep21.jpg)
- 02/20/08 - Crack calibration - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep22.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep22.jpg)
- 02/20/08 - Crack end back view - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep23.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep23.jpg)
- 02/20/08 - End A with tape - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep24.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep24.jpg)
- 02/20/08 - End A - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep25.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep25.jpg)
- 02/20/08 - End B including crack - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep26.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep26.jpg)
- 02/20/08 - End B - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep27.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep27.jpg)
- 02/20/08 - Isometric close-up view of groove at crack - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep28.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep28.jpg)
- 02/20/08 - Isometric view of exposed crack end\_edited-1 - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep29.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep29.jpg)
- 02/20/08 - Overall crack 1 - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep30.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep30.jpg)
- 02/20/08 - Overall crack back view -M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep31.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep31.jpg)
- 02/20/08 - Overall crack side - M:[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep32.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep32.jpg)
- 02/20/08 - Overall crack - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep33.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep33.jpg)
- 02/20/08 - Overall opposite crack - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep34.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep34.jpg)
- 02/20/08 - Pipe deflection close-up- crack down - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep35.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep35.jpg)
- 02/20/08 - Pipe deflection end view- crack up - M:[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep36.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep36.jpg)
- 02/20/08 - Pipe deflection front view- crack up - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep37.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep37.jpg)
- 02/20/08 - Pipe deflection isometric view- crack down - M:  
[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep38.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep38.jpg)
- 02/20/08 - Pipe ID surface after cleaning - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep39.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep39.jpg)
- 02/20/08 - Pipe ID surface after cleaning - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep40.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep40.jpg)
- 02/20/08 - Section cut from End B for tensile - M:[puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep41.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep41.jpg)
- 02/20/08 - surface groove at fracture overall - M: [puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep42.jpg](http://puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep42.jpg)

## Individual Report for Docket Number : PS07-002

02/20/08 - Table examination set-up - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002/VEP/vep43.jpg  
05/23/08 - Letter and Commission Pipeline Safety Staff Report -  
M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002M/052308.pdf  
05/28/08 - Letter and Report - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002M/052808.pdf  
06/16/08 - Response to Staff's May 23, 2008 Report -  
M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002M/061608.pdf  
06/17/08 - Letter from Kara Semmler Regarding Scheduling Order -  
M:puc.sd.gov/commission/dockets/telecom/2006/TC06-178/061608.pdf  
06/30/08 - Letter and Motion to Close Docket - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/PS07-002M/063008.pdf  
08/21/08 - Order Closing Docket - M:puc.sd.gov/commission/orders/pipelinesafety/2008/ps07-002.pdf  
08/21/08 - Docket Closed - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/ps07-002/close.pdf  
10/10/08 - Staff's Request to Reopen Docket and Amended Report -  
M:puc.sd.gov/commission/dockets/pipelinesafety/2007/ps07-002/101008.pdf  
10/24/08 - Order Granting Staff's Request to Reopen Docket and Accept Staff's Amended Safety Report  
- M:puc.sd.gov/commission/orders/pipelinesafety/2008/ps07-002a.pdf  
10/24/08 - Docket Closed - M:puc.sd.gov/commission/dockets/pipelinesafety/2007/ps07-002/close.pdf