

**OTTER TAIL POWER COMPANY**

Docket No: EL10-011

Response to: Otter Tail Power Company

Analyst: Bryan D. Morlock

Date Received: 02/25/2011

Date Due: 03/11/2011

Date of Response:

Responding Witness:

Question No. : SD-OTP-04

The IRP-Manager indicates that a resource designated as “Firm” is one that is not dispatchable. Do you believe that a wind plant should be designated as dispatchable or non-dispatchable?

**RESPONSE:**

A wind plant should be designated as non-dispatchable and non-firm. IRP-Manager does not provide the necessary options.