
Pictorial explanation for <u>why the dBA metric is not useful</u> for the quantification of infrasound and low frequency noise.



(by Mariana Alves-Pereira, 2018)

Image source: Dirac Dirac Delta Science & Engineering Encyclopedia (2018) A-Weighting. http://www.diracdelta.co.uk/science/source/a/w/aweighting/source.html#.W45nwy220Rs

