

**LYNN  
JACKSON**  

---

**ATTORNEYS**

110 N. Minnesota Ave., Suite 400  
Sioux Falls, SD 57104  
Phone (605) 332-5999 · Fax (605) 332-4249

909 Saint Joseph Street, Suite 800  
Rapid City, SD 57701  
Phone (605) 342-2592 · Fax (605) 342-5185

311 N. 27th Street, Suite 4  
Spearfish, SD 57783  
Phone (605) 722-9000 · Fax (605) 722-9001

*From the office of Miles F. Schumacher*  
e-mail address: [mschumacher@lynnjackson.com](mailto:mschumacher@lynnjackson.com)

March 16, 2022

Ms. Patricia Van Gerpen, Executive Director  
South Dakota Public Utilities Commission  
Capital Building, 1<sup>st</sup> Floor  
500 East Capital Avenue  
Pierre, SD 57501-5070

Re: Docket #EL19-003; Application to the SD PUC for a Facility Permit to Construct  
A 300 megawatt Wind Facility

Dear Ms. Van Gerpen:

On March 11, 2022, the Aircraft Detection Lighting System (“ADLS”) for Crowned Ridge Wind, LLC (“Crowned Ridge”) reverted to having the Federal Aviation Administration (“FAA”) warning lights on due to an interruption with the communication between ADLS radar and the turbine warning lights system. The ADLS properly reverted to a lights-on mode to ensure the safety of aircraft. The cause of the communication interruption is damaged underground fiber. Crowned Ridge estimates that the fiber will be repaired and the ADLS communications restored by March 21, 2022.

If there are any questions, please contact me.

Yours very truly,

LYNN, JACKSON, SHULTZ & LEBRUN, P.C.



Miles F. Schumacher