



## Notice of Proposed Construction or Alteration - Off Airport

[Add New Multiple Cases Off Airport - Desk Reference Guide V\\_2018.2.1](#)

[Add a New Case \(Off Airport\) for Wind Turbines - Met Towers \(with WT Farm\) - WT-Barge Crane - Desk Reference Guide V\\_2018.2.1](#)

**Project Name:** CROWN-000560930-20

### Project Summary : CROWN-000560930-20

Structure	City, State	Lat/Long	Map	Actions	7460-2 Received	Latest Letter
CRI-24 Accepted 2020-WTE-10-OE	Milbank, SD	45° 5' 17.38" N 97° 1' 10.29" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-22 Accepted 2020-WTE-11-OE	Milbank, SD	45° 5' 21.50" N 97° 0' 38.54" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-21 Accepted 2020-WTE-12-OE	Milbank, SD	45° 5' 23.63" N 96° 59' 35.25" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-20 Accepted 2020-WTE-13-OE	Milbank, SD	45° 5' 22.92" N 96° 58' 3.99" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-31 Accepted 2020-WTE-14-OE	Milbank, SD	45° 4' 58.57" N 97° 1' 48.54" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-29 Accepted 2020-WTE-15-OE	Milbank, SD	45° 4' 58.42" N 97° 1' 6.94" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-33 Accepted 2020-WTE-16-OE	Milbank, SD	45° 4' 53.78" N 97° 0' 38.45" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-27 Accepted 2020-WTE-17-OE	Milbank, SD	45° 5' 1.05" N 96° 59' 58.13" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-25 Accepted 2020-WTE-18-OE	Milbank, SD	45° 5' 3.61" N 96° 59' 21.03" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-34 Accepted 2020-WTE-19-OE	Milbank, SD	45° 4' 49.10" N 96° 58' 48.84" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-30 Accepted 2020-WTE-20-OE	Milbank, SD	45° 4' 54.70" N 96° 58' 7.24" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-32 Accepted 2020-WTE-21-OE	Milbank, SD	45° 4' 52.29" N 96° 57' 29.24" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-28 Accepted 2020-WTE-22-OE	Milbank, SD	45° 4' 54.67" N 96° 54' 34.73" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-26 Accepted 2020-WTE-23-OE	Milbank, SD	45° 4' 54.62" N 96° 53' 54.10" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-39 Accepted 2020-WTE-24-OE	Milbank, SD	45° 4' 21.99" N 97° 0' 42.25" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-45 Accepted 2020-WTE-25-OE	Milbank, SD	45° 4' 8.79" N 96° 59' 54.86" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-35 Accepted 2020-WTE-26-OE	Milbank, SD	45° 4' 33.72" N 96° 59' 51.78" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-38 Accepted 2020-WTE-27-OE	Milbank, SD	45° 4' 21.27" N 96° 59' 18.52" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-36 Accepted 2020-WTE-28-OE	Milbank, SD	45° 4' 30.90" N 96° 58' 3.75" W	Show Map	Clone Upload a PDF Add 7460-2		None
CRI-41 Accepted	Milbank, SD	45° 4' 13.64" N 96° 55' 9.85" W	Show Map	Clone Upload a PDF		None

2020-WTE-29-OE					<a href="#">Add 7460-2</a>	
<a href="#">CRI-37</a> Accepted 2020-WTE-30-OE	Milbank, SD	45° 4' 20.48" N 96° 54' 40.47" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-46</a> Accepted 2020-WTE-31-OE	Milbank, SD	45° 4' 0.90" N 96° 54' 42.57" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-44</a> Accepted 2020-WTE-32-OE	Milbank, SD	45° 3' 58.40" N 96° 53' 44.23" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-43</a> Accepted 2020-WTE-33-OE	Milbank, SD	45° 4' 9.39" N 96° 53' 20.21" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-50</a> Accepted 2020-WTE-34-OE	Milbank, SD	45° 3' 34.56" N 96° 55' 50.22" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-48</a> Accepted 2020-WTE-35-OE	Milbank, SD	45° 3' 37.98" N 96° 55' 10.58" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-52</a> Accepted 2020-WTE-36-OE	Milbank, SD	45° 3' 24.18" N 96° 53' 55.76" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-54</a> Accepted 2020-WTE-37-OE	Milbank, SD	45° 3' 9.03" N 96° 53' 31.70" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-51</a> Accepted 2020-WTE-38-OE	Milbank, SD	45° 3' 33.98" N 96° 53' 16.14" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-55</a> Accepted 2020-WTE-39-OE	Milbank, SD	45° 3' 13.27" N 96° 58' 48.60" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-53</a> Accepted 2020-WTE-40-OE	Milbank, SD	45° 3' 15.36" N 96° 58' 16.30" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-62</a> Accepted 2020-WTE-41-OE	Milbank, SD	45° 2' 48.11" N 96° 57' 22.22" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-65</a> Accepted 2020-WTE-42-OE	Milbank, SD	45° 2' 38.66" N 96° 56' 46.99" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-61</a> Accepted 2020-WTE-43-OE	Milbank, SD	45° 2' 46.70" N 96° 55' 49.56" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-64</a> Accepted 2020-WTE-44-OE	Milbank, SD	45° 2' 46.32" N 96° 55' 9.54" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-63</a> Accepted 2020-WTE-45-OE	Milbank, SD	45° 2' 38.84" N 96° 54' 34.64" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-58</a> Accepted 2020-WTE-46-OE	Milbank, SD	45° 2' 48.52" N 96° 53' 46.94" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-59</a> Accepted 2020-WTE-47-OE	Milbank, SD	45° 2' 47.39" N 96° 53' 7.72" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-71</a> Accepted 2020-WTE-48-OE	Milbank, SD	45° 2' 21.84" N 96° 58' 33.96" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-72</a> Accepted 2020-WTE-49-OE	Milbank, SD	45° 2' 20.94" N 96° 58' 2.82" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-69</a> Accepted 2020-WTE-50-OE	Milbank, SD	45° 2' 25.19" N 96° 57' 38.26" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-73</a> Accepted 2020-WTE-51-OE	Milbank, SD	45° 2' 19.55" N 96° 57' 5.44" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-70</a> Accepted 2020-WTE-52-OE	Milbank, SD	45° 2' 19.55" N 96° 56' 27.62" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-66</a> Accepted 2020-WTE-53-OE	Milbank, SD	45° 2' 28.26" N 96° 55' 41.88" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-77</a> Accepted 2020-WTE-54-OE	Milbank, SD	45° 2' 0.08" N 96° 58' 46.01" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-81</a> Accepted 2020-WTE-55-OE	Milbank, SD	45° 1' 50.57" N 96° 58' 15.86" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> <a href="#">Add 7460-2</a>		None
<a href="#">CRI-78</a>	Milbank, SD	45° 1' 56.02" N		<a href="#">Clone</a>		None

Accepted 2020-WTE-56-OE	Milbank, SD	96° 57' 30.62" W 45° 1' 52.93" N 96° 56' 56.85" W	<a href="#">Show Map</a>	<a href="#">Upload a PDF Add 7460-2</a>	None
<b>CRI-80</b> Accepted 2020-WTE-57-OE	Milbank, SD	45° 1' 52.93" N 96° 56' 56.85" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-76</b> Accepted 2020-WTE-58-OE	Milbank, SD	45° 1' 58.25" N 96° 56' 17.96" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-74</b> Accepted 2020-WTE-59-OE	Milbank, SD	45° 2' 0.23" N 96° 55' 48.54" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-75</b> Accepted 2020-WTE-60-OE	Milbank, SD	45° 1' 57.96" N 96° 54' 58.55" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-86</b> Accepted 2020-WTE-61-OE	Milbank, SD	45° 1' 31.99" N 96° 59' 15.53" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-85</b> Accepted 2020-WTE-62-OE	Milbank, SD	45° 1' 32.65" N 96° 58' 40.72" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-88</b> Accepted 2020-WTE-63-OE	Milbank, SD	45° 1' 22.03" N 96° 58' 1.71" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-84</b> Accepted 2020-WTE-64-OE	Milbank, SD	45° 1' 34.18" N 96° 57' 37.51" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-87</b> Accepted 2020-WTE-65-OE	Milbank, SD	45° 1' 24.06" N 96° 56' 45.22" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-83</b> Accepted 2020-WTE-66-OE	Milbank, SD	45° 1' 40.13" N 96° 56' 26.46" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-82</b> Accepted 2020-WTE-67-OE	Milbank, SD	45° 1' 40.26" N 96° 55' 38.76" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-91</b> Accepted 2020-WTE-68-OE	Milbank, SD	45° 1' 4.35" N 97° 0' 25.51" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-89</b> Accepted 2020-WTE-69-OE	Milbank, SD	45° 1' 5.67" N 96° 59' 51.91" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-90</b> Accepted 2020-WTE-70-OE	Milbank, SD	45° 1' 3.55" N 96° 59' 16.01" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-93</b> Accepted 2020-WTE-71-OE	Milbank, SD	45° 0' 57.21" N 96° 58' 49.37" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-92</b> Accepted 2020-WTE-72-OE	Milbank, SD	45° 0' 59.85" N 96° 58' 7.89" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-94</b> Accepted 2020-WTE-73-OE	Milbank, SD	45° 0' 54.63" N 96° 57' 37.12" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-AIT22</b> Accepted 2020-WTE-74-OE	Milbank, SD	45° 1' 1.02" N 96° 56' 16.12" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-97</b> Accepted 2020-WTE-75-OE	Milbank, SD	45° 0' 27.89" N 97° 1' 18.13" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-96</b> Accepted 2020-WTE-76-OE	Milbank, SD	45° 0' 37.65" N 97° 0' 39.21" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-95</b> Accepted 2020-WTE-77-OE	Milbank, SD	45° 0' 41.82" N 97° 0' 5.07" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-98</b> Accepted 2020-WTE-78-OE	Milbank, SD	45° 0' 10.07" N 97° 0' 27.77" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-100</b> Accepted 2020-WTE-79-OE	Milbank, SD	45° 2' 45.23" N 96° 51' 19.77" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-99</b> Accepted 2020-WTE-80-OE	Milbank, SD	45° 2' 38.88" N 96° 48' 33.82" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-101</b> Accepted 2020-WTE-81-OE	Milbank, SD	45° 2' 49.07" N 96° 48' 15.13" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None
<b>CRI-102</b> Accepted 2020-WTE-82-OE	Milbank, SD	45° 3' 9.79" N 96° 51' 56.66" W	<a href="#">Show Map</a>	<a href="#">Clone Upload a PDF Add 7460-2</a>	None

<a href="#">CRI-103</a> Accepted 2020-WTE-83-OE	Milbank, SD	45° 3' 11.73" N 96° 51' 0.77" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-105</a> Accepted 2020-WTE-84-OE	Milbank, SD	45° 3' 9.91" N 96° 50' 5.56" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-106</a> Accepted 2020-WTE-85-OE	Milbank, SD	45° 3' 17.13" N 96° 49' 29.17" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-104</a> Accepted 2020-WTE-86-OE	Milbank, SD	45° 3' 10.53" N 96° 48' 55.98" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-108</a> Accepted 2020-WTE-87-OE	Milbank, SD	45° 3' 29.94" N 96° 48' 13.74" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-107</a> Accepted 2020-WTE-88-OE	Milbank, SD	45° 3' 35.24" N 96° 52' 11.04" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-AI2</a> Accepted 2020-WTE-89-OE	Milbank, SD	45° 4' 9.56" N 96° 50' 59.94" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-109</a> Accepted 2020-WTE-90-OE	Milbank, SD	45° 3' 58.93" N 96° 49' 44.96" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-112</a> Accepted 2020-WTE-91-OE	Milbank, SD	45° 4' 33.33" N 96° 50' 5.58" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-111</a> Accepted 2020-WTE-92-OE	Milbank, SD	45° 4' 28.14" N 96° 49' 29.14" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-114</a> Accepted 2020-WTE-93-OE	Milbank, SD	45° 4' 53.41" N 96° 50' 55.17" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-117</a> Accepted 2020-WTE-94-OE	Milbank, SD	45° 5' 15.09" N 96° 50' 46.58" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-118</a> Accepted 2020-WTE-95-OE	Milbank, SD	45° 5' 21.29" N 96° 50' 24.71" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-120</a> Accepted 2020-WTE-96-OE	Milbank, SD	45° 5' 21.82" N 96° 49' 35.55" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-116</a> Accepted 2020-WTE-97-OE	Milbank, SD	45° 5' 0.17" N 96° 49' 8.61" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-68</a> Accepted 2020-WTE-98-OE	Milbank, SD	45° 2' 21.45" N 96° 53' 59.04" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-67</a> Accepted 2020-WTE-99-OE	Milbank, SD	45° 2' 23.04" N 96° 53' 22.14" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">CRI-42</a> Accepted 2020-WTE-100-OE	Milbank, SD	45° 4' 15.42" N 96° 58' 18.93" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">East Radar</a> Accepted 2020-WTE-101-OE	Milbank, SD	45° 2' 38.47" N 96° 48' 20.56" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None
<a href="#">West Radar</a> Accepted 2020-WTE-102-OE	Milbank, SD	45° 4' 39.94" N 97° 0' 5.08" W	<a href="#">Show Map</a>	<a href="#">Clone</a> <a href="#">Upload a PDF</a> Add 7460-2	None

[Mapping - Desk Reference Guide V\\_2018.2.0](#) [Attaching Documents - Desk Reference Guide V\\_2018.2.0](#)

[Upload a PDF to the Project](#)

**Draft:** Cases that have been saved by the user but have not been submitted to the FAA.  
**Waiting:** Wind Turbine/Met Tower (w/WT Farm) cases that have not been submitted to the FAA and are waiting for an action from the user, either to verify the map or attach specific documents

**Accepted:** Cases that have been submitted to the FAA.

**Add Letter:** Cases that have been reviewed by the FAA and require additional information from the user.

**Work in Progress:** Cases that are being evaluated by the FAA.

**Interim:** Cases that have been reviewed by the FAA and require resolution from the user.

**Determined:** Cases that have a completed aeronautical study and an FAA determination.

**Terminated:** Cases that are no longer valid.

Please allow the FAA a minimum of 45 days to complete a study.

**Case Transfer:**

- Use the check box(es) to select the case(s) you want to transfer.
- Select the "Transfer Cases button" to open the "Manage Transfer Cases" screen.

**Note:** Drafts and cases in Add and Terminated status can not be transferred.

[Click here to contact the appropriate representative.](#)





**Project Submission Success**  
**Project Name: CROWN-000560930-20**

Project CROWN-000560930-20 has been submitted successfully to the FAA.

Your filing is assigned Aeronautical Study Number (ASN):

- 2020-WTE-10-OE
- 2020-WTE-11-OE
- 2020-WTE-12-OE
- 2020-WTE-13-OE
- 2020-WTE-14-OE
- 2020-WTE-15-OE
- 2020-WTE-16-OE
- 2020-WTE-17-OE
- 2020-WTE-18-OE
- 2020-WTE-19-OE
- 2020-WTE-20-OE
- 2020-WTE-21-OE
- 2020-WTE-22-OE
- 2020-WTE-23-OE
- 2020-WTE-24-OE
- 2020-WTE-25-OE
- 2020-WTE-26-OE
- 2020-WTE-27-OE
- 2020-WTE-28-OE
- 2020-WTE-29-OE
- 2020-WTE-30-OE
- 2020-WTE-31-OE
- 2020-WTE-32-OE
- 2020-WTE-33-OE
- 2020-WTE-34-OE
- 2020-WTE-35-OE
- 2020-WTE-36-OE
- 2020-WTE-37-OE
- 2020-WTE-38-OE
- 2020-WTE-39-OE
- 2020-WTE-40-OE
- 2020-WTE-41-OE
- 2020-WTE-42-OE
- 2020-WTE-43-OE
- 2020-WTE-44-OE
- 2020-WTE-45-OE
- 2020-WTE-46-OE
- 2020-WTE-47-OE
- 2020-WTE-48-OE
- 2020-WTE-49-OE
- 2020-WTE-50-OE
- 2020-WTE-51-OE
- 2020-WTE-52-OE
- 2020-WTE-53-OE
- 2020-WTE-54-OE
- 2020-WTE-55-OE
- 2020-WTE-56-OE
- 2020-WTE-57-OE
- 2020-WTE-58-OE
- 2020-WTE-59-OE
- 2020-WTE-60-OE
- 2020-WTE-61-OE
- 2020-WTE-62-OE
- 2020-WTE-63-OE
- 2020-WTE-64-OE
- 2020-WTE-65-OE
- 2020-WTE-66-OE
- 2020-WTE-67-OE
- 2020-WTE-68-OE
- 2020-WTE-69-OE
- 2020-WTE-70-OE
- 2020-WTE-71-OE
- 2020-WTE-72-OE
- 2020-WTE-73-OE
- 2020-WTE-74-OE
- 2020-WTE-75-OE
- 2020-WTE-76-OE
- 2020-WTE-77-OE
- 2020-WTE-78-OE
- 2020-WTE-79-OE
- 2020-WTE-80-OE
- 2020-WTE-81-OE
- 2020-WTE-82-OE

2020-WTE-83-OE  
2020-WTE-84-OE  
2020-WTE-85-OE  
2020-WTE-86-OE  
2020-WTE-87-OE  
2020-WTE-88-OE  
2020-WTE-89-OE  
2020-WTE-90-OE  
2020-WTE-91-OE  
2020-WTE-92-OE  
2020-WTE-93-OE  
2020-WTE-94-OE  
2020-WTE-95-OE  
2020-WTE-96-OE  
2020-WTE-97-OE  
2020-WTE-98-OE  
2020-WTE-99-OE  
2020-WTE-100-OE  
2020-WTE-101-OE  
2020-WTE-102-OE

Please refer to the assigned ASN on all future inquiries regarding this filing.

Please return to the system at a later date for status updates.

It is the responsibility of each e-filer to exercise due diligence to determine if coordination of the proposed construction or alteration is necessary with their state aviation department. Please use the link below to contact your state aviation department to determine their requirements:

[State Aviation Contacts](#)

*To ensure e-mail notifications are delivered to your inbox please add noreply@faa.gov to your address book. Notifications sent from this address are system generated FAA e-mails and replies to this address will NOT be read or forwarded for review. Each system generated e-mail will contain specific FAA contact information in the text of the message.*