

May 28, 2021

Mrs. Patricia Van Gerpen Executive Director Public Utilities Commission 500 East Capitol Avenue Pierre, SD 57501

RE: In the Matter of the Application by Tatanka Ridge Wind, LLC for a Permit of a Wind Energy Facility in Deuel County, South Dakota – Order Granting Extension for Compliance with Condition 29 – EL19-026

Bi-Monthly Update #2: May 15, 2021-May 31, 2021

Dear Mrs. Van Gerpen:

Tatanka Ridge Wind, LLC (Tatanka Ridge Wind) respectfully submits this filing in compliance with the Order granting an extension to Condition 29 of the Facility Permit.

Condition 29:

Within 90 days after the Project's commercial operation date, Applicant shall submit a report to the Commission that provides the following information:

a) as-built location of structures and facilities, including drawings clearly showing compliance with the setbacks required by state and local governments;

b) the status of remedial activities for road damage, landowner property damage, crop damage, environmental damage, or any other damage resulting from Project construction activities; and

c) a summary of known landowner complaints and Applicant's plan for resolving those complaints.

On April 16, 2021, the Commission granted Motion for Extension to Comply with Condition 29 until August 5, 2021. Applicant shall provide updates to Staff on a bi-monthly basis, to be provided on the Fifteenth and Thirtieth of each month.

Response to part a:

No change since previous bi-weekly report. No additional information since updated provided to Commission April 12, 2021. The as-built survey will be completed after site reclamation is completed and is anticipated by August 2021.

Response to part b:

The Contractor (Wanzek) is actively working on Tatanka Ridge site reclamation including removing temporary approach radii to access roads, narrowing access and spur roads, decompacting, reclaiming areas around turbines, final surface grading, and seeding. Additionally, Wanzek is removing silt fence in areas that are stabilized from erosion and ready for planting. Their subcontractor is removing rocks and final grading along the electrical collection line. Wanzek is removing the temporary intersection modifications at public roads. Wanzek and their subcontractor are repairing known drain tile impacts. They are working, in general, west to east across the site. Table 1 summarizes current construction reclamation activities at the site.

It is anticipated road repairs will be completed by June 30, 2021. As the roads are completed, Avangrid will continue to work with Deuel County and the Townships to inspect the final road status. On May 24, 2021 Avangrid, Wanzek, and the three townships reviewed the status of township roads. The County has expressed wanting to delay the final inspection of the roads until the temporary radii are removed and repairs are completed for the entire project.

To date, there is no known environmental damage or property damage. If those are identified during construction restoration or through landowner communication, they will be addressed. Other damage from Project construction activities will also be addressed if identified by landowners or during restoration activities.

DATE	SWPPP	Intersection	Beauty	Approaches/	Spur	Reclaim
		Modifications	Rings	Radius	Roads	Sites
5/15/21	Check silt	No planned	A2, B2	P8	A2, B2	Complete
	fence	work				
5/17/21	Check silt	No planned	B1, A1	I3, P8	B1, A1	Complete
	fence	work				
5/18/21	Check silt	192 nd & Hwy	A1, A2	P8	A1, A2	Complete
	fence	15 east				
5/19/21	Check silt	192 nd & Hwy	A2	No planned	A2	Complete
	fence	15 east		work		

Table 1: Summary of Reclamation Activities

5/22/21 5/23/21 5/24/21	Check silt fence Check silt fence Check silt fence (0.25" rain) Check silt	Hwy 28 & 480th 190 th & 478th 190 th & 478th	work No planned work No planned work No planned work	E5, E6 F1, F2 F1, F2	work No planned work No planned work L3	Complete Complete Complete
5/22/21 5/23/21 5/24/21	fence Check silt fence Check silt fence (0.25" rain) Check silt	480th 190 th & 478th 190 th & 478th	planned work No planned work No planned	F1, F2	planned work No planned work	Complete
5/22/21 5/23/21 5/24/21	Check silt fence Check silt fence (0.25" rain) Check silt	190 th & 478th 190 th & 478th	work No planned work No planned		work No planned work	
5/23/21	fence Check silt fence (0.25" rain) Check silt	190 th & 478th	No planned work No planned		No planned work	
5/23/21	fence Check silt fence (0.25" rain) Check silt	190 th & 478th	planned work No planned		planned work	
5/23/21	Check silt fence (0.25" rain) Check silt		work No planned	F1, F2	work	Complete
5/24/21	fence (0.25" rain) Check silt		No planned	F1, F2		Complete
5/24/21	fence (0.25" rain) Check silt		planned	F1, F2	L3	Complete
5/24/21	(0.25" rain) Check silt					
5/24/21	rain) Check silt		work			
5/24/21	Check silt					
				~~		
	<i>c</i>	Hwy 28 &	No	C5	G1, E6	Complete
	fence	481 st	planned			
	(0.10"		work			
	rain)			5.4	01 51	
	Check silt	Hwy 28 &	No	B1	G1, E4,	Complete
	fence	480th	planned		E5, E6	
E /00 /04	0 1 11		work	A 0 0 1 0 0	F 4 F 0	
	Check silt	Hwy 28 &	No	A2, B1, B2	E1, E2	Complete
	fence	480 th , Hwy 28	planned			
E/07/04		& 481 st	work	A0 D0	Dumahliat	Osmanlata
	Check silt	Hwy 28 &	No	A2, B2	Punchlist	Complete
	fence &	481 st , 192 nd & 478th	planned		Touch ups	
	wattles (1.40"	47 oui	work			
	rain)					
	Check silt	No planned	No	No planned	No	Complete
	fence &	work (wet site	planned	work (wet	planned	
	wattles	conditions)	work (wet	site	work (wet	
	Watties	conditions	site	conditions)	site	
			conditions)	conditions)	conditions)	
5/29/21	No Work/	No Work/	No Work/	No Work/	No Work/	No Work/
	Holiday	Holiday	Holiday	Holiday	Holiday	Holiday
	No Work/	No Work/	No Work/	No Work/	No Work/	No Work/
	Holiday	Holiday	Holiday	Holiday	Holiday	Holiday
	No Work/	No Work/	No Work/	No Work/	No Work/	No Work/
	Holiday	Holiday	Holiday	Holiday	Holiday	Holiday

Response to part c:

Avangrid Renewables (Avangrid) and Wanzek have been talking to and meeting one-on-one with landowners to discuss reclamation work on their farms. The construction team is working to rectify issues or monitor the situation, depending on the issue and site conditions.

Summary of Landowner Communication since last report:

- Randy Stroschein (5/21/21) Avangrid, Wanzek, and Randy S met at L9 to discuss water from road into field. Wanzek will install riprap at bottom side of access road. Reviewed L4 drainage design.
- Wayne Knutson and Jim Koeing (5/22/21) Avangrid and Wanzek met with Wayne Knutson & Jim Koeing at A1 and A2 to discuss low water crossings. Landowner prefers no rip rap in ditch. Engineering will evaluate potential revision.

Please let me know if you have any additional questions (mark.croissant@avangrid.com).

Sincerely,

Mark Croissant

Mark Croissant Senior Project Manager - Projects