

## Stork Twin City Testing Corporation

**PROJECT NUMBER:** SOU263-01-15-91979

**DATE:** January 16 & 17, 2008

**PAGE** 1 of 1

### CD INDEX


**Project:**

Cracked 2" diameter gas pipe section from PS07-002 Natural Gas Incident, Mitchell, South Dakota

**Order of Documents:**


1. LIST OF ATTENDEES
2. VISUAL EXAMINATION
3. CHEMICAL ANALYSIS
4. TENSILE TEST
5. QUANTITATIVE CHEMICAL ANALYSIS
6. GRAIN STRUCTURE EXAMINATION
7. ADDITIONAL PHOTOS
  - A. On-site Photos
  - B. Visual Examination Photos
  - C. SEM EDS Photos Data
  - D. Grain Structure Examination (GSE) Photos

**Prepared By:**



**Richard Kielty, P.E.**  
Senior Metallurgical Engineer  
Materials Testing & Analysis Group  
Phone: (651) 659-7229

**Reviewed By:**



**Viswanathan Krishnamoorthi, P.E.**  
Manager, Failure Analysis  
Materials Testing & Analysis Group  
Phone: (651) 659-7346